
RAW and R152: step displacement (30 repeated scans)
RAW: mean ± 1 SD
R152: mean ± 1 SD
Measured step displacement (nm)
1020
1015
1010
1005
1000
995
990
985
980
1
5
10
15
20
25
30
Step number
Each point uses 30 paired scans; shaded bands show sample SD, not standard error.