Apex Precision Manufacturing Pvt. Ltd.

Production Planning & Process Control SOP

CONTROLLED SAMPLE DOCUMENT FOR RAG CHATBOT TESTING

Document ID	APM-PROD-SOP-004	**Department**	Production
Version	1.0 – Sample	**Effective date**	30 October 2026
Document owner	Production Department	**Review status**	Training sample
Classification	Internal – Fictional	**Approval**	Not approved for real operations

IMPORTANT NOTICE

This document is fictional sample content created solely to develop and test a Retrieval-Augmented Generation (RAG) chatbot. It is not an approved company procedure, machine-specific instruction, legal policy, or substitute for manufacturer documentation, site risk assessments, qualified supervision, or applicable laws. Do not use it to operate, repair, inspect, or service real equipment.

Purpose

Standardize the flow of a manufacturing work order from release through production, in-process checks, and final handover.

Document control

The document owner is responsible for review and controlled distribution in a real organization. For this training dataset, version 1.0 is fixed and all names, policies, workflows, and examples are fictional.

1. Work order release

• Production planning releases a work order with part number, drawing revision, quantity, due date, material specification, and routing.

• The line supervisor confirms that the latest approved documents are available at the workstation.

• Any mismatch between the work order, drawing, material, or process route must be resolved before production starts.

2. Material verification

• Stores issues material against the work order and records the batch or heat number where applicable.

• Production verifies part identity, quantity, visible condition, and traceability information before use.

• Segregate unidentified or nonconforming material and notify Quality and Stores.

3. Line readiness

• Confirm trained personnel, approved equipment, tooling, fixtures, gauges, and current work instructions are available.

• Complete the area readiness and safety checks defined for the process.

• Record equipment status and any open maintenance restrictions.

4. First-piece approval

• Produce the first piece using the approved process and setup documentation.

• Submit the first piece to Quality for inspection when the control plan requires approval.

• Do not continue batch production until required first-piece approval is recorded.

5. In-process control

• Perform checks at the frequency stated in the control plan; do not invent or reduce inspection frequency.

• Record actual measurements, gauge ID, operator, time, and lot/work-order reference.

• Identify and segregate suspect output when a result is outside specification; notify the supervisor and Quality.

6. Nonconforming output

• Stop or contain the affected process as directed by the nonconformance procedure.

• Identify affected parts and preserve traceability; do not rework, use-as-is, or scrap without authorized disposition.

• Document the issue and support root-cause and corrective-action activities.

7. Shift handover and completion

• Reconcile produced, accepted, rejected, and remaining quantities against the work order.

• Record downtime, material shortages, process deviations, and open quality issues.

• Hand over machine condition, WIP status, and pending approvals to the next shift.

8. Records

• Work order; material issue and traceability record; line-readiness checklist; first-piece approval; in-process inspection log; nonconformance report; shift handover.

Revision history

Version	Date	Description	Prepared by
1.0	30-Oct-2026	Initial fictional sample for RAG testing	Project team