Apex Precision Manufacturing Pvt. Ltd.

Quality Control & Product Inspection SOP

CONTROLLED SAMPLE DOCUMENT FOR RAG CHATBOT TESTING

Document ID	APM-QLT-SOP-006	**Department**	Quality
Version	1.0 – Sample	**Effective date**	30 October 2026
Document owner	Quality Department	**Review status**	Training sample
Classification	Internal – Fictional	**Approval**	Not approved for real operations

IMPORTANT NOTICE

This document is fictional sample content created solely to develop and test a Retrieval-Augmented Generation (RAG) chatbot. It is not an approved company procedure, machine-specific instruction, legal policy, or substitute for manufacturer documentation, site risk assessments, qualified supervision, or applicable laws. Do not use it to operate, repair, inspect, or service real equipment.

Purpose

Describe a generic inspection and nonconformance workflow for manufactured components.

Document control

The document owner is responsible for review and controlled distribution in a real organization. For this training dataset, version 1.0 is fixed and all names, policies, workflows, and examples are fictional.

1. Scope and responsibilities

• Applies to incoming, in-process, and final inspection activities in the fictional Apex Precision Manufacturing training environment.

• Quality personnel use the current approved drawing, specification, control plan, and calibrated inspection equipment.

• This sample SOP does not define product tolerances; always use the current engineering-approved specification.

2. Document and gauge verification

• Confirm part number, drawing revision, inspection stage, and applicable acceptance criteria before inspection.

• Verify the measuring instrument ID, calibration status, range, and suitability for the measurement.

• Do not use instruments that are damaged, overdue for calibration, or unsuitable for the required measurement.

3. Incoming inspection

• Check supplier identification, purchase order, material certificate where required, batch traceability, quantity, and visible condition.

• Perform dimensional or material checks according to the incoming inspection plan.

• Identify and segregate material that is damaged, unidentified, or outside specification.

4. In-process inspection

• Inspect characteristics and at the frequency specified in the control plan.

• Record actual results rather than only marking pass/fail where numeric results are required.

• If a result is outside specification, contain potentially affected product and notify Production and Quality leadership.

5. Final inspection and release

• Verify all required operations and inspection records are complete.

• Confirm product identification, quantity, traceability, packaging, and customer-specific requirements where applicable.

• Only authorized Quality personnel may release product when the defined acceptance criteria are met.

6. Nonconformance control

• Identify and segregate nonconforming product to prevent unintended use or shipment.

• Open a nonconformance report with part, lot, work order, defect description, quantity, and detection point.

• Disposition such as rework, repair, scrap, or concession requires authorized approval and documented verification.

• Review recurring defects for root cause and corrective action.

7. Records

• Incoming inspection report; in-process inspection log; final inspection report; gauge calibration record; nonconformance report; corrective-action record.

Revision history

Version	Date	Description	Prepared by
1.0	30-Oct-2026	Initial fictional sample for RAG testing	Project team