

Measuring & Layout

→ Equal Spacing

Measured all faces for uniform proportions.

→ Grid Lines

Drew precise lines using a square and scribe.

→ Pip Positions

Marked exact dot locations on each face.

