









ACS Temperature Sensor
Allows connection of a remote 10k NTC to the system
Set thresholds for high, low temperature to assert interrupt
Passes ACS signal through, no need for splitter
HD15 on either side, polarity doesn't matter










Schematic Page	ACS Interface		Page Number	1
Source Link	https://github.com/rit-construct-makerspace/access-control-hardware		Total Pages	3
Version	V3.0.0	ACS Temperature Sensor Main Board		
				
		Licensed Under CERN-OHL-S 2.0		

7 segment 4-char screen
Increment/decrement buttons in increments of 1 deg
Edit button press and hold to edit, cycle between modes
High (Indicated H) - H095 for 95 deg
Low (Indicated L) - L010 for 10 deg
Units (indicated U) - U-CE or U-FH for celsius/farenheit
Brightness (indicated b) - b-01 to b-16
Beta (Indicated by bEtA) - screen shows the word then goes to all 4 chars as the beta value
Indicator light for high temp, low temp, interrupt state
The LEDs in the buttons are re-used as these status LEDs



Schematic	Main Board			Create at	2026-03-11
				Update at	2026-03-12
Board	V3.0.0			Page	User Interface
Drawn	ACS Temperature Sensor				
Reviewed					
		Version	Size	Page 2 Total 3	
		V1.0	A4	EasyEDA.com	



Schematic	Main Board			Create at	2026-03-11
Board	V3.0.0			Update at	2026-03-12
Drawn		ACS Temperature Sensor			
Reviewed					
		Version	Size	Page 3 Total 3	
EasyEDA		V1.0	A4	EasyEDA.com	