(6).

MPPL	MEENAKSHI POLYMERS PRIVATE LIMITED HARIDWAR	DOC.NO- MPPL/F/STR/07
	LINE REJECTION REPORT	REV NO:-00
	WELDSHOP	REV DATE:-00
	MONTH:- JULY-26.	ORG DATE:-01.04.2017

S.NO.	ITEM CODE	MATERIAL PARTICULARS	UNIT	REJECTION QTY	VENDOR NAME	REASON / REMARKS
(1)	SF500254	main steering plate fabb.	Nos.	54	MPPL P-10	Bending out.
(2)	RM500003	Pedal A 2.6 MM	Nos	55	"	Pedal cut due to Scratch Not ok.
(3)	SF500255	Rear guide brake pedal Assy	Nos.	181	MPPL P-10	Rear guide profile Not ok.
(4)	SF500252	main stand tube L	Nos.	290	P-10	Hole out

(PREPARED BY) SIGN (PROD. Head) SIGN (Q.A. Head) APPROVED BY-VP Operations)

Rajeev (any)