

Organization: ACME INDUSTRIES LTD.

Work Station Having No Plan Period: 01-10-2014 To 24-03-2015

| Shift Name : Morning Shift | | |
|----------------------------|-------------------|------------------------------|
| SI.No. | Work Station Code | Work Station Description |
| 1 | WS000002 | Vertical Casting Machine A |
| 2 | WS000004 | Packing Machine A |
| 3 | WS000005 | Packing Machine B |
| 4 | WS000006 | Packing Machine C |
| 5 | WS000007 | Horizontal Casting Machine B |
| 6 | WS000008 | Horizontal Casting Machine C |
| 7 | WS000011 | Raw Binding Machine B |

| Shift Name | e : Evening | |
|------------|-------------------|------------------------------|
| SI.No. | Work Station Code | Work Station Description |
| 1 | WS000004 | Packing Machine A |
| 2 | WS00005 | Packing Machine B |
| 3 | WS000006 | Packing Machine C |
| 4 | WS000007 | Horizontal Casting Machine B |
| 5 | WS000008 | Horizontal Casting Machine C |
| 6 | WS000011 | Raw Binding Machine B |