

QC Type

: COMPLETE CHECK

Organisation: ACME INDUSTRIES LTD.

Period: 01-02-2015 To 02-05-2015

QC For : ROUTE CARD QC No. : QC000005 QC Date : 09/02/2015 Document No.: RC000017 **Document Date** : 02/02/2015 : SAMPLE CHECK Status QC Type : COMPLETE Item Description : Output Itm T Quantity: 4.79 Unit :kg Values Limit **Parameter Name** Result Standard Actual Lower Upper Check Serial No : 1 Checked Qty: 1.00 OK Qty: 0.00 Rejected Qty: 1.00 Reworkable Qty: 0.00 **BAT HANDLE** 1.00 REJECTED 1.00 1 00 Check Serial No: 2 Checked Qty: 2.00 OK Qty: 2.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 BAT HANDLE 1.00 1.00 OK Check Serial No: 3 Checked Qty: 1.79 OK Qty: 1.79 Rejected Qty: 0.00 Reworkable Qty: 0.00 **BAT HANDLE** 1.00 1.00 1.00 OK QC For : JOB EXECUTION QC No. QC0000006 QC Date : 11/02/2015 Document No. : JE000020 **Document Date** : 31/01/2015 QC Type : SAMPLE CHECK **Status** : INCOMPLETE Item Description : NOutput-1 Quantity: 10.00 Unit :kg Values Limit **Parameter Name** Result Standard Actual Lower Upper Check Serial No: 1 Checked Qtv: 4.00 OK Qty: 4.00 Rejected Qty: 0.00 Reworkable Qtv: 0.00 **NEW TEST** 1.00 1.00 1.00 1.00 OK PRD QC 1.00 1.00 1.00 QC For : JOB EXECUTION QC No. : QC0000007 QC Date : 11/02/2015 Document No. : JE000006 : 10/02/2015 **Document Date** QC Type : COMPLETE CHECK : INCOMPLETE Item Description : op2 Unit :Pcs Quantity: 1.00 **Parameter Name** Result Standard Actual Lower Upper Check Serial No: 1 Rejected Qty: 0.00 Checked Qty: 1.00 OK Qty: 0.00 Reworkable Qty: 0.00 **DUAL SIM** 1.00 1.00 1.00 1.00 OK GORILLA AMOLED SCREEN 0.00 **REJECTED** 1.00 1.00 1.00 QC For : JOB EXECUTION QC No. : QC0000016 QC Date : 24/02/2015 Document No. : JE000025 **Document Date** : 11/02/2015 QC Type : SAMPLE CHECK Status : INCOMPLETE 1.00 Unit :Pcs Item Description : op2 Quantity: Values Limit **Parameter Name** Result Standard Actual Lower Upper Checked Qty: 1.00 Check Serial No: 1 OK Qty: 0.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 **DUAL SIM** 1 00 1.00 1 00 1 00 OK **GORILLA AMOLED SCREEN** 1.00 1.00 1.00 1.00 OK QC For : JOB EXECUTION QC No. : QC0000008 QC Date : 16/02/2015 Document No. : JE000042 **Document Date** : 12/02/2015

02-May-2015, **6.16 PM** Page 1 of 6

Status

: COMPLETE

Period: 01-02-2015 To 02-05-2015





Organisation: ACME INDUSTRIES LTD.

Item Description : op2			Quantity:	1.00		Unit :Pcs	
Parameter Na	me	Val Standard	ues Actual	Lowe	Lin	nit Upper	Result
Check Serial No : 1	Checked Qty : 1.00			Rejected Qt			able Qty: 0.00
DUAL SIM		1.00		1.00	1.00		OK
GORILLA AMOLED SCREEN		1.00		0.00	1.00		REJECTED
QC For : JOB EXEC	LITION						
QC No. : QC0000009				QC Date		: 19/02/2015	
Document No. : JE000047	J				nt Date	: 16/02/2015	
QC Type : COMPLETE	E CHECK			Status	ii Duio	: COMPLETE	
Item Description : op2			Quantity:	5.00		Unit :Pcs	
Parameter Na	mo	Val			Liņ		Result
		Standard	Actual	Lowe	<u> </u>	Upper	
Check Serial No : 1	Checked Qty: 3.00			Rejected Qt			cable Qty: 0.00
DUAL SIM		1.00		1.00	1.00	1.00	OK
GORILLA AMOLED SCREEN		1.00		1.00	1.00		ОК
Check Serial No : 2	Checked Qty: 2.00	OK Qty :	0.00	Rejected Qt	y: 2.00	Rework	able Qty: 0.00
DUAL SIM		1.00		1.00	1.00	1.00	OK
GORILLA AMOLED SCREEN		1.00		0.00	1.00	1.00	REJECTED
QC For : JOB EXEC	UTION						
QC No. : QC0000012	2			QC Date		: 19/02/2015	
Document No. : JE000058				Documer	nt Date	: 19/02/2015	
QC Type : COMPLETE	E CHECK			Status		: COMPLETE	
Item Description : op3			Quantity:	2.00		Unit :Pcs	
Parameter Na	me	Val Standard	ues Actual	Lowe	Lin er	nit Upper	Result
Check Soviel No. 4							
Check Serial No : 1	Checked Qty: 1.00	OK Qty:	0.00	Rejected Qt	y: 1.00	Rework	able Qty: 0.00
	Checked Qty: 1.00	OK Qty : 1.00		Rejected Qt	y: 1.00 1.00		REJECTED
	Checked Qty : 1.00	1.00			1.00	1.00	<u>-</u>
CHEAP SET ISO YES NO Check Serial No : 2		1.00	1.00	0.00	1.00	1.00	REJECTED
CHEAP SET ISO YES NO	Checked Qty : 1.00	1.00 OK Qty :	1.00	0.00 Rejected Qt	1.00 y: 0.00	1.00	REJECTED
CHEAP SET ISO YES NO Check Serial No : 2 CHEAP SET ISO YES NO QC For : JOB EXECT	Checked Qty : 1.00	1.00 OK Qty :	1.00	0.00 Rejected Qt	1.00 y: 0.00	1.00	REJECTED
CHEAP SET ISO YES NO Check Serial No : 2 CHEAP SET ISO YES NO QC For : JOB EXECT	Checked Qty : 1.00	1.00 OK Qty :	1.00	0.00 Rejected Qt	1.00 y: 0.00 1.00	1.00 Rework 1.00	REJECTED
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059	Checked Qty : 1.00 UTION	1.00 OK Qty :	1.00	0.00 Rejected Qt 1.00 QC Date	1.00 y: 0.00 1.00	1.00 Rework 1.00 : 19/02/2015	REJECTED
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059	Checked Qty : 1.00 UTION	1.00 OK Qty :	1.00	0.00 Rejected Qt 1.00 QC Date Documer	1.00 y: 0.00 1.00	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015	REJECTED
CHEAP SET ISO YES NO Check Serial No : 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE	Checked Qty : 1.00 UTION 0 E CHECK	1.00 OK Qty: 1.00	1.00 Quantity:	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00	1.00 y: 0.00 1.00	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs	REJECTED
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3	Checked Qty : 1.00 UTION 0 E CHECK	1.00 OK Qty: 1.00 Value Standard	Quantity:	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lower	1.00 1.00 1.00 Line	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs nit Upper	REJECTED sable Qty: 0.00 OK Result
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na	Checked Qty : 1.00 UTION 0 E CHECK	1.00 OK Qty: 1.00 Values	Quantity: ues Actual	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00	1.00 1.00 1.00 Line	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs nit Upper Rework	REJECTED sable Qty: 0.00 OK
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1	Checked Qty: 1.00 UTION 0 E CHECK IMPE Checked Qty: 1.00	1.00 OK Qty: 1.00 Values Standard OK Qty: 1.00	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lower Rejected Qt	1.00 1.00 1.00 1.00 Line or y: 0.00 1.00	1.00 Rework 1.00 : 19/02/2015 :: 19/02/2015 :: COMPLETE Unit :Pcs nit Upper Rework 1.00	REJECTED cable Qty: 0.00 OK Result cable Qty: 0.00 OK
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2	Checked Qty : 1.00 UTION 0 E CHECK	1.00 OK Qty: 1.00 Values Standard OK Qty: 1.00	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt	1.00 1.00 1.00 1.00 Line or y: 0.00 1.00	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs nit Upper Rework 1.00 Rework	REJECTED Stable Qty: 0.00 OK Result Stable Qty: 0.00 OK Stable Qty: 0.00
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO	Checked Qty: 1.00 UTION 0 E CHECK Checked Qty: 1.00 Checked Qty: 1.00	1.00 OK Qty: 1.00 Vali Standard OK Qty: 1.00 OK Qty:	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt 1.00 Rejected Qt	1.00 1.00 1.00 1.00 Lint Date Lint or	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs nit Upper Rework 1.00 Rework	REJECTED cable Qty: 0.00 OK Result cable Qty: 0.00 OK
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT	Checked Qty: 1.00 UTION CHECKE Checked Qty: 1.00 Checked Qty: 1.00 UTION	1.00 OK Qty: 1.00 Vali Standard OK Qty: 1.00 OK Qty:	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt 1.00 Rejected Qt	1.00 1.00 1.00 1.00 Lint Date Lint or	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs nit Upper Rework 1.00 Rework 1.00	REJECTED Stable Qty: 0.00 OK Result Stable Qty: 0.00 OK Stable Qty: 0.00
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC00000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO	Checked Qty: 1.00 UTION CHECKE Checked Qty: 1.00 Checked Qty: 1.00 UTION	1.00 OK Qty: 1.00 Vali Standard OK Qty: 1.00 OK Qty:	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt 1.00 Rejected Qt 0.00	1.00 y: 0.00 1.00 1.00 Lin er y: 0.00 1.00 1.00 1.00	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs hit Upper Rework 1.00 Rework 1.00 : 19/02/2015	REJECTED Stable Qty: 0.00 OK Result Stable Qty: 0.00 OK Stable Qty: 0.00
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000012 Document No. : JE000060	Checked Qty: 1.00 UTION Checked Qty: 1.00 Checked Qty: 1.00 UTION 1	1.00 OK Qty: 1.00 Vali Standard OK Qty: 1.00 OK Qty:	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt 1.00 Rejected Qt 0.00	1.00 y: 0.00 1.00 1.00 Lin er y: 0.00 1.00 1.00 1.00	1.00 Rework 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	REJECTED Stable Qty: 0.00 OK Result Stable Qty: 0.00 OK Stable Qty: 0.00
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000012 Document No. : JE000060 QC Type : COMPLETE	Checked Qty: 1.00 UTION Checked Qty: 1.00 Checked Qty: 1.00 UTION 1	1.00 OK Qty: 1.00 Vali Standard OK Qty: 1.00 OK Qty:	Quantity: ues Actual 1.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt 1.00 Rejected Qt 0.00 QC Date Documer Status	1.00 y: 0.00 1.00 1.00 Lin er y: 0.00 1.00 1.00 1.00	1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : COMPLETE Unit :Pcs nit Upper Rework 1.00 Rework 1.00 : 19/02/2015 : 19/02/2015 : 19/02/2015 : COMPLETE	REJECTED Stable Qty: 0.00 OK Result Stable Qty: 0.00 OK Stable Qty: 0.00
CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000059 QC Type : COMPLETE Item Description : op3 Parameter Na Check Serial No: 1 CHEAP SET ISO YES NO Check Serial No: 2 CHEAP SET ISO YES NO QC For : JOB EXECT QC No. : QC0000010 Document No. : JE000060	Checked Qty: 1.00 UTION Checked Qty: 1.00 Checked Qty: 1.00 UTION Checked Qty: 1.00 UTION CHECK	1.00 OK Qty: 1.00 Vali Standard OK Qty: 1.00 OK Qty:	Quantity: ues Actual 1.00 0.00	0.00 Rejected Qt 1.00 QC Date Documer Status 2.00 Lowe Rejected Qt 1.00 Rejected Qt 0.00	1.00 y: 0.00 1.00 1.00 Lin er y: 0.00 1.00 1.00 1.00	1.00 Rework 1.00 1.00	REJECTED Stable Qty: 0.00 OK Result Stable Qty: 0.00 OK Stable Qty: 0.00

02-May-2015, **6.16 PM** Page 2 of 6



Organisation: ACME INDUSTRIES LTD.

Period: 01-02-2015 To 02-05-2015

CHEAP SET ISO YES NO		1.00		1.00	1.00	1.00	OK	
Check Serial No : 2	Checked Qty: 1.00			Rejected C			able Qty :	0.00
CHEAP SET ISO YES NO	<u>-</u>	1.00		0.00	1.00		REJECTE	
QC For : JOB EXECUT	ΓΙΟΝ							
QC No. : QC0000015				QC Date	e	: 23/02/2015		
Document No. : JE000077				Docume	ent Date	: 20/02/2015		
QC Type : COMPLETE C	CHECK			Status		: COMPLETE		
Item Description : op3			Quantity:	2.00		Unit :Pcs		
Parameter Nam	е —	Val Standard	ues Actual	Lov	Lim	it Upper	R	esult
Check Serial No : 1	Checked Qty: 1.00			Rejected C	<u> </u>		able Qty :	0.00
CHEAP SET ISO YES NO		1.00		0.00	1.00	1.00	REJECTE	ED
Check Serial No : 2	Checked Qty: 1.00	OK Qty :	1.00	Rejected C	Qty: 0.00	Rework	able Qty :	0.00
CHEAP SET ISO YES NO		1.00		1.00	1.00	1.00	OK	
QC For : JOB EXECUT	ΓΙΟΝ							
QC No. : QC0000017				QC Date	e	: 24/02/2015		
Document No. : JE000080				Docume	ent Date	: 20/02/2015		
QC Type : COMPLETE C	CHECK			Status		: COMPLETE		
Item Description : op3			Quantity:	2.00		Unit :Pcs		
Parameter Nam	e	Val Standard	ues Actual	Lov	Lim	it Upper	R	esult
Check Serial No : 1	Checked Qty : 1.00			Rejected C			able Qty :	1.00
CHEAP SET ISO YES NO		1.00		1.00	1.00	1.00		
LAPTOP - CHECK		1.00		0.00	1.00	1.00	REWORK	 (ABLE
Check Serial No : 2	Checked Qty : 1.00	OK Qty :	1.00	Rejected C	Qty: 0.00	Rework	able Qty :	0.00
CHEAP SET ISO YES NO		1.00		1.00	1.00	1.00	OK	
LAPTOP - CHECK		1.00		1.00	1.00	1.00	OK	
QC For : JOB EXECUT	ΓΙΟΝ							
QC No. : QC0000013				QC Date	9	: 23/02/2015		
Document No. : JE000100				Docume	ent Date	: 23/02/2015		
QC Type : COMPLETE (CHECK			Status		: COMPLETE		
Item Description : op2			Quantity:	2.00		Unit :Pcs		
Parameter Nam	e	Val		Lau	Lim		R	esult
Check Serial No : 1	Checked Qty : 1.00	Standard OK Qty :	Actual	Rejected C	<u> </u>	Upper Rework	able Qty :	0.00
DUAL SIM		1.00		1.00	1.00	1.00		
GORILLA AMOLED SCREEN		1.00		1.00	1.00	1.00		
Check Serial No : 2	Checked Qty: 1.00			Rejected C			able Qty :	0.00
DUAL SIM		1.00		1.00	1.00	1.00	-	
GORILLA AMOLED SCREEN		1.00		0.00	1.00		REJECTE	 ≣D
QC For : JOB EXECUT	ΓΙΟΝ							
QC No. : QC0000014				QC Date	9	: 23/02/2015		
Document No. : JE000101						: 23/02/2015		
QC Type : COMPLETE 0	CHECK			Status		: COMPLETE		
Item Description : op2			Quantity:	2.00		Unit :Pcs		
Parameter Nam	e	Val			Lim		R	esult
	Checked Qty : 1.00	Standard OK Qty :	Actual	Lov	<u> </u>	Upper		
Check Serial No : 1				Rejected C			able Qty:	0.00

02-May-2015, **6.16 PM** Page 3 of 6





Organisation: ACME INDUSTRIES LTD.

Period: 01-02-2015 To 02-05-2015

DUAL SIM		1.00	1.00	1.00	1.00	OK
GORILLA AMOLED SCREEN		1.00	1.00	1.00	1.00	OK
Check Serial No : 2	Checked Qty: 1.0	OK Qty:	0.00	Rejected Qty: 1.00) Rework	able Qty: 0.00
DUAL SIM		1.00	1.00	1.00	1.00	OK
GORILLA AMOLED SCREEN		1.00	0.00		1.00	REJECTED
QC For : JOB EXECU	TION					
QC No. : QC0000018				QC Date	: 24/02/2015	
Document No. : JE000102				Document Date	: 23/02/2015	
QC Type : COMPLETE	CHECK			Status	: COMPLETE	
Item Description : op3			Quantity: 2	.00	Unit :Pcs	
Parameter Nam	ie –	Val Standard	ues Actual		imit	Result
Check Serial No : 1	Checked Qty : 1.0			Rejected Qty : 0.00	Upper	able Qty: 0.00
CHEAP SET ISO YES NO	Officered Qty : 1.0	1.00	1.00			
LAPTOP - CHECK		1.00	1.00			
	Checked Qty : 1.0			Rejected Qty: 0.00		
			1.00			
LAPTOP - CHECK		1.00	1.00	1.00	1.00	UK
QC For : JOB EXECUTION	HON				00/00/00/-	
QC No. : QC0000023 Document No. : JE000108				QC Date	: 09/03/2015	
	FOK			Document Date		
QC Type : SAMPLE CH	ECK			Status	: COMPLETE	
Itam Deceriation 1 and			Ouantitus : 3	00	Unit Doo	
Item Description : op3		Vali		.00	Unit :Pcs	
Item Description : op3 Parameter Nam	е	Val Standard			Unit :Pcs imit Upper	Result
	Checked Qty : 1.0	Standard	ues Actual	Li	imit Upper	Result able Qty: 0.00
Parameter Nam		Standard	Actual 1.00	Lower Rejected Qty: 0.00	imit Upper Rework	able Qty: 0.00
Parameter Nam Check Serial No : 1		Standard OK Qty:	Actual 1.00 1.00	Lower Rejected Qty: 0.00	Upper Rework	able Qty: 0.00
Parameter Nam Check Serial No : 1 CHEAP SET ISO YES NO		Standard OK Qty: 1.00 1.00	1.00 1.00	Lower Rejected Qty: 0.00	Upper D Rework 1.00	able Qty: 0.00
Parameter Nam Check Serial No : 1 CHEAP SET ISO YES NO LAPTOP - CHECK	Checked Qty : 1.0	Standard OK Qty: 1.00 1.00	1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00	Upper	able Qty: 0.00 OK OK able Qty: 0.00
Parameter Nam Check Serial No : 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No : 2	Checked Qty : 1.0	Standard OK Qty: 1.00 1.00 OK Qty:	1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00	Upper 1.00 1.00 Rework 1.00 1.00	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No : 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No : 2 CHEAP SET ISO YES NO	Checked Qty: 1.0 Checked Qty: 1.0	Standard OK Qty: 1.00 1.00 OK Qty: 1.00	1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00	Upper 1.00 1.00 Rework 1.00 1.00	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK	Checked Qty: 1.0 Checked Qty: 1.0	Standard OK Qty: 1.00 1.00 OK Qty: 1.00	1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00	Upper 1.00 1.00 Rework 1.00 1.00	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTATION	Checked Qty: 1.0 Checked Qty: 1.0	Standard OK Qty: 1.00 1.00 OK Qty: 1.00	1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 1.00	Upper 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR ISO YES NO QC No. : QC0000019	Checked Qty: 1.0 Checked Qty: 1.0	Standard OK Qty: 1.00 1.00 OK Qty: 1.00	1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date	Upper 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR	Checked Qty: 1.0 Checked Qty: 1.0	Standard OK Qty: 1.00 1.00 OK Qty: 1.00	1.00 1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date	Upper 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF JO	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK	Standard O OK Qty: 1.00 1.00 OK Qty: 1.00 1.00 Val	1.00 1.00 1.00 1.00 1.00 2.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date Status	Upper	able Qty: 0.00 OK OK able Qty: 0.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF JO	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK	Standard 1.00 1.00 1.00 0 OK Qty: 1.00 1.00 1.00 1.00	Actual 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date Status .00	Upper	able Qty: 0.00 OK OK able Qty: 0.00 OK OK Result
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF SERIES OF	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK	Standard 1.00 1.00 1.00 0 OK Qty: 1.00 1.00 1.00 1.00	Actual 1.00	Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date Status .00 Lower Rejected Qty: 0.00	Upper	able Qty: 0.00 OK OK able Qty: 0.00 OK OK Result able Qty: 1.00
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR SERVICUTOR S	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK	Standard 1.00 1.00 1.00 0 OK Qty: 1.00 1.00 1.00 1.00 1.00 1.00	Quantity: 2 Quantity: 2 Actual 1.00 1.00 1.00 1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 QC Date Document Date Status .00 Lower Rejected Qty: 0.00 1.00	Upper	able Qty: 0.00 OK OK able Qty: 0.00 OK OK OK OK OK OK OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF JO	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK	Standard 1.00 1.00 1.00 0 OK Qty: 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0	Quantity: 2 Actual 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date Status .00 Lower Rejected Qty: 0.00 1.00	Upper	able Qty: 0.00 OK OK able Qty: 0.00 OK OK OK OK OK OK OK OK Result able Qty: 1.00 OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF SERIES OF	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK Checked Qty: 1.0	Standard 1.00	Quantity: 2 Quantity: 2 Actual 1.00 1.00 1.00 1.00 1.00 1.00 0.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date Status .00 Lower Rejected Qty: 0.00 1.00 1.00 1.00 1.00	Upper	Result able Qty: 0.00 OK OK OK OK OK OK OK OK OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF JO	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK	Standard 1.00	Quantity: 2 Actual 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 QC Date Document Date Status .00 Lower Rejected Qty: 0.00 1.00 1.00 1.00 Rejected Qty: 0.00 1.00 Rejected Qty: 0.00 1.00	Upper	Able Qty: 0.00 OK OK Able Qty: 0.00 OK OK OK OK OK OK RESult Able Qty: 1.00 OK OK OK Able Qty: 1.00 OK OK Able Qty: 0.00
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR SERVED SER	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK Checked Qty: 1.0	Standard 1.00	Quantity: 2 Quantity: 2 Loc 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 QC Date Document Date Status .00 Lower Rejected Qty: 0.00 1.00 1.00 Rejected Qty: 0.00 1.00 1.00 1.00 1.00 1.00 1.00 Rejected Qty: 0.00	Upper	Able Qty: 0.00 OK OK Able Qty: 0.00 OK OK OK OK OK Result Able Qty: 1.00 OK OK OK OK OK OK OK OK OK
Parameter Nam Check Serial No: 1 CHEAP SET ISO YES NO LAPTOP - CHECK Check Serial No: 2 CHEAP SET ISO YES NO LAPTOP - CHECK QC For : JOB EXECUTOR OF JO	Checked Qty: 1.0 Checked Qty: 1.0 TION CHECK Checked Qty: 1.0 Checked Qty: 1.0	Standard 1.00	Quantity: 2 Actual 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	Lower 1.00 1.00 1.00	Upper	Able Qty: 0.00 OK OK Able Qty: 0.00 OK OK OK OK OK OK RESult Able Qty: 1.00 OK OK OK OK OK OK OK OK OK

02-May-2015, **6.16 PM** Page 4 of 6

Period: 01-02-2015 To 02-05-2015





Organisation: ACME INDUSTRIES LTD.

QC For : JOB EXECUTION QC No. : QC0000020 QC Date : 25/02/2015 Document No.: JE000112 **Document Date** : 25/02/2015 : COMPLETE CHECK Status QC Type : COMPLETE Item Description : op2 Quantity: 2.00 Unit :Pcs Values Limit **Parameter Name** Result Standard Actual Lower Upper Check Serial No: 1 Reworkable Qty: 1.00 Checked Qty: 1.00 OK Qty: 0.00 Rejected Qty: 0.00 1.00 **DUAL SIM** 1.00 1.00 1.00 OK **GORILLA AMOLED SCREEN** 1.00 1.00 1.00 1 00 OK LAPTOP - CHECK 1 00 0.00 1 00 1 00 **REWORKABLE** Check Serial No: 2 OK Qty: 1.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 Checked Qty: 1.00 **DUAL SIM** 1.00 1.00 1.00 **GORILLA AMOLED SCREEN** 1.00 1.00 1.00 1.00 OK LAPTOP - CHECK 1.00 1.00 1.00 1.00 OK QC For : MATERIAL RECEIPT **Supplier Name** : Navigant Consulting QC No. : QC0000024 QC Date : 16/03/2015 Document No.: RCPT0000000057 **Document Date** : 12/01/2015 : COMPLETE : SAMPLE CHECK Status QC Type Item Description : Leather Jackets Quantity: 5.00 Unit :Piece Values Limit **Parameter Name** Result Standard Actual Lower Upper Check Serial No: 1 Checked Qty: 1.00 OK Qty: 1.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 **BAT HANDLE** 1.00 1.00 1.00 OK XYZ TEST 2 1 00 1 00 1.00 1 00 OK Unit :Piece Item Description : SlimFlt Blazer Quantity: 5.00 **Values** Limit **Parameter Name** Result Standard Actual Lower Upper Checked Qty: 1.00 OK Qty: 1.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 Check Serial No : 1 LAPTOP - CHECKONE 10.00 10.00 11.00 OK 1.00 SOFT 1 00 1 00 1.00 ΟK XYZ TEST 10.20 10.00 5.11 20.40 OK Check Serial No: 2 Checked Qty: 1.00 OK Qty: 1.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 LAPTOP - CHECKONE 10.00 10.00 9.00 11.00 OK 1.00 SOFT 1.00 1.00 1.00 OK XYZ TEST 10.20 10.00 5.11 20.40 OK QC For : MATERIAL RECEIPT **Supplier Name** : 007 BOND QC No. : QC0000021 QC Date : 27/02/2015 Document No.: RCPT0000000257 Document Date : 27/02/2015 : SAMPLE CHECK Status : COMPLETE QC Type Item Description : Leather Jackets Quantity: 20.00 Unit :Piece Limit Values Result **Parameter Name** Standard **Actual** Lower Upper Check Serial No: 1 Checked Qty: 10.00 OK Qty: 10.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 **BAT HANDLE** 1.00 1.00 1.00 OK XYZ TEST 2 1.00 1.00 1.00 OK 1.00 Check Serial No: 2 Checked Qty: 10.00 OK Qty: 10.00 Rejected Qty: 0.00 Reworkable Qty: 0.00 **BAT HANDLE** 1.00 1.00 1.00 1.00 OK

02-May-2015, **6.16 PM** Page 5 of 6



Organisation: ACME INDUSTRIES LTD.

Period: 01-02-2015 To 02-05-2015

XYZ TEST 2		1.00	1.00	1.0	0 1.00	OK
Item Description : SlimFlt Blazer			Quantity: 20	0.00	Unit :Piece	
Parameter Name	Sta	Values Standard Actual Lov		Lower	Limit Upper	Result
Check Serial No : 1 Checke	ed Qty : 10.00	OK Qty :		Rejected Qty: 0.0		cable Qty: 0.00
LAPTOP - CHECKONE		10.00	10.00			
 SOFT		1.00	1.00	1.00	0 1.00	 ОК
XYZ TEST		10.20	20.00	5.1°	1 20.40	 ОК
Check Serial No : 2 Checke	ed Qty : 5.00	OK Qty:	5.00	Rejected Qty: 0.0	00 Rework	cable Qty: 0.00
APTOP - CHECKONE		10.00	10.00	9.0	0 11.00	ОК
SOFT		1.00	1.00	1.0	0 1.00	OK
XYZ TEST		10.20	20.00	5.1	1 20.40	OK
Check Serial No : 3 Checke	ed Qty : 5.00	OK Qty:	5.00	Rejected Qty: 0.0	00 Rework	cable Qty: 0.00
APTOP - CHECKONE		10.00	10.00	9.00	0 11.00	OK
SOFT		1.00	1.00	1.00	0 1.00	OK
(YZ TEST		10.20	20.00	5.1	1 20.40	OK
QC For : MATERIAL RECEIPT				Supplier Name	: 007 BOND	
QC No. : QC0000025				QC Date	: 18/04/2015	
Document No. : RCPT0000000009				Document Date	e : 18/04/2015	
COMPLETE CHECK				Status	: COMPLETE	
Item Description : Leather Jackets				00.00	Unit :Piece	
Parameter Name	Sta	Valu andard	ues Actual	Lower	Limit Upper	Result
Check Serial No : 1 Checke	d Qty: 100.00	OK Qty:		Rejected Qty: 10		cable Qty: 0.00
BAT HANDLE		1.00	0.00	1.00	0 1.00	REJECTED
(YZ TEST 2		1.00	1.00	1.00	0 1.00	OK
Check Serial No : 2 Checke	d Qty: 100.00	OK Qty:	100.00	Rejected Qty: 0.0	00 Rework	cable Qty: 0.00
BAT HANDLE		1.00	1.00	1.00	0 1.00	OK
(YZ TEST 2		1.00	1.00	1.00	0 1.00	OK
Item Description : Microsoft Office			Quantity: 2	21.00	Unit :Piece	
Parameter Name				Limit		
	C+-		Jes Actual		_	Result
	Sta ed Qty : 221.00	ok Qty :	Actual	Lower Rejected Qty: 0.0	Upper	Result
		andard	Actual	Lower Rejected Qty : 0.0	Upper 00 Rework	
Check Serial No : 1 Checke		OK Qty :	Actual 221.00	Lower Rejected Qty : 0.0	Upper 00 Rework 0 1.00	cable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE		OK Qty :	Actual 221.00	Lower Rejected Qty: 0.0	Upper 00 Rework 0 1.00	cable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026		OK Qty :	Actual 221.00	Lower Rejected Qty: 0.0 1.00 Supplier Name	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00	cable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Document No. : RCPT0000000010		OK Qty :	Actual 221.00	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00	cable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Document No. : RCPT0000000010 QC Type : SAMPLE CHECK		OK Qty :	Actual 221.00 1.00	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date Document Date	Upper 00 Rework 0 1.00 : 007 BOND : 18/04/2015 e : 18/04/2015	cable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Document No. : RCPT0000000010 QC Type : SAMPLE CHECK	d Qty: 221.00	OK Qty : 1.00	Actual 221.00 1.00 Quantity: 20 ues	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date Document Date Status 0.00	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	cable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Cocument No. : RCPT0000000010 QC Type : SAMPLE CHECK Item Description : Leather Jackets Parameter Name	d Qty: 221.00	OK Qty : 1.00 Valuandard	Actual 221.00 1.00 Quantity: 20 ues Actual	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date Document Date Status 0.00	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	OK
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Document No. : RCPT0000000010 QC Type : SAMPLE CHECK Item Description : Leather Jackets Parameter Name Check Serial No : 1 Checke	d Qty : 221.00	OK Qty : 1.00	Actual 221.00 1.00 Quantity: 20 ues Actual	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date Document Date Status 0.00 Lower Rejected Qty: 0.0	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	OK Result
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Cocument No. : RCPT0000000010 QC Type : SAMPLE CHECK Item Description : Leather Jackets Parameter Name Check Serial No : 1 Checke BAT HANDLE	d Qty : 221.00	Valuandard OK Qty:	Actual 221.00 1.00 Quantity: 20 Jes Actual 0.00	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date Document Date Status 0.00 Lower Rejected Qty: 0.0	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	OK Result Rable Qty: 0.00
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Document No. : RCPT0000000010 QC Type : SAMPLE CHECK Item Description : Leather Jackets Parameter Name Check Serial No : 1 Checke BAT HANDLE KYZ TEST 2	d Qty : 221.00	Valuandard OK Qty: 1.00 Valuandard OK Qty: 1.00	Actual 221.00 1.00 Quantity: 20 les Actual 0.00 1.00	Lower Rejected Qty: 0.0 1.00 Supplier Name QC Date Document Date Status 0.00 Lower Rejected Qty: 0.0	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	Result Cable Qty: 0.00 OK
Check Serial No : 1 Checke BAT HANDLE QC For : MATERIAL RECEIPT QC No. : QC0000026 Document No. : RCPT0000000010 QC Type : SAMPLE CHECK Item Description : Leather Jackets Parameter Name Check Serial No : 1 Checke BAT HANDLE KYZ TEST 2	Stand Qty : 10.00	Valuandard OK Qty: 1.00 Valuandard OK Qty: 1.00 1.00	Actual 221.00 1.00 Quantity: 20 les Actual 0.00 1.00	Lower Rejected Qty: 0.0 Supplier Name QC Date Document Date Status 0.00 Lower Rejected Qty: 0.0 1.00 Rejected Qty: 0.0	Upper 00 Rework 0 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.	Result Cable Qty: 0.00 OK Result Cable Qty: 0.00 OK OK