

Organization: ACME INDUSTRIES LTD.

Work C	Center Name: RBD Center ((WC000001)				
Shift Na	ame : Morning Shift					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS00001	Raw Binding Machine A	MACHINE	13	AZ90	256
Shift Na	ame : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS00001	Raw Binding Machine A	MACHINE	13	AZ90	256
Shift Na	ame : Morning Shift					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000011	Raw Binding Machine B	MACHINE	13	AZ20	25622
Shift Na	ame : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000011	Raw Binding Machine B	MACHINE	13	AZ20	25622
Shift Na	ame : Morning Shift					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000012	Raw Binding Machine C	MACHINE	13	AZ9022	25632
Shift Na	ame : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000012	Raw Binding Machine C	MACHINE	13	AZ9022	25632
Work C	Center Name : Vertical Caste	er Center (WC000002)				
Shift Na		, , ,				
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000002	Vertical Casting Machine A	MACHINE	14	DC23	787
2	WS000009	Vertical Casting Machine B	MACHINE	14	DC75	78711
3	WS000010	Vertical Casting Machine C	MACHINE	14	GC46	2783
Work C	Center Name: Horizontal C	aster Center (WC000003)				
Shift Na		, , ,				
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS00003	Horizontal Casting Machine A	MACHINE	14	GT34	345
Shift Na	ame : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000003	Horizontal Casting Machine A	MACHINE	14	GT34	345
Shift Na	ame : Morning Shift					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS00007	Horizontal Casting Machine B	MACHINE	14	GT34x	3456
Shift Na	ame : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.

24-Mar-2015, **11.54 AM** Page 1 of 2



Organization: ACME INDUSTRIES LTD.

1	WS000007	Horizontal Casting Machine B	MACHINE	14	GT34x	3456
Shift Nan	ne : Morning Shift					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000008	Horizontal Casting Machine C	MACHINE	14	GT89c	34511
Shift Nan	ne : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS00008	Horizontal Casting Machine C	MACHINE	14	GT89c	34511
Work Cer Shift Nan	· ·	er (WC000004)				
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
1	WS000004	Packing Machine A	MACHINE	14	PK34	7878
Shift Nan	ne : Evening					
SI.No.	Work Station Code	Work Station Description	Туре	Capacity	Model No.	Serial No.
					-	