MEENAKSHI POLYMERS PVT LTD.

DOC.No MPPL/F/QMS/09 /QG-02-MS-AAEE
REV NO- 00
REV. DATE - 00

CHECK SHEET- QUALITY GATE-2(VISUAL INSPECTION-100%), QGEI-WELD SHOP

PART NAME : STAND COMP. MAIN AAEE SHIFT - B LINE NO- Ro. No-04 DATE- 29/9/26

S.No	OPERATION NAME	DESCRIPTION	WELDER NAME	OBSERVATION 7 TO 9	9 TO 11	11 TO 1	1 TO 3	3 TO 5	5 TO 7	TOTAL
1	PIPE & PIPE CROSS	PUNCHER ROUND WELD PIPE CROSS			III - 3		III - 3			6
2		WELDING INCOMPLETE WELD PIPE CROSS								
3		EXCESS WELD								
4		WELDING SHIFT WELD PIPE CROSS								
5		GAS FAULT ON PIPE CROSS						II - 2		2
6	PIPE &PIVOT	PUNCHER ROUND WELD PIVOT & PIPE								
7		WELDING INCOMPLETE WELD PIVOT & PIPE			II - 2	III - 3	I - 1			6
8		EXCESS WELD								
9		WELDING SHIFT /MISS WELD PIVOT & PIPE								
10		WIRE SHOT								
11		GAS FAULT ON PIVOT								
12	PIPE & TREAD BAR PLATE (BOTTOM)	PUNCHER IN TREAD BAR PLATE (BOTTOM PLATE) WITH PIPE L/R				II - 2	I - 1			3
13		WELDING SHIFT IN TREAD BAR PLATE (BOTTOM PLATE) PIPE L/R								
14		WELDING CUT IN THREAD PLATE (BOTTOM PLATE)								2
15		EXCESS WELD IN TREAD PLATE (BOTTOM PLATE) PIPE L/R								2
16		WELDING MISS IN TREAD BAR PLATE (BOTTOM PLATE) PIPE L/R			II - 2					
17	PIPE & TRADE TUBE WITH TREAD PLATE	PUNCHER ON TREAD TUBE			II - 2		~~III III IIIIII~~ II - 22	III - 3	1	28
18		WELDING SHIFT/MISS ON TREAD TUBE								
19		WELDING INCOMPLETE ON TREAD TUBE								
20		EXCESS WELDING ON TREAD TUBE								3
21		PUNCHER IN TREAD BAR PLATE(TREAD SUPPORT PLATE)			III - 3					
22		EXCESS WELD TREAD SUPPORT PLATE						II - 2		2
23		WELDING SHIFT TREAD BAR PLATE(TREAD SUPPORT PLATE)								
24	PIPE & MAIN PLATE	PUNCHER ON MAIN PLATE				II - 2	III - 3			5
25		WELDING INCOMPLETE MAIN PLATE				II - 2				2
26		WELDING SHIFT MAIN PLATE							1	1
27		EXCESS WELDING ON MAIN PLATE								
28		WIRE SHOT				I - 1		II - 2		3
29		GAS FAULT ON MAIN PLATE			II - 2					2
30	PIVOT & PLATE STOPPER	WELDING SHIFT STOPPER PLATE							1	
31		EXCESS WELDING ON STOPPER PLATE				I - 1		I - 1		1
32		WELDING INCOMPLETE ON STOPPER PLATE								1
33		GAS FAULT ON STOPPER PLATE			I - 1					
34	PIPE & RIVET PIN	PUNCHER ON RIVET PIN								
35		WELDING INCOMPLETE ON RIVET PIN								
36		EXCESS WELDING ON RIVET PIN								
37		RIVET PIN BROKEN								
38		PIVOT ID UNDER SIDE								
39	VISUAL DEFECT	SPATTER								
40		MIG WIRE								
41		DENT								
42		SOUND								
43		CRACK ON PIPE								
44		PIPE BEND								
45		PLATE STOPPER OUT WELD								
TOTAL PRODUCTION					65	63	100	50	11	289
OK QTY (FIRST TIME RIGHT)					50	52	70	40	8	220
DEFECT QTY (REJECTION)					15	11	30	10	3	69
REWORK OK					15	11	30	10	3	69
STRAIGHT PASS					76 %	82 %	70 %	80 %	72 %	73 %
SCRAP QTY										
INSPECTION/CHIPPING PENDING QTY				Mohit	Mohit	Mohit	Mohit	Mohit		Mohit

NAME INSPECTOR:-

PREPARED BY:-

VERIFIED BY:-

APPROVED BY:-