MEENAKSHI POLYMERS PVT LTD.

DOC.No MPPL/F/QAD/39 /QG-02/BP-ACKA
REV NO-00
REV DATE-

CHECK SHEET- QUALITY GATE-2(VISUAL INSPECTION-100%), QGFI-WELD SHOP

PART NAME:-PEDAL BRAKE AAE SHIFT:- LINE NO:- DATE-

S.No	OPERATION NAME	DEFECT'S DESCRIPTION	WELDER NAME	OBSERVATION 7 TO 9	9 TO 11	11 TO 1	1 TO 3	3 TO 5	5 TO 7	TOTAL
1	PEDAL & PIPE WELDING	BLOW HOLE ROUND WELDING- PEDAL&PIPE		III	IIII	IIII	IIII	IIII III	IIII I	31
2		WELDING SHIFT-PEDAL & PIPE		IIII	IIII II	IIII III	IIII IIII	IIII IIII II	IIII II	49
3		WELDING INCOMPLETE-PEDAL & PIPE		II	II	III	IIII	IIII	II	18
4		EXCESS WELD ROUND WELDING-PEDAL&PIPE								
5		WIRE SHOT ROUND WELDING-PEDAL&PIPE		I	I					2
6		PEDAL CUT			I		I	II		4
7		GAS FAULT -PEDAL & PIPE				I		I		2
8	COLLOR & PIPE WELDING	BLOW HOLE ROUND WELDING- COLLOR&PIPE		II	III	II	III	IIII	III	19
9		WELDING SHIFT-COLLOR & PIPE		III	III	III	IIII	IIII	II	19
10		WELDING INCOMPLETE-COLLOR& PIPE		III	II	III	II	IIII	III	17
11		EXCESS WELD ROUND WELDING-COLLOR&PIPE		II	I	II	I	III	II	11
12		WIRE SHOT ROUND WELDING-COLLOR&PIPE						I		1
13		GAS FAULT -PEDAL & PIPE			I	I		II	I	5
14	COLLOR & MIDDLE ARM WELDING	WELDING SHIFT-COLLOR &MIDDLE ARM				I	I	II		4
15		WELDING INCOMPLETE-COLLOR&MIDDLE ARM		I	I		II	III	II	9
16		GAS FAULT -COLLOR&MIDDLE ARM								
17	MIDDLE ARM&RETURN SPRING BKT WELDING	WELDING SHIFT-RETURN SPRING BKT &MIDDLE ARM		I	II	III	II	IIII	III	15
18		WELDING INCOMPLETE-RETURN SPRING BKT&MIDDLE ARM		I	I	I	II	III	II	10
19		EXCESS WELDING -RETURN SPRING BKT&MIDDLE ARM					I	I		2
20		GAS FAULT -RETURN SPRING BKT&MIDDLE ARM			I	I				2
21	PIPE & STAY STOP SWITCH WIRE WELDING	WELDING SHIFT-PIPE & STAY STOP SWITCH WIRE		IIII III	IIII IIII	IIII IIII II	IIII IIII IIII	IIII IIII IIII IIII	IIII IIII I	76
22		WELDING INCOMPLETE-PIPE & STAY STOP SWITCH WIRE		III	IIII I	IIII I	IIII II	IIII IIII	IIII	35
23		GAS FAULT -PIPE & STAY STOP SWITCH WIRE WELDING			I	I		II	I	5
24		EXCESS WELDING -PIPE & STAY STOP SWITCH WIRE		II	II	II	I	III	I	12
25	PIPE & BAR GUIDE BKT WELDING	WELDING SHIFT-PIPE & STAY STOP SWITCH WIRE		IIII	IIII	IIII I	IIII III	IIII IIII II	IIII II	43
26		WELDING INCOMPLETE-PIPE & STAY STOP SWITCH WIRE		II	I	II	IIII	IIII II	III	19
27		GAS FAULT -PIPE & BAR GUIDE BKT WELDING				I		II	I	4
28		EXCESS WELDING -PIPE & STAY STOP SWITCH WIRE		II	II	III	IIII	IIII II	IIII	21
1	VISUAL DEFECT	BUSH CUT &CRACK			I	II	III	IIII	III	19
2		DENT & SCRATCH								
3		MATERIAL FAULT								
4		PEDAL EMBOSING MISS/WRONG PEDAL								
5		PIPE CRACK ON SEAM LINE								
6		EITCHING MISS ON ARM MIDDLE								
7		REAL MARK ON PIPE /WRINKLE/LINING				I	II	III	II	9
TOTAL PRODUCTION				200	300	400	500	600	400	2400
OK QTY (FIRST TIME RIGHT)				155	242	328	415	467	330	1987
DEFECT QTY (REJECTION)				45	58	72	85	133	70	463
REWORK OK				45	58	72	85	133	70	463
STRAIGHT PASS				77%	80%	82%	83%	77%	82%	80%
SCRAP QTY										
INSPECTION/CHIPPING PENDING QTY										
NAME & SIGNATURE INSPECTOR:-										

PREPARED BY: VERIFIED BY: APPROVED BY: