FI VISUAL INSPECTION 100%(POWDER COATING)

DATE- 28/09/26

REV DATE-01.06
REV NO.-02

O.	DESCRIPTION OF DEFECT	SARI GUARD-AAH	SARI GUARD-AAE	STEP WOMEN-AAH	STEP PILLION-AAE	SARI GUARD-AACY	STEP WOMEN AACY	ENGINE GUARD-KVH	CROSS PIPE AAEL	HANDEL ABZA	ENGINE GUARD-ABZA PAINTED	PEDAL BRAKE-	SIDE STAND ABZA	TOTAL	FOR REWORK		REJECTION	B-GRADE/GPC
															MINOR	MAJOR	SCRAP	
	PEEL OFF	09	13	—	—	—	—	—	—	—	—	—	—	22	—	—	—	
	TOUCHING	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
	DULL PAINT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
	PAINT DRY/LACK OF PAINT	78	69	05	09	—	—	—	06	—	—	06	—	173	—	—	—	
	UNCOVERAGE	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
	DUST	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
	PIN HOLE	69	41	—	—	—	—	—	—	—	—	—	—	110	—	—	—	
	ORANGE PEEL	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
	OIL MARK	08	06	08	28	—	—	—	—	—	—	—	—	50	—	—	—	
0	WATER FLOW/MARK	—	—	09	09	—	—	—	—	—	—	—	—	18	—	—	—	
1	CESSING	08	28	—	—	—	—	—	—	—	—	—	—	36	—	—	—	
2	PAINT OVER-FLOW	09	48	—	04	—	—	—	04	—	—	04	—	69	—	—	—	
3	PAINT MIXING	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
4	DENT/SCRATCH AFTER P C	05	14	—	—	—	—	—	—	—	—	04	—	23	—	—	—	
TAL		186	219	22	50	—	—	—	10	—	—	14	—	501				
	FABRICATION DEFECT																	
	BLOW HOLE	02	08	—	04	—	—	—	—	—	—	—	—	14	—	—	—	
2	WELDING SPATTER	04	08	04	08	—	—	—	03	—	—	05	—	32	—	—	—	
3	SPATTER SOUND	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
4	U-BKT NUT MISS/OUT	—	04	—	—	—	—	—	—	—	—	—	—	04	—	—	—	
5	U-BKT NUT BROKEN	—	03	—	—	—	—	—	—	—	—	—	—	03	—	—	—	
	SHIFT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
7	STAY BEND	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
8	U- BKT BEND	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
9	PIPE CHOCK	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
0	GRINDER MARK	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
1	DRAIN HOLE WRONG SIDE	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
2	PIPE CRECK/LINE	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
3	GAUGE OUT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
4	U-BKT THREAD WASH/NOT OK	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
5	DENT & SCRATCH	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
6	OVER WELDING	—	05	—	—	—	—	—	—	—	—	—	—	05	—	—	—	
7	WIRE SHORT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
8	WELDING IN COMPLETE	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
9	WELDING BROKEN BAR-A	—	04	—	—	—	—	—	—	—	—	—	—	04	—	—	—	
0	WELDING BROKEN BAR-B	02	08	—	—	—	—	—	—	—	—	—	—	10	—	—	—	
1	WELDING BROKEN BAR-C	—	06	—	—	—	—	—	—	—	—	—	—	06	—	—	—	
2	WELDING BROKEN BAR-D	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
3	WELDING BROKEN BAR-E	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
4	WELDING SHIFT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
5	METERIAL FAULT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
6	PUNCH MISS	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
	IFICATION/ MISS	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
8	NUT OUT WELD	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
9	NUT INSIDE WELD	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
0		—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
TAL		08	46	04	12	—	—	—	03	—	—	05	—	78	—	—	—	
TAL REJECTION OF THE DAY		194	265	26	62	—	—	—	13	—	—	19	—	579	—	—	—	
ODUCTION		1254	545	986	342	—	—	—	473	—	—	399	—	13399	—	—	—	
AIGHTPASS		87.18	95.2	99.36	98.83	—	—	—	97.73	—	—	95.64	—	95.83	—	—	—	
TAL REJECTION %																		
TAL REJECTION PPM.																		

VISION DETAIL	22.01.2025 -REV-1-FI CHECK SHEET COMMONIZE (DUBLE SHEET CONVERTED TO SINGAL SHEET)
	01.06.2025 -REV-2-FI REWORK REJECTION COLUMN ADDED,DEFECTS UPDATED AS PER CUSTOMER COMPLAINT AND FI/PDI

PARED BY- | CHECKED BY - | APPROVED BY:-

28/09/2026

28/09/26