MEENAKSHI POLYMERS PVT.LTD. HARIDWAR

DAILY MIS REPORT- A+B+C

DATE- :03-10-26

MONTH-OCT

DOC NO. MPPL/F/QAD/35/PL
REV.DATE-02-01-2018
ORG.01/08/2016
REV NO-02

SR.NO	DEFECT	REASON	CR AAEL	CR AAD	EG-KST	PB-AAE	PGC	HANDLE	TOTAL	RENICKEL	RECHROME	BUFFF	OK	B GRADE	SCRAP	TOTAL
1	PEEL OFF	PLATING SHOP	01	01	–	01	–	–	03	–	–	–	–	–	03	03
2	TOUCHING	PLATING SHOP	01	01	–	–	–	–	02	–	–	–	–	–	02	02
3	DULL PLATING	PLATING SHOP	45	21	08	04	03	04	83	83	–	–	–	–	–	83
4	CLAENING FAULT	PLATING SHOP	39	11	12	03	02	03	70	65	–	–	–	05	–	70
5	PLATING PITTING	PLATING SHOP	04	32	–	–	–	–	36	36	–	–	–	–	–	36
6	YELLOW	PLATING SHOP	73	91	04	200	100	04	472	–	472	–	–	–	–	472
7	ROUGHNESS	PLATING SHOP	26	27	120	–	–	–	173	–	–	173	–	–	–	173
8	PASSIVE BUFF	PLATING SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
9	CHROME BUFF	PLATING SHOP	08	05	–	147	–	–	160	–	–	160	–	–	–	160
10	HANDLE OD OVER SIZE	PLATING SHOP	–	–	–	–	–	68	68	–	–	–	68	–	–	68
	TOTAL PLATING DEFECT		197	189	142	355	105	79	1067	184	472	333	68	05	05	1067
	TOTAL PLATING DEFECT %															
11	CLEANING FAULT	WELD SHOP	10	03	–	02	–	–	15	15	–	–	–	–	–	15
12	SPATTER	WELD SHOP	05	05	–	04	–	–	14	–	–	–	14	–	–	14
13	MIG WIRE	WELD SHOP	02	04	01	–	–	–	07	–	–	–	07	–	–	07
14	PEDAL CUT	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
15	TRACIBILITY MISS	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
16	WELD PUNCTURE	WELD SHOP	06	09	07	06	–	–	28	–	–	–	28	–	–	28
17	WELD PIN HOLE	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
18	ID UNDER SIZE	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
19	WIRE SHORT	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
20	WELDING MISS	WELD SHOP	–	–	–	01	–	–	01	–	–	–	01	–	–	01
21	WELDING SHIFT	WELD SHOP	01	–	–	–	–	–	01	–	–	–	01	–	–	01
22	SPATTER SOUND	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
23	WELDING IN COMPLETE	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
24	EXCESS WELDING	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
25	GRINDING MARK	WELD SHOP	07	02	–	–	–	06	15	07	–	–	–	08	–	15
	TOTAL WELDING DEFECT		31	23	08	13	–	06	81	22	–	–	51	08	–	81
	TOTAL WELDING DEFECT %															
23	RUSTY MARK	BOP.	–	–	–	01	–	02	03	–	–	–	–	03	–	03
24	GRAIN OPENING	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
25	PGC THREAD MISS	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
26	MATERIAL FAULT	BOP.	06	10	09	01	–	20	46	16	–	–	–	30	–	46
27	MATERIAL PITTING	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
28	PGC THREAD OPPOSITE	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
29	LINE MARK	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
32	CD BEND /Sdoj	WELD SHOP	–	–	02	–	–	08	08	–	–	–	–	08	–	08
33	BAR LINE	PRESS SHOP	–	–	–	–	–	–	02	–	–	02	–	–	02	02
34	WRINKLE	MACHINE SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
35	DIE MARK ON PIPE	PRESS SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
	TOTAL BOP DEFECT		06	10	11	02	–	30	59	16	–	02	41	–	59	59
	TOTAL BOP DEFECT%															
36	DENT & SCRATCH	HANDLING	26	12	41	01	–	39	119	74	–	–	45	–	119	119
37	BUFFING NG	BUFFING SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
38	KNURLING SLIP	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
39	HANDLE PUNCH MISS	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
40	HANDLE STAMP MISS	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
	TOTAL OTHER PLATING DEFECT		–	–	–	–	–	–	–	–	–	–	–	–	–	–
	OTHER DEFECT %															
31	CENTERLESS MARK	center less shop	–	–	–	–	–	06	06	–	–	–	06	–	06	06
	TOTAL CENTER LESS DEFECT															
	CENTER LESS DEFECT %															
	OVER ALL TOTAL DEFECT		260	234	202	371	105	160	1332	296	472	333	121	105	05	1332
	TOTAL DEFECT %															
	TOTAL STRAIGHT PASS															
	PRODUCTION		3272	3380	4500	5040	7467	3600	26939							
	REWORK PLANT PRODUCTION															
	REWORK PLANT DEFECTIVITY															
	CUSTOMER RETURN DEFECTIVITY															
	TOTAL DEFECTIVITY															

Rejection 02/10/26

B-GRADE - CARRIER AAD = NOS. ENGINE GUARD = NOS , PEDAL BRAKE = NOS. , HANDLE = NOS. PGC = NOS.

PREPARED BY- AJAY UPADHYAY

REVIEWED BY- SURENDERA VERMA/ RAJEEV GAUR

APPROVED BY- PLANT HEAD

note