MEENAKSHI POLYMERS PVT.LTD. HARIDWAR

DAILY MIS REPORT-

DATE-: 25-09-26 MONTH- Sep-26

DOC NO. MPPL/F/QAD/35/PL
REV.DATE-02-01-2018
ORG.01/08/2016
REV NO-02

SR.NO	DEFECT	REASON	CR AAEL	CR AAD	EG-KST	PB-AAE	PGC	HANDLE	TOTAL	RENICKEL	RECHROME	BUFFF	OK	B GRADE	SCRAP	TOTAL
1	PEEL OFF	PLATING SHOP	–	01	02	–	–	–	03	–	–	–	–	–	03	03
2	TOUCHING	PLATING SHOP	01	01	–	–	–	–	02	–	–	–	–	–	02	02
3	DULL PLATING	PLATING SHOP	29	27	08	13	16	20	113	113	–	–	–	–	–	113
4	CLAENING FAULT	PLATING SHOP	24	19	21	06	–	03	73	70	–	–	–	03	–	73
5	PLATING PITTING	PLATING SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
6	YELLOW	PLATING SHOP	97	86	07	83	49	–	322	–	322	–	–	–	–	322
7	ROUGHNESS	PLATING SHOP	12	10	133	–	06	–	161	–	–	–	161	–	–	161
8	PASSIVE BUFF	PLATING SHOP	–	–	–	45	–	–	45	–	45	–	–	–	–	45
9	CHROME BUFF	PLATING SHOP	68	77	–	114	–	32	291	–	–	291	–	–	–	291
10	HANDLE OD OVER SIZE	PLATING SHOP	–	–	–	–	–	40	40	–	–	–	40	–	–	40
	TOTAL PLATING DEFECT		231	221	171	261	71	95	1050	183	367	291	201	03	05	1050
	TOTAL PLATING DEFECT %															
11	CLEANING FAULT	WELD SHOP	53	10	–	05	–	–	68	68	–	–	–	–	–	68
12	SPATTER	WELD SHOP	08	05	07	02	–	–	22	–	–	–	22	–	–	22
13	MIG WIRE	WELD SHOP	04	03	–	01	–	–	08	–	–	–	08	–	–	08
14	PEDAL CUT	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
15	TRACIBILITY MISS	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
16	WELD PUNCTURE	WELD SHOP	11	12	06	04	–	–	33	–	–	–	33	–	–	33
17	WELD PIN HOLE	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
18	ID UNDER SIZE	BOP.	–	–	–	05	–	–	05	–	–	–	05	–	–	05
19	WIRE SHORT	WELD SHOP	02	01	–	–	–	–	03	–	–	–	–	03	–	03
20	WELDING MISS	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
21	WELDING SHIFT	WELD SHOP	–	01	–	03	–	–	04	–	–	–	04	–	–	04
22	SPATTER SOUND	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
23	WELDING IN COMPLETE	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
24	EXCESS WELDING	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
25	GRINDING MARK	WELD SHOP	09	05	13	01	–	01	29	20	–	–	–	09	–	29
	TOTAL WELDING DEFECT		87	37	26	21	–	01	172	88	–	–	72	12	–	172
	TOTAL WELDING DEFECT %															
23	RUSTY MARK	BOP.	01	01	–	–	–	–	02	–	–	–	–	02	–	02
24	GRAIN OPENING	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
25	PGC THREAD MISS	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
26	MATERIAL FAULT	BOP.	26	16	123	03	–	27	195	160	–	–	–	35	–	195
27	MATERIAL PITTING	BOP.	06	06	–	–	–	01	13	12	–	–	–	01	–	13
28	PGC THREAD OPPOSITE	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
29	LINE MARK	BOP.	–	–	–	–	–	03	03	–	–	–	–	03	–	03
32	CD BEND	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
33	BAR LINE	PRESS SHOP	–	01	–	–	–	–	01	–	–	–	–	01	–	01
34	WRINKLE	MACHINE SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
35	DIE MARK ON PIPE	PRESS SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
	TOTAL BOP DEFECT		33	24	123	03	–	31	214	172	–	–	–	212	–	214
	TOTAL BOP DEFECT%															
36	DENT & SCRATCH	HANDLING	31	19	96	04	–	44	194	138	–	–	–	56	–	194
37	BUFFING NG	BUFFING SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
38	KNURLING SLIP	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
39	HANDLE PUNCH MISS	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
40	HANDLE STAMP MISS	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
	TOTAL OTHER PLATING DEFECT		31	19	96	04	–	44	194	138	–	–	–	56	–	194
	OTHER DEFECT %															
31	CENTERLESS MARK	center less shop	–	–	–	–	–	–	–	–	–	–	–	–	–	–
	TOTAL CENTER LESS DEFECT															
	CENTER LESS DEFECT %															
	OVER ALL TOTAL DEFECT		382	301	416	289	71	171	1630	581	367	291	273	113	05	1630
	TOTAL DEFECT %															
	TOTAL STRAIGHT PASS															
	PRODUCTION		1770	3350	2140	3060	7490	3140	23250							
	REWORK PLANT PRODUCTION															
	REWORK PLANT DEFECT QTY.															
	CUSTOMER RETURN DEFECT QTY.															
	TOTAL DEFECT QTY															

B-GRADE - CARRIER PAD = NOS. ENGINE GUARD = NOS , PEDAL BRAKE = NOS. , HANDLE = NOS. PGC = NOS.

PREPARED BY- AJAY UPADHYAY | REVIEWED BY- SURENDERA VERMA/ RAJEEV GAUR | APPROVED BY- PLANT HEAD

note