MEENAKSHI POLYMERS PVT.LTD. HARIDWAR

DAILY MIS REPORT- ATRTC.

DATE- : 29-09-26 MONTH- Sep

DOC NO. MPPL/F/QAD/35/PL
REV.DATE-02-01-2018
ORG.01/08/2016
REV NO-02

SR.NO	DEFECT	REASON	CR AAEL	CR AAD	EG-KST	PB-AAE	PGC	HANDLE	TOTAL	RENICKEL	RECHROME	BUFFF	OK	B GRADE	SCRAP	TOTAL
1	PEEL OFF	PLATING SHOP	02	–	01	–	–	–	03	–	–	–	–	–	03	03
2	TOUCHING	PLATING SHOP	02	01	–	–	–	–	03	–	–	–	–	–	03	03
3	DULL PLATING	PLATING SHOP	29	24	03	14	08	04	82	82	–	–	–	–	–	82
4	CLAENING FAULT	PLATING SHOP	49	08	19	–	–	07	83	76	–	–	–	07	–	83
5	PLATING PITTING	PLATING SHOP	04	02	–	27	–	–	33	33	–	–	–	–	–	33
6	YELLOW	PLATING SHOP	62	88	08	129	46	09	342	–	342	–	–	–	–	342
7	ROUGHNESS	PLATING SHOP	12	10	120	–	–	–	142	–	–	–	142	–	–	142
8	PASSIVE BUFF	PLATING SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
9	CHROME BUFF	PLATING SHOP	12	10	–	90	–	03	115	–	–	115	–	–	–	115
10	HANDLE OD OVER SIZE	PLATING SHOP	–	–	–	–	–	50	50	–	–	–	50	–	–	50
TOTAL PLATING DEFECT			172	143	151	260	54	73	853	191	342	115	192	07	06	853
TOTAL PLATING DEFECT %																
11	CLEANING FAULT	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
12	SPATTER	WELD SHOP	09	05	02	07	–	–	23	–	–	–	23	–	–	23
13	MIG WIRE	WELD SHOP	04	05	03	–	–	–	12	–	–	–	12	–	–	12
14	PEDAL CUT	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
15	TRACIBILITY MISS	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
16	WELD PUNCTURE	WELD SHOP	16	11	07	03	–	–	37	–	–	–	37	–	–	37
17	WELD PIN HOLE	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
18	ID UNDER SIZE	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
19	WIRE SHORT	WELD SHOP	04	06	01	–	–	–	11	–	–	–	–	11	–	11
20	WELDING MISS	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
21	WELDING SHIFT	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
22	SPATTER SOUND	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
23	WELDING IN COMPLETE	WELD SHOP	–	01	–	–	–	–	01	–	–	–	01	–	–	01
24	EXCESS WELDING	WELD SHOP	–	01	–	–	–	–	01	–	–	–	01	–	–	01
25	GRINDING MARK	WELD SHOP	02	12	–	–	–	03	17	12	–	–	–	05	–	17
TOTAL WELDING DEFECT			35	41	13	10	–	03	102	12	–	–	74	16	–	102
TOTAL WELDING DEFECT %																
23	RUSTY MARK	BOP.	–	–	–	–	–	02	02	–	–	–	–	02	–	02
24	GRAIN OPENING	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
25	PGC THREAD MISS	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
26	MATERIAL FAULT	BOP.	19	32	16	05	–	15	87	62	–	–	–	25	–	87
27	MATERIAL PITTING	BOP.	05	18	36	–	–	06	65	54	–	–	–	11	–	65
28	PGC THREAD OPPOSITE	BOP.	–	–	–	–	–	–	–	–	–	–	–	–	–	–
29	LINE MARK	BOP.	–	–	–	–	–	06	06	–	–	–	–	06	–	06
32	CO BEND	WELD SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
33	BAR LINE	PRESS SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
34	WRINKLE	MACHINE SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
35	DIE MARK ON PIPE	PRESS SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
TOTAL BOP DEFECT			24	50	52	05	–	29	160	116	–	–	–	44	–	160
TOTAL BOP DEFECT%																
36	DENT & SCRATCH	HANDLING	32	18	41	02	–	120	213	83	–	–	–	130	–	213
37	BUFFING NG	BUFFING SHOP	–	–	–	–	–	–	–	–	–	–	–	–	–	–
38	KNURLING SLIP	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
39	HANDLE PUNCH MISS	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
40	HANDLE STAMP MISS	FEBRACTION	–	–	–	–	–	–	–	–	–	–	–	–	–	–
TOTAL OTHER PLATING DEFECT			32	18	41	02	–	120	213	83	–	–	–	130	–	213
OTHER DEFECT %																
31	CENTERLESS MARK	center less shop	–	–	–	–	–	06	06	–	–	–	–	06	–	06
TOTAL CENTER LESS DEFECT																
CENTER LESS DEFECT %																
OVER ALL TOTAL DEFECT			263	252	257	277	54	231	1334	402	342	115	266	203	06	1334
TOTAL DEFECT %																
TOTAL STRAIGHT PASS																
PRODUCTION			2067	3349	4140	3753	5420	3520	22849							
REWORK PLANT PRODUCTION																
REWORK PLANT DEFECT QTY.																
CUSTOMER RETURN DEFECT QTY.																
TOTAL DEFECT QTY																

B-GRADE - CARRIER PAD = NOS, ENGINE GUARD = NOS , PEDAL BRAKE = NOS. , HANDLE = NOS. PGC = NOS.

PREPARED BY- AJAY UPADHYAY

REVIEWED BY- SURENDERA VERMA/ RAJEEV GAUR

APPROVED BY- PLANT HEAD

note