

 VALUE INTEGRATOR	MAINTENANCE WORK FORMS	SOP No: MAW154
	Clean out filters on electrical panels	Rev: 00 Date: 24-JUL-2025

No.	INSTRUCTIONS	KEY POINTS / CONTACTS
1.	<p>Check out all humidifier filters.</p> 	<p>ENSURE PERSONNAL PROTECTIVE EQUIPMENT (PPE) IS WORN: - 1. HARD HAT 2. STEEL CAP BOOTS 3. EYE PROTECTION</p> <p>ENSURE LOCK- OUTS AND SAFETY BLOCKS ARE USED AT ALL TIMES.</p> <p>PPE REQUIRED AT THIS AREA</p> 
2.	<p>Remove filter by lifting it up and out.</p> <p>If the filter is dirty, cut out new filters from material roll kept in the stores.</p>  	
3.	<p>Lock out the filter and blow out any dust from components,</p> <p>Use a dusk mask.</p>	



Controlled By: Maintenance

Approved By: Pending Approval

Date: 24 07 2025

Page [page] of [toPage]

UNCONTROLLED WHEN PRINTED WITHOUT RED CONTROLLED STAMP & SIGNATURES