

 VALUE INTEGRATOR	MAINTENANCE WORK INSTRUCTIONS	SOP No: PW22
	DRY FLOOR SWEEPER	Rev: 02
		Date: 20 OCT 2025

No.	INSTRUCTIONS	VISUALS	KEY POINTS / CONTACTS
1.	Check out all humidifier filters. REV2		<p>ENSURE PERSONNAL PROTECTIVE EQUIPMENT (PPE) IS WORN: -</p> <p>1. HARD HAT 2. STEEL CAP BOOTS 3. EYE PROTECTION</p> <p>ENSURE LOCK- OUTS AND SAFETY BLOCKS ARE USED AT ALL TIMES.</p>
2.	Remove filter by lifting it up and out. If the filter is dirty, cut out new filters from material roll kept in the stores.		
3.	Lock out the filter and blow out any dust from components, Use a dusk mask.		

Controlled By:	Maintenance	Approved By:	Zondi, Ndumiso	Page 1 of 1
Date: Monday, October 20, 2025				

UNCONTROLLED WHEN PRINTED WITHOUT RED CONTROLLED STAMP & SIGNATURES