

PHARMACEUTICAL PRODUCT COMPLAINT & DEFECT ADVISORY

CLASSIFICATION: URGENT STERILITY & PACKAGING DEFECT (21 CFR PART 211 COMPLIANT)

Document Reference: QA-CMP-2024-00918 | **Incident Date:** 2024-09-14

Customer Name: Great Lakes Regional Trauma Center (Pharmacy Operations)

Complaint Source: Hospital Critical Care Pharmacist Direct Hotline

Parameter	Details
Product Name	Ciprofloxacin Injection 200mg/100mL (Sterile FDF)
Strength / Grade	200 mg / 100 mL Solution for Infusion (USP Grade)
Batch / Lot Number	CIP-INJ-2024-1102
Manufacturing Date	2024-04-10
Expiration Date	2026-04-09
Originating Site Block	Aseptic Fill-Finish Block A (Cleanroom ISO 5)
Quantity Affected	850 vials (17 shipper cartons)
Impacted NPM	Type I Borosilicate Glass Vial & Chlorobutyl Rubber Stopper
Initial Severity	Critical
Priority	Urgent

Defect Description & Clinical Impact:

During pre-administration inspection in the Intensive Care Unit, clinical pharmacists discovered hairline fractures along the neck curvature beneath the aluminum flip-off crimp seal in multiple vials of Lot CIP-INJ-2024-1102. Liquid seepage was confirmed upon gentle inversion, accompanied by loss of container-closure integrity (CCI). This represents an acute compromise of sterility for an injectable drug product, presenting severe bacteremia / sepsis risks if administered. Immediate product quarantine has been enforced across all hospital satellite pharmacies.

Preliminary Containment & Recommended CAPA:

Immediate recall protocol evaluation required. Root cause hypothesis points to crimping head pneumatic pressure calibration on Aseptic Capping Station #2 following the April 2024 preventative maintenance window. Full visual inspection of retained reserve samples at the manufacturing plant is urgently requested.