To wead a pain of input co-oudinates in BCD and move the curson i at specified position.

. model small

disp macro meg

lea dx, msg

mov ah, 09H

int 21H

endm

. data

new db 02 dup(?)

migl db odb. orah. "Enter x-coordinate's" mig2 do Odh. Oah. "Enter y-coordinate \$" . code mor ax, adata mov ds, ax disp msq1 lea si, now call read disp msq2 lea si, column call read lea si, now moy ah, [si] inc si mov al, [si] sub ax, 3030 H acid mov dh, & al mov ah, OOH mov al, O3H int 10H mor ah, 02H int 10H imp final read prior near mov Cx, O2H back: mov ah, OIH mov [si], al dec ex

jnz back PAGE NO. DATE: 1 1 gread endp final: mov ah, OIH Ent 21H mov an, 4ch int 21H end

