
2001



Upd: 22 NOV 2005

2001

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	840701	2		NOTES
2	970945		Screw	(955315)
3	838262	2		(000010)
4	959236	2		L = 20 MM
4A	941908	2		L - ZO WIWI
5	971071	2		(955783)
6	940109	2	Lock washer	
7	859898	1		(840804)
8	840829	2		
9	941906		Spring washer	
10	955781	2		
11	840348	2		
12	955821	4	Nut	
13	829892	8	Lock washer	
14	840421	2		SN-19215. REPLACED BY ENGINE BRACKET 858591 AND 858592 PLUS 6EA SCREW 955320
	858591	1	Engine mountings	P SN19216-
				REPL BY 860344
	858592	1	Engine mountings	S.B MO19216-
				REPL BY 860343
14A	860344	1	Engine bracket	P
1 17 (	860343	1		S.B
15	955318	6	Screw	FOR 840421
	970950	6		(955320)
				FOR 858591-858592
				860343-860344
16	840338	2	Rubber element	EARLY TYPE
16	838262		Rubber element	
16A	838264	2	Adjuster screw	FOR 838262
16B	838263	2	Attaching plate	
16C	949149	2		
17	955805	4		FOR 840338
	955806	4	Nut	FOR 838262
L		_		500.04000
18	829892	8		FOR 840338
	829893	8	Lock washer	FOR 838262
404	04.4000	4	Allen was a st	
18A	914003	1	Allen wrench	