
2003



10626

Upd: 22 NOV 2005

**02A** 

Upd: 22 NOV 2005

2003

7726000 - 02A - 02A-5300

REF	PART NO.	QTY	DESCRIPTION		SEE SEC.	NOTES
1	858498	1	Cylinder block			REPLACED BY 1EA CYLINDER BLOCK 860235,3EA O-RINGS 97896
						FOR SEALING OF FUEL INJECTION PUMPS + SPACER 6EA
						860211 TJ=0,20MM,3EA 838298 TJ=0,30MM,3EA 838299 TJ=0,
						60MM AND 3EA 838300 TJ=0,90MM.
						SN-2300041589
					02A-5320	
2	477024	3	<ul> <li>Expansion plug</li> </ul>			(192211)
3	463360		Bushing			
4		2	BEARING CAP			
5	963257		· Screw			
6	840210	8	Washer			
7	3875305	6	Guide sleeve			
8	33.333	1	OIL SUMP			*
9	840588	1				*
10	840713	1				
11	946778	1	Cap plug			
12	955300		Screw			
13	941907	12	Spring washer			
14	840889	14	Cylinder liner			
15	950885	2			1	
16	943177	1		IK		
17	943177	1		IK		
	967590					
18	967592	1		IK		
19	947893	1	Drain cock			
20	950586	4				
21	840846	1				
22	924061		Stud			
23	192154	1				(000470) (050504)
24 25	838929 838928	1	Zinc anod Plug			(800476) (858501) (800475)

10626