

10270

Upd: 22 NOV 2005

| | | _ | | | 1 |
|----------|----------|---|------------------|----------|---|
| REF | PART NO. | | DESCRIPTION | SEE SEC. | |
| 1 | 829527 | 1 | Starter motor | | 1-POLE. REPLACED BY STARTER MOTOR 859252,GROUND CABLE 968048 AND NUT 945408. ALSO AVAILABLE AS AN EXCHANGE PART. |
| | | | | 030-1130 | |
| | 859252 | 1 | Starter motor | | 2-POLE. ALSO AVAILABLE AS AN EXCHANGE PART. |
| | | | | 030-1150 | |
| 1A | 968048 | 1 | | | FOR 859252 |
| 1B | 968862 | 1 | Nut | | FOR 859252 (945408) |
| 2 | 959239 | 3 | Screw | | |
| 3 | 941908 | | Spring washer | | |
| 4 | 942551 | 3 | Washer | | |
| 5 | 012001 | 1 | | 030-0775 | |
| 6 | 840672 | 1 | Attaching plate | | |
| 7 | 941793 | 1 | | | + |
| - | 824823 | | Fuse box | | |
| 8 | | | | | |
| 9 | 955247 | 1 | | | (0.40700) 40) //50 A |
| 10 | 860339 | | Relay | | (846762) 12V/50A |
| 11 | 858683 | 1 | | | FOR W |
| 12 | 955119 | | Screw | | |
| 13 | 970945 | | Screw | | (955315) |
| 13A | 940109 | | Lock washer | | |
| 14 | 846648 | | Extension cable | | L = 3000 MM |
| | 846649 | | Extension cable | | L = 5000 MM |
| | 846650 | | Extension cable | | L = 7000 MM |
| | 0.0000 | | ZACHOICH COLOR | | |
| 15 | 859058 | 1 | Instrument panel | 030-1337 | |
| 16 | 1324750 | 4 | Pressure monitor | 030-1337 | |
| 16 17 | 833927 | 1 | | | |
| | | | | | |
| 18 | 947624 | 1 | Gasket | | |
| 20 | 858642 | 1 | Bracket | | |
| 21 | 955271 | 1 | Screw | | |
| 22 | 963105 | 1 | Nut | | |
| 23 | 948210 | X | | | |
| | | | | | |
| | | | | | |

7726000 - 030 - 030-0283C 10270 Upd: 22 NOV 2005