
2002



10624



Upd: 22 NOV 2005

02A

2002

		_			
REF				SEE SEC.	NOTES
1	840977	1	Cylinder block		REPLACED BY 1EA CYLINDER BLOCK 860234,2EA O-RINGS 978961 FOR SEALING OF FUEL INJECTION PUMPS + SPACER 4EA 860211 TJ=0,20MM,2EA 838298 TJ=0,30MM,2EA 838299 TJ=0,60MM AND 2EA 838300 TJ=0,90MM.
				02A-5160	·
2	477024	2	Expansion plug	02.10100	(192211)
3	463360	3	Bushing		
4		1			
5	963257	6			
6	840210	6			
7	3875305	4			
8	00.000		· OIL SUMP		*
9	840588	1			*
10	840713	1			
11	946778	1			
12	955300	8	Screw		
13	941907	8	Spring washer		
14	840889	2	Cylinder liner		
15	192134		• Plug		
16	943177	1	O-ring		
17	967590	1	O-ring		
18	967592	1			
19	947893	1			
20	950586	4			
21	924061	4	Stud		
22	840846	1			