
2002



Upd: 22 NOV 2005

2002

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	840701	2		NOTED
2	970945	6	Screw	(955315)
3	838262	2		(000010)
4	959236	2		L = 20 MM
4A	941908	2		
5	971071	2	Nut	(955783)
6	940109	2	Lock washer	
7	859898	1		(840804)
8	840829		Rubber element	
9	941906	2	Spring washer	
10	955781	2	Nut	
11	840348	2	Adjusting plate	
12	955821	4	Nut	
13	829892	8	Lock washer	
14	840421	2		SN-19215. REPLACED BY ENGINE BRACKET 858591 AND 858592 PLUS 6EA SCREW 955320
	858591	1	Engine mountings	P SN19216-
				REPL BY 860344
	858592	1	Engine mountings	S.B SN19216-
				REPL BY 860343
440	000044	4	Engine breekst	P
14A	860344 860343	1		S.B
	000343	I	Engine bracket	5.0
15	955318	6	Screw	FOR 840421
	970950	6		(955320)
				FOR 858591-858592
				860343-860344
16	838262	2	Rubber element	
400	000004	_	A divista a same	
16A 16B	838264 838263	2	Adjuster screw Attaching plate	
16C	949149	2	Screw	
17	955806	4		(955821)
18	829893	8		(000021)
18A	914003	1		
	0.1000			