
2002



Upd: 22 NOV 2005

2002

REF	PART NO.	QTY			NOTES
1	840701	2	Engine mountings		
2	970945	6			(955315)
3	838262	2			
4	959236	2	Screw		L = 20 MM
4A	941908	2	Spring washer		
5	971071	2			(955783)
6	940109	2			
7	859898	1			(840804)
8	840829	2	Rubber element		
9	941906		Spring washer		
10	955781	2	Nut		
	0.100.10		A 11		
11	840348	2	Adjusting plate		
12	955821	4			
13	829892		Lock washer		ON 40045 DEDI AGED BY ENGINE DRAGUET OFFICA AND OFFICA BLUG OF A
14	840421	2	Engine mountings		SN-19215. REPLACED BY ENGINE BRACKET 858591 AND 858592 PLUS 6EA SCREW 955320
14	858591	1	Engine mountings		S.B SN19216-
' -	000091	<u> </u>	Engine mountings		REPL BY 860344
	858592	1	Engine mountings		P SN19216-
	030332		Lingine mountings		REPL BY 860343
					NET E DT 000040
14A	860344	1	Engine bracket		S.B
	860343	1			P
15	955318	6	Screw		FOR 840421
	970950	6			(955320)
	0.000				FOR 858591-858592
					860343-860344
16	840845	2	Rubber element		
16A	838264	2	Adjuster screw		
16B	838263	2	Attaching plate		
16C	949149	2	Screw		
17	955806	4	Nut		(955821)
18	829893	8			
18A	914003	1	Allen wrench		
19	840861	1			
20	955395	1			
21	955786	1			
22	840348	2			
23	955805	4			(955821)
24	829892	8	Lock washer		
				_	