



Association Services of Florida 10112 USA Today Way

Miramar, Florida 33025 **P**: (954)922-3514

PROPOSAL REPORT FOR:

Star Paradise Condominium Apartments Inc 415 NE 2nd Street Hallandale Beach, Fl 33009

Summary Details For RFP No.992777:

Reference Name: concrete restoration Industry Solicited: Structural Concrete, Steel, Shear, Curtainwall

RFP Close Date & Time: 12-06-2011 18:00 Location where work is to be performed: Other

Projected Contract Term: one time

Proposal Overview Details:

Proposals Submitted: 4 Alt.Proposals Submitted: 0 High Bid: \$29,377.00 Low Bid: \$8,000.00 Average Bid: \$13,861.75

VENDOR 1 VENDOR 2 VENDOR 3 VENDOR 4 No image **F. TANATUM** ommercial and Residential Orion Contracting **ANATOM Construction Company** Pro-Max Restoration & Paint Corp Arpin & sons 312 S. Old Dixie Hwy,, 8461 Lake Worth Road, 12355 sw 129 ct, 4920 N dixie hwy, oakland park, Jupiter, Lake Worth, Miami. Florida 33467 Florida 33186 Florida 33334 Florida 33458 In-House Vendor? No In-House Vendor? No In-House Vendor? No In-House Vendor? No Company Phone: (561) 847-2870 Company Phone: (954) 772-8345 Company Phone: (561) 745-7800 Company Phone: (305) 253-7900 Extension: 0 Extension: 0 Extension: 0 Extension: 200 Alt.Phone: () -Alt.Phone: (561) 745-7800 Alt.Phone: () -Alt.Phone: (305) 253-7900 Alt.Extension: 0 Alt.Extension: 0 Alt.Extension: 0 Alt.Extension: 0 Year Business Established: 1980 Year Business Established: 2002 Year Business Established: 2005 Year Business Established: 1994 Contact: Don Arpin Contact: Paul Damigos Contact: Luis R. Valderrama Contact: Maximilian Tower orioncontracting@bellsouth.net LRV@anatomconstruction.com max@promaxrestorationandpaint.com arpin2@bellsouth.net Mobile Phone: (954) 772-3699 Mobile Phone: (561) 662-0946 Mobile Phone: () -Mobile Phone: (305) 494-8040 **TOTAL AMOUNT PROPOSED TOTAL AMOUNT PROPOSED TOTAL AMOUNT PROPOSED TOTAL AMOUNT PROPOSED** \$8,000.00 \$9,900.00 * \$29,377.00 \$8,170.00 Alternate Proposal Provided? Alternate Proposal Provided? Alternate Proposal Provided? Alternate Proposal Provided? No No No No Alt.Price: N/A Alt.Price: N/A Alt.Price: N/A Alt.Price: N/A

st Designates exception for 1 or more line items. Please see vendor notes for details.





Association Services of Florida

10112 USA Today Way Miramar, Florida 33025 **P**: (954)922-3514

LINE ITEM #1: All second floor edge of catwalk. Engineering Specifications Attached

Attachment for Line Item 1:engeneer.pdf

VENDOR 1 NOTES:

NOTES :Repair appx. 200 Lin ft of balcony edge and 3.5 sq. ft. of ceiling spall per site visit and take off. include plans and GC permit......exclude city/county permit fees.....

LINE ITEM PRICE:

\$ 29.377.00

VENDOR 2 NOTES:

ATTACHMENT(S):

STAR_PARADISE_CONDO_PROPOSAL.pdf

LINE ITEM PRICE:

\$8.170.00

VENDOR 3 NOTES:

LINE ITEM PRICE:

\$ 8,000.00

VENDOR 4 NOTES:

NOTES: Proposal Information. Also see attachments. From my visual inspection I saw about 80 lineal feet of concrete edge repair. Mobilization/General Conditions: \$2500.00 Permitting Allowance: \$750.00 Edge Repairs (80 lineal feet @ \$75): \$6000.00 Total: \$9,250.00 This proposal is based on completing the repairs in accordance with the engineering drawings provided in the bid package. This proposal excludes any additional engineering, shoring, moving electrical equipment, railing replacement, repainting, or any other item not specified in this Proposal. The quantities for edge repair may +/- depending on the actual amount of deteriorated concrete that is found after the sounding and excavation of the suspected areas. Pro-Max will not demolish or repair any areas without the prior written approval of the engineer/association.

EXCEPTION(S):

Please be advised we have done a best-faith observation and estimate, however there is no way for us to know how far the deterioration really goes and what exactly needs to be removed without sounding out all of the suspected areas. This is typically the engineer's responsibility to do this inspection and also provide the estimated set of quantities for each type of repair required. Our typical contract is based the engineer's estimate, and in this case on our observation and the general engineering instruction. Estimated quantities will vary up or down depending on actual conditions encountered. NOTE AND PLEASE BE ADVISED THAT DAMAGE BEYOND THAT OBSERVABLE MAY RESULT IN INCREASED SCOPE OF WORK AND THUS COST.

ATTACHMENT(S):

Pro-Max_Brochure_2011.pdf

ATTACHMENT(S):

Licenses, insurances and Certificates (No letterhead)12.5.11.pdf

LINE ITEM PRICE:

\$ 9,250.00

All other items, charges & fees not itemized above

| VENDOR 1: | \$ 0.00 |
|-----------|-----------|
| | |
| VENDOR 2: | \$ 0.00 |
| | |
| VENDOR 3: | \$ 0.00 |
| | - |
| VENDOR 4: | \$ 650.00 |

SPECIAL REQUIREMENTS -- Vendors meet the following requirements:

Licensed

Professional

Insured

Worker's Comp General Liability

Minimum Liability Insurance Amount Required:\$

Property Association MUST Be Listed As An "Additional Insured" Management Company MUST Be Listed As An "Additional Insured"

VENDOR 1:

OLN License: Occupational_Licenses-.pdf,Occupational_Licenses-.pdf

PLN License: ArpinGC.pdf,PE_LicenseArpin.pdf

GLI Insurance: GL-Arpin.pdf WCI Insurance: WC-Arpin.pdf

W9: W9-Arpin.pdf

VENDOR 2:

OLN License: img001.pdf PLN License: img002.pdf GLI Insurance: img003.pdf WCI Insurance: img004.pdf

W9: img005.pdf

VENDOR 3:

OLN License: PB_Occ.pdf
PLN License: FL_MoldRem.pdf,FL_GCCert.pdf

GLI Insurance: Acord-GL.pdf

WCI Insurance: WC-FLExemption.pdf

W9: W9-A.pdf

VENDOR 4:

OLN License: img357.pdf PLN License: img358.pdf

GLI Insurance: Acord-Promax.pdf,Acord-Promax.pdf

WCI Insurance: Acord-Promax.pdf

W9: img360.pdf