







San diego, California 92105 **P**: (654) 987-6549



PROPOSAL REPORT FOR:

Ocean Beach Residency 234 San Diego City, CA 92115

Summary Details For RFP No.183994:

Reference Name: Ocean Beach Residency Phase One

Industry Solicited: Landscape Architect RFP Close Date & Time: 07-27-2012 16:00

Location where work is to be performed: All Lawn and Planting Areas Include private residences/lots,Common areas,Gate/Guard House

Proposal Overview Details:

Proposals Submitted: 1 Alt.Proposals Submitted: 0 High Bid: \$2,300.00 Low Bid: **\$2,300.00** Average Bid: **\$2,300.00**



^{*}Designates exception for 1 or more line items. Please see vendor notes for details.

RFP TASKS REQUESTED

LINE ITEM #1: Ocean Beach Residency Phase One.

See attached Aerial View for current configuration (2X Half Courts) - To be replaced with single FULL COURT.

- 1) Remove exisiting hoops and posts. Fill/patch removed posts...
- 2) Install two new gooseneck Basketball hoops at ends of court creating a full court. The Board had previously selected a style hoop from a website model # PR52 at www.basketballhoopsunlimited.com. http://www.basketballhoopsunlimited.com/store/Scripts/prodView.asp?idproduct=77 Additional example photos attached in "Additional Documents". Substitutions must be same style and equal or better quality/materials.
- 3) The current surface appears to be in fairly good condition, I believe it is asphalt with a green painted surface but I did observe two large cracks. These should be filled/sealed for safety and appearance.
- 4) Remove existing painted keys (remove/coat over for smooth surface, best recommendation(s) for economy & durability of new coating/paint) and repaint keys for full court.

Attachment for Line Item 1:None

VENDOR 1:

LINE ITEM PRICE: \$ 1,000.00

NOTES:test

EXCEPTION(S): teste

LINE ITEM #2: Secon.

See attached Aerial View for current configuration (2X Half Courts) - To be replaced with single FULL COURT.

- 1) Remove exisiting hoops and posts. Fill/patch removed posts...
- 2) Install two new gooseneck Basketball hoops at ends of court creating a full court. The Board had previously selected a style hoop from a website model # PR52 at www.basketballhoopsunlimited.com. http://www.basketballhoopsunlimited.com/store/Scripts/prodView.asp?idproduct=77 Additional example photos attached in "Additional Documents". Substitutions must be same style and equal or better quality/materials.
- 3) The current surface appears to be in fairly good condition, I believe it is asphalt with a green painted surface but I did observe two large cracks. These should be filled/sealed for safety and appearance.
- 4) Remove existing painted keys (remove/coat over for smooth surface, best recommendation(s) for economy & durability of new coating/paint) and repaint keys for full court.

Attachment for Line Item 2:None

VENDOR 1:

LINE ITEM PRICE: \$ 100.00

NOTES: See attached Aerial View for current configuration (2X Half Courts) - To be replaced with single FULL COURT.

- 1) Remove exisiting hoops and posts. Fill/patch removed posts...
- 2) Install two new gooseneck Basketball hoops at ends of court creating a full court. The Board had previously selected a style hoop from a website model # PR52 at www.basketballhoopsunlimited.com.

http://www.basketballhoopsunlimited.com/store/Scripts/prodView.asp?idproduct=77

Additional example photos attached in "Additional Documents". Substitutions must be same style and equal or better quality/materials.

- 3) The current surface appears to be in fairly good condition, I believe it is asphalt with a green painted surface but I did observe two large cracks. These should be filled/sealed for safety and appearance.
- 4) Remove existing painted keys (remove/coat over for smooth surface, best recommendation(s) for economy & durability of new coating/paint) and repaint keys for full court.

EXCEPTION(S): See attached Aerial View for current configuration (2X Half Courts) - To be replaced with single FULL COURT.

- 1) Remove exisiting hoops and posts. Fill/patch removed posts...
- 2) Install two new gooseneck Basketball hoops at ends of court creating a full court. The Board had previously selected a style hoop from a website model # PR52 at www.basketballhoopsunlimited.com.

http://www.basketballhoopsunlimited.com/store/Scripts/prodView.asp?idproduct=77

Additional example photos attached in "Additional Documents". Substitutions must be same style and equal or better quality/materials.

- 3) The current surface appears to be in fairly good condition, I believe it is asphalt with a green painted surface but I did observe two large cracks. These should be filled/sealed for safety and appearance.
- 4) Remove existing painted keys (remove/coat over for smooth surface, best recommendation(s) for economy & durability of new coating/paint) and repaint keys for full court.

All other items, charges & fees not itemized above

VENDOR 1:

\$ 1,000.00

SPECIAL REQUIREMENTS -- Vendors meet the following requirements:

Licensed

Professional

VENDOR 1:

Professional License: OLN_Allied_Local_Business_Tax_Receipt.jpg,Barbie_Doll.jpg General Liability Insurance: Smarty_10_on_@Wc-2.6.5-docs.pdf

Workers Comp Insurance:

W-9: Scan2.jpg

WARRANTY-INFO: No Files

Warranty: test

NOTES:General notes test...

EXCEPTION(S):General exception test...