



Association Services of Florida 10112 USA Today Way Miramar, Florida 33025 P: (954)922-3514

# PROPOSAL REPORT FOR:

Sandpiper Landing Association Inc aka Regency Lakes 6501 Sandpiper Dr. Coconut Creek, Fl 33073

# **Summary Details For RFP No.515201:**

Reference Name: sidewalk

Industry Solicited: Roadway/Driveway/Walkway - Asphalt/Concrete/Pavers

RFP Close Date & Time: 11-30-2011 12:00

Location where work is to be performed: Common areas

Projected Contract Term: one time

# **Proposal Overview Details:**

Proposals Submitted: 3 Alt.Proposals Submitted: 0 High Bid: \$19,100.00 Low Bid: \$4,250.00 Average Bid: \$10,842.33

VENDOR 1	VENDOR 2	VENDOR 3
	50	
Eskimo Construction, A/C & Refrigeration, Inc.	Arpin & sons	1-800 Asphalt, Inc.
ઁ૽૾૽૾૽૾૽૾૽૽૾	ಿಕಕಕ	ૼૢ૽ૼૡ૽ૡૼૡૼ
8900 Woodlake Blvd, Suite 203, Lake Worth, Florida 33463	4920 N dixie hwy , oakland park, Florida 33334	1309 SW 21st Terr, Ft. Lauderdale, Florida 33312
In-House Vendor? <b>No</b>	In-House Vendor? <b>No</b>	In-House Vendor? No
Company Phone: (561) 210-7283	Company Phone: (954) 772-8345	Company Phone: (954) 588-4467
Extension: 1	Extension: 0	Extension: 0
Alt.Phone: (561) 210-7283	Alt.Phone: () -	Alt.Phone: (800) 277-4258
Alt.Extension: 1	Alt.Extension: 0	Alt.Extension: 0
Year Business Established: 2010	Year Business Established: 1980	Year Business Established: 2010
Contact: Damian Carrera	Contact: Don Arpin	Contact: Ken Vella
jboyd@air24hour.com	arpin2@bellsouth.net	kvella@1800asphaltinc.com
Mobile Phone: (561) 699-0199	Mobile Phone: (954) 772-3699	Mobile Phone: (954) 598-3708
OTAL AMOUNT PROPOSED	TOTAL AMOUNT PROPOSED	TOTAL AMOUNT PROPOSED
\$19,100.00	\$9,177.00	\$4,250.00
Alternate Proposal Provided?	Alternate Proposal Provided?	Alternate Proposal Provided?
No	No	No
Alt.Price: N/A	Alt.Price: N/A	Alt.Price: N/A

st Designates exception for 1 or more line items. Please see vendor notes for details.





# **Association Services of Florida**

10112 USA Today Way Miramar, Florida 33025 **P**: (954)922-3514

**LINE ITEM #1:** Replacement of multiple sidewalk sections: Existing sections to be cut out leaving clean, relieved finish on retained sections. New concrete to match existing concrete color and finish within customary standards. Reinforcement and drainage per conditions and code. Jointing and crack relief to match existing. Sections and extent of replacement will be identified at site visit. During Construction all work areas to be clearly marked or roped or harricaded for recident safety.

barricaded for resident safety.
Attachment for Line Item 1:None
VENDOR 1 NOTES:
NOTES :includes permit costs
ATTACHMENT(S): Coconut_Creek_Sidewalk.jpg
LINE ITEM PRICE: \$ 19,100.00
VENDOR 2 NOTES:
LINE ITEM PRICE: \$ 9,177.00
VENDOR 3 NOTES:
LINE ITEM PRICE: \$ 4,250.00
LINE ITEM #2: All formwork to be removed, and filled where soil removed. Any damaged plantings to be restored or replaced to pre-work condition.
Attachment for Line Item 2:None
VENDOR 1 NOTES:
VENDOR 2 NOTES:
VENDOR 3 NOTES:

# All other items, charges & fees not itemized above

VENDOR 1:	\$ 0.00
VENDOR 2:	\$ 0.00
VENDOR 3:	\$ 0.00

# **SPECIAL REQUIREMENTS -- Vendors meet the following requirements:**

**Licensed** Professional

# Insured

Worker's Comp General Liability

Minimum Liability Insurance Amount Required:\$

Property Association MUST Be Listed As An "Additional Insured"
Management Company MUST Be Listed As An "Additional Insured"

# **VENDOR 1:**

OLN License: CCF10142011\_00000.pdf

PLN License: CCF10142011\_00001.pdf,IBM\_GC\_License.pdf
GLI Insurance: Eskimo-COI\_(no\_name).pdf
WCI Insurance: Eskimo\'s\_WC\_COI-\_no\_name.pdf

W9: Eskimo\'s\_W-9\_2011.pdf

# **VENDOR 2:**

OLN License: Occupational\_Licenses-.pdf,Occupational\_Licenses-.pdf

PLN License: ArpinGC.pdf,PE\_LicenseArpin.pdf

GLI Insurance: GL-Arpin.pdf WCI Insurance: WC-Arpin.pdf

W9: W9-Arpin.pdf

# **VENDOR 3:**

OLN License: 20111101165807530-1.pdf PLN License: 20111101165807530-1.pdf

GLI Insurance: Liability-Umbrella.pdf, Liability-Umbrella.pdf

WCI Insurance: WorkComp.pdf

W9: W-9-1.pdf