





Fredrick Fletcher 5711 Kimberton way Lake Worth, Florida 33463 **P**: (561) 596-4283

PROPOSAL REPORT FOR:

Calumet Lane 10121 Calumet Lane Lake Wort, FL 33467

Summary Details For RFP No.740468:

Reference Name: Calumet Roof Leaks-Damage: REPAIR -Proposals & Job ASAP

Industry Solicited: Roofing

RFP Close Date & Time: 04-21-2012 11:00 Location where work is to be performed: Other

Projected Contract Term: Single Service

Proposal Overview Details:

Proposals Submitted: **3** Alt.Proposals Submitted: 0 High Bid: **\$4,900.00** Low Bid: **\$3,230.00** Average Bid: **\$4,011.67**

VENDOR 1	VENDOR 2	VENDOR 3
RES.		PSI ROOFING
Blues Brothers Construction Corporation	Latite Roofing & Sheetmetal LLC	PSI Roofing
Vendor Apple Rating:	Vendor Apple Rating:	Vendor Apple Rating:
4260 NW 1st Avenue #53, Boca Raton, Florida 33431	2280 W. Copans road, Pompano Beach, Florida 33069	792 NE 45 th St, Oakland Park, Florida 33334
In-House Vendor? No	In-House Vendor? No	In-House Vendor? No
Company Phone: (866) 527-7663	Company Phone: (954) 335-5015	Company Phone: (954) 791-7663
Extension: 0	Extension: 0	Extension: 226
Alt.Phone: (561) 361-6378	Alt.Phone: (954) 772-3446	Alt.Phone: (954) 791-7663
Alt.Extension: 0	Alt.Extension: 0	Alt.Extension: 226
Year Business Established: 2005	Year Business Established: 1943	Year Business Established: 1994
Contact: Soniya Patel	Contact: Al Zobec	Contact: Shannan Morales
info@bluesbrotherscc.com	alz@latite.com	smorales@psi-roofing.com
Mobile Phone: () -	Mobile Phone: (772) 260-0647	Mobile Phone: (954) 325-9670
TOTAL AMOUNT PROPOSED	TOTAL AMOUNT PROPOSED	TOTAL AMOUNT PROPOSED
\$4,900.00	\$3,230.00	\$3,905.00
Alternate Proposal Provided?	Alternate Proposal Provided?	Alternate Proposal Provided?
No	No	No
Alt.Price: N/A	Alt.Price: N/A	Alt.Price: N/A

RFP TASKS REQUESTED

LINE ITEM #1: Calumet Roof Leaks-Damage: REPAIR -Proposals & Job ASAP. Property Photos at: http://bit.ly/lgvjgk
THIS IS A BANK-OWNED PROPERTY THAT REQUIRES YOUR PROPOSAL NO LATER THAN FRIDAY MORNING AT 10 AM.

1) Suspected leaks above Master Bedroom and Laundry Room. Quote minimum appropriate repair.

2) If there are non-leak related issues or recommendations, please use the "ALTERNATE PROPOSAL" option after you submit the basic repair Proposal:

HOW TO SUBMIT AN ALTERNATE PROPOSAL: Once you submit your first (primary proposal) CAMassistant will automatically ask you if you would like to create an "Alternate Proposal".

Attachment for Line Item 1: Layout-Calumet.pdf

VENDOR 1:

NOTES: NONE EXCEPTION(S): NONE

ATTACHMENT(S): Calumet.pdf

VENDOR 2:

NOTES : NONE

EXCEPTION(S): NONE

ATTACHMENT(S): SKMBT__101221_Calumey_Lane.pdf

VENDOR 3:

NOTES:Inspection Report: PSI Roofing inspected the roof and interior of the building to locate reported leaks in the Master bedroom and Laundry Room. Found one leak at the base valley and return around 2 goosenecks and one 3" lead stack with rotten wood replacement. The second leak is from the return base valley and flashing with rotten wood replacement. Scope of Work: 1. Remove the existing tiles at both leak areas, one at the base valley and return the other at return base valley and flashing total of approximately 200sq ft to a smooth workable surface. 2. Remove the existing rotted plywood sheathing and wood structural member, to a smooth workable surface. 3. Install new plywood sheathing and wood structural member fastened with galvanized eight penny nails at repair area. 4. Install new thirty pound organic underlayment fastened with tin caps and 1 ½" ring shank roofing nails. 5. Install new 90lb mineral surfaced underlayment fastened with tin caps and 1 ½" ring shank roofing nails. 6. Seal the perimeter of the newly installed 90lb membrane using a three course application of premium mastic and membrane. 7. Re-install existing cement tiles and new tiles as needed fully adhered with new tile bond and mortar.

EXCEPTION(S): NONE

ATTACHMENT(S): #12626, Calumet 4-19-12.pdf

ATTACHMENT(S): HPIM5978.JPG

ATTACHMENT(S): HPIM5973.JPG

ATTACHMENT(S): HPIM5981.JPG

ATTACHMENT(S): HPIM5965.JPG

ATTACHMENT(S): HPIM5961.JPG

ATTACHMENT(S): HPIM5966.JPG

ATTACHMENT(S): HPIM5958.JPG

All other items, charges & fees not itemized above

VENDOR 1:	\$ 4,900.00
VENDOR 2:	\$ 3,230.00
VENDOR 3:	\$ 3,905.00

SPECIAL REQUIREMENTS -- Vendors meet the following requirements:

VENDOR 1:

Occupational License: Boca_Raton_Occupational_License.pdf

Professional License: Roofing_License.pdf

General Liability Insurance: CCE04182012_00000.pdf Workers Comp Insurance: 14_G_L__Work_comp.pdf

W-9: w9.pdf

WARRANTY-INFO: nofiles Warranty: 1 year warranty

NOTES:NONE

EXCEPTION(S):None

VENDOR 2:

Occupational License: City_-_Pompano_Beach_-_2012_-_Scott.pdf

Professional License: State_of_Florida_-_2012.pdf

General Liability Insurance: Cert.pdf Workers Comp Insurance: Cert.pdf

W-9: W-9_1-4-12.pdf WARRANTY-INFO: nofiles Warranty: ! year NOTES:NONE

EXCEPTION(S):None

VENDOR 3:

Occupational License: GC-Broward.pdf,Roofing-Broward.pdf Professional License: Roofing_Contractor_FL.pdf,GC-FL.pdf General Liability Insurance: Liability.pdf,Liability-Umbrella.pdf Workers Comp Insurance: Certificate_of_Insurance_-_74983.pdf

W-9: W-9.pdf

WARRANTY-INFO: nofiles Warranty: One Year Warranty

NOTES:NONE

EXCEPTION(S):None