

October 28, 2009

Four Mid-Town Miami 3301 NE 1ST Ave Miami Beach, FL 33137

Attention: Alina Cruz, Association Manager 305-335-7345

Dear Alina:

Enclosed please find the FY 2010 updated reserve study for the above property. You should find the information to be self-explanatory; however, if there are any questions let me know.

• We recommend an annual contribution to the Reserves of \$318,200, \$65/Unit average/mo, beginning in FY10 with annual increases of 3% per year. (See 20 Year Cash Flow Chart)

We take this approach which allows the association to gradually increase the annual contribution and still be financially prepared for projected future work. The analysis indicates the sensitivity of the Reserve Year End Balance to the inflation rate and the Yearly Reserve Contribution. Our recommendation reflects the posture of collecting well before the future need at an affordable rate to be prepared for the larger expenses as the property ages.

We thank the Board for the opportunity to serve the association in this project. Please continue to call upon us for your reserve study needs.

Sincerely,

Paul Orr

Paul H. Orr, PE – FL #64898

Enclosures: Reserve Study

10112 USA Today Way, Miramar, Florida 33025 Telephone 954.922.3514 Toll Free 800.714.3514 Fax 954.922-3607
5300 Powerline Road, Suite 200A Fort Lauderdale, Florida 33309 Telephone 954.745.1170 Fax 954.745.1175 Web
www.dci-jnc.com

ASSOCIAe | The nation's leader in community management | www.associaonline.com | 800.808.4882

FY2O1O REPAIR AND REPLACEMENT RESERVE STUDY UPDATE

October 28, 2009

For:

Property Name:

FOUR MIDTOWN MIAMI

Property Location:

3301 NE 1st Ave

Miami Beach, FL 33137

Property Type:

Condominium Association

308 Res

Total Units: OCCUPIED

408

10 Comm

Association manager:

2008

408 Total

Alina Cruz 305-335-7345

Paul H. Orr, PE - FL #64898

Table of Contents

Section

Executive Summary

Introduction `

Definition of Terms

Component Description

Appendix

General Reserves

Analysis Results

Repair and Replacement Reserves Calculations

Projected Annual Expenses

20 Year Cash Flow Chart

Executive Summary

This is a Level II Update, With Site Visit/On-Site Review as defined by CAI's National Reserve Study Standards. The on-site visit of the property was performed on October 13, 2009.

The association's FY begins January 1st. The Association is projected to have \$-0-Reserve Amount On Hand at the start of the fiscal year. The tables were calculated using this amount. In this study we provide a scenario of reserve tables.

Our analysis of the Reserve Study program is attached.

• We recommend an annual contribution to the Reserves of \$318,200, \$65/Unit average/mo, beginning in FY10 with annual increases of 3% per year. (See 20 Year Cash Flow Chart)

We take this approach which allows the association to gradually increase the annual contribution and still be financially prepared for projected future work. The analysis indicates the sensitivity of the Reserve Year End Balance to the inflation rate and the Yearly Reserve Contribution. Our recommendation reflects the posture of collecting well before the future need at an affordable rate to be prepared for the larger expenses as the property ages.

There are two methods of determining the required Reserve Contribution: The Cash Flow Method and the Component Method.

The Component Method develops the Reserve Funding Plan based on the sum of contributions for individual components. This method of funding usually results in relatively high annual contributions and fund balances.

This study was calculated using the Cash Flow method - This method develops a reserve funding plan where annual contributions to the reserves are designed to offset the variable annual expenditures from the reserves. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

The funding goal used in this study is: Threshold Funding — this method is designed to keep the reserve balance above a specific dollar amount or percent funded amount. In this reserve study the threshold is set to keep the reserve balance above \$150,000 which this does for the next 20 years..

All costs in this study are expressed in constant dollars.

Introduction

The purpose of this study is to design a Table of Repair/Replacement Reserves for the common and limited common elements of the property to establish an annual reserve contribution to fund predictable future expenditures for the repair and replacement of these property components.

Typically associations fund capital repairs and replacements in one of three ways:

- 1) Special assessments collected from the owners when major work is needed.
- 2) Acquiring a loan using borrowed capital for major repair and replacement projects.
- 3) A level monthly reserve contribution to fund expected future repair and replacement projects.

Our goal is to establish a reasonable reserve contribution that would avoid the need for special assessments and acquiring loans. This will also ensure that every owner pays their fair share for the time that they own their property. Loans and special assessments only penalize the owners that are present at the time the work is needed.

Example:

If a component has a replacement cost of \$1,000 and an average useful life of 10 years, by straight calculations a contribution of \$100 per year should be made to the reserves.

If the contribution level is suppressed and only \$50 per year is contributed to the reserves, the result would be a \$500 short fall. Additionally if one owner owns his or her property for the first 8 years and then sells their unit, that owner should have paid their share of \$800, but at the suppressed contribution level they only paid their share of \$400. In the 10th year when the component is due for replacement the new owner has to pay their share of the \$200 for the two years that they owned as well as the share of the previous owners \$400 short fall.

It is important to note that a reserve study is a valuable budget management tool not a work plan. The remaining useful life of each component is based on averages and is the point at which the association should be financially prepared to replace repair that component. This does not suggest that if the component has reached its average useful life that the component should be repaired/replaced if is not failing.

In developing the table we consider items that have a predictable life cycle as well as those that will most likely need annual repairs to extend the useful life of the component. Although we use generally accepted techniques and the best information available, it is possible actual costs and useful life can vary from our estimates.

Current cost estimates are based on similar work recently performed on other local properties, estimating publications and software, information provided by local contractors and other reliable sources.

This study does not consider correcting hazardous or defective conditions associated with asbestos, radon, lead, mold, etc. unless otherwise noted in this report

Different Levels of Work

There are three levels of work necessary to properly care for equipment and property components.

- 1) Maintenance typically this is the least expensive and most important task that is performed on property components. Good maintenance extends the useful life of property components and keeps them in good working order.
- 2) Repair replacing a portion of an item to keep the component as a whole in good working order. Repair is usually more expensive than maintenance but less expensive than total replacement. If repairs are excessively expensive a cost analysis should be performed to determine if replacement of the item is more economical.
- 3) Replacement involves the entire replacement of the item.

DEFINITION OF ABBREVIATIONS

AN — An annual allowance for components without a predictable useful life. AOH — Reserve fund Amount-On-hand at the start of the fiscal year.

EA - Each HP - Horsepower

CY - Cubic Yards SF - Square Feet

LF - Linear Feet SY - Square Yards

LS - Lump Sum TN - Tons

Definition of Terms

These definitions pertain to the categories shown in the Repair & Replacement Reserves Tables and Chart.

Property Component - The components on the property we believe the community should include in the reserves. If we have omitted or added any items that are not common or limited common area responsibility, please inform us so we can provide a revised table

Quantity — The approximate quantity and unit of measure of each component.

Average Useful Life — The average of how long a component should be expected to last before replacement is needed. Leading publications on useful life data, information from local contractors, our own experiences and historical trends are used to determine the average useful life.

Remaining Useful Life — The time remaining before we believe the associations should be financially prepared to replace a component. This is determined by the age and existing condition of the component. Providing good maintenance to a component can extend the remaining useful life beyond the average useful life of the component.

Replacement Cost — The amount we believe the association should set aside in today's dollars for the replacement of each component. These are budget numbers and could vary from actual bids to do the work. This assumes the association will competitively seek bids and obtain a fair price in today's market

Recommended Contribution - The contribution needed to achieve the funding goal of this study.

Projected Annual Expenses — A table of expected expenditure for each component and the annual expenses from the reserves over the life of the study.

20 Year Cash Flow Chart — A chart showing the anticipated annual reserve balance based on the projected annual expenses and the recommended reserve contributions over the life of the study.

Component Description

In general, each item has been reviewed for current cost and remaining useful life. In future Studies, where appropriate, changes should be made to reflect current conditions.

One of the larger cost, Painting, has been approached by separating the painting into three years, each building painted in a different year in order to keep the required cash more stable.

Also in our approach, we show an "Annual Reserve – Allowance" expenditure for the minor items during the time frame when we feel the association should be financially prepared to repair these components. This Annual Reserve Allowance expenditure is also used for some of the items of great quantity which would be very costly if they need fully replaces – so annual reserve money is allocated to keep these components in good repair.

These are:

WATERPROOFING ALLOW.
BALCONIES & RAILINGS (30,570')
OFFICE EQUIP. & FURNISHINGS
GARAGE REPAIRS
PLUMBING/ELECT. ALLOW.
MISC. EQUIPMENT ALLOW.
PAVEMENT, SIDEWALKS, CURBS
DECK & TILE ALLOW.
FURNITURE ALLOW.
MISC. SITE ITEMS

WATERPROOFING ALLOW.

For instance - we show an "Annual" Reserve expenditure for Waterproofing Allowance during the time frame when we feel the association should be financially prepared to repair/replace each component i.e. roofing; however we recognize that in the interim, periodic isolated repairs may be needed to keep these components as a whole in good serviceable condition until total repair replacement is needed. This "Annual" line item allows the association to make such repairs on an as needed basis. We also recognize that these types of expenditures will vary from year to year; therefore this average annual allowance should also be viewed as an allowance to spend over an extended year to year period.

BALCONIES & RAILINGS (30,570')

Balconies & railings are of great quantity and should be watched yearly.

OFFICE EQUIP. & FURNISHINGS

We show an "Annual" Reserve expenditure to realistically address those expenses.

GARAGE REPAIRS

Another item of great quantity and should be watched yearly.

PLUMBING/ELECT. ALLOW. MISC. EQUIPMENT ALLOW.

Mechanical/Electrical Equipment and Misc Equipment - we show an "Annual" Reserve expenditure to realistically address those expenses of plumbing and electric items as well as a separate line item for small equipment and other controls. This average annual allowance is intended to be a 'catch all" line item to allow the association to make repairs on an as needed basis. Again we recognize that these types of expenditures will vary from year to year.

PAVEMENT, SIDEWALKS, CURBS

Pavements & Sidewalks - we show an "Annual" Reserve expenditure to realistically address those expenses.

DECK & TILE ALLOW. FURNITURE ALLOW.

Recreation Areas – we show an "Annual" expense to reserves separating deck & tile from a furniture allowance.

MISC. SITE ITEMS

Site Items – we show an "Annual" expense to reserves for the various miscellaneous items to Reserves.

<u>Appendix</u>

EXECUTIVE SUMMARY Budget Year - 01/01/2010 - 2011

10/21/2009 P.Orr, PE

PROPERTY DATA

Property Name: Property Location:

FOUR MIDTOWN MIAMI 3301 NE 1st Avenue Miami Beach, FL 33 137 Condominium Association 408 2008

Property Type:
Total Units:
OCCUPIED
Association manager:
Alina Cruz
305-335-7345

PROJECTED COMPONENT CATEGORIES AND PARAMETERS - CASH FLOW METHOD

Ď.	70 40 40 40 60 60 60 60 60 60 60 60 60 60 60 60 60	00 00	Analysis 1 Analysis 2 Expanded Line letres Expanded Line letres Commonent Method Commonent Method 318240 \$ 403,012	NA 760 \$ 988	8 9 10 11 2016 2017 2018 2019 2020	\$379,947 \$391,346 \$403,066 \$415,179 \$427,534 \$1270,001 \$452,002 \$1,001 \$
2010 Funding	169,040 67,170 12,940 51,340 1,970 8,410 7,280	5,201,300 - 10 27,000	Analys Expanded Li Cash Flow		7	\$32,239 \$379,947 \$1,287,100 \$931 \$78
21	๛๛๛๛๛๛¤ ^t	<i>ம</i>	49 49	Z &	6 2015	\$471,987 \$368,881 \$939,400 \$904
					5 2014	\$512,883 \$358,137 1,042,500 \$878 \$73
					4 2013	\$28.644 \$50,539 \$512,883 \$337,578 \$347,706 \$358.137 \$500,000 \$1,197,200 \$1,042,500 \$627 \$852 \$878
					3 2012	\$28,644 \$337,578 \$900,000 \$827 \$69
		TE.		12	2 2011	\$27,810 \$327,746 \$591,100 \$803 \$67
alysis		onents in reserve analysis: for reserve analysis: r replacement in the 2010 budget ye placement in the 2010 budget year.	ons amount (2009 Budget): ng contribution amount:	commended contribution amounts	2019	\$27,000 \$316,200 \$291,200 \$78 \$78 \$78
Component Categories in Reserve Analysis	BUILDING EXTERIOR BUILDING INTERIOR GARAGES MECHANCAL EQUIPMENT PAVEMENTS & SIDEWALKS RECREATION AREAS SITE ITEMS GENERAL RESERVE RESERVES TOTALS	Total replacement cost of all reserve components in reserve analysis: Estimated beginning reserve find balance for reserve analysis; Total number of components scheduled for replacement in the 2010 budget year: Total cost of components scheduled for replacement in the 2010 budget year.	ANALYSIS RESULTS. Annual Current reserve funding contributions amount (2009 Budget): Annual Recommended 2010 reserve funding contribution amount:	Annual Increase between current and recommended contribution amounts: % Increase Avg S per UnitYR	Future yr # ==> FISCAL YEAR	ANNUAL EXPENSE \$27,000 CONTRIBUTION - POOLED METHOD \$316,200 YEAR END BALANCE UNIT CONTRIBUTION (\$4 MONTH (\$4\)G) UNIT CONTRIBUTION (\$4 MONTH (\$4\)G)

We have identified the Reserve Line items from lists and conversation supplied by the Property Manager's office.

We incommend using the Pooled Muhatod for the Reserve Account.
Design criteria for this Reserve Study lis:
S150,000
Maintain Reserves for 20 years above
1, 03
1010 Reserve Contitution is:

\$318,240 \$293,760 1.05 \$318,240 Contrib 1,03 2,026 2026 \$309,300 \$150,000 1.03 5318,200 Reserve Value \$609,500 A change in inflation rate from 3% to 5% produce A change in average contribution from \$65 to \$60 at 3% inflation produces A change in average confluitution from \$45 to \$60 at 5% inflation produces \$60 at 5% inflation produces At i-3% & Mo Avg Contib = \$65 the Lowest Reserves in 20 yr window

\$60 \$65

\$293,760

1.05

2,026

-\$21,200

٠.
ÿ
ō
Ē
۹
닉
ಠ
ľ
⋖
LACEMENT RESERVE CALCULATIONS
æ
Щ
ព
æ
⊢
z
띹
ជ
$\overline{\mathbf{o}}$
۲
굽
Щ
œ
흳
z
∼
불
ፈ
竝
REPAIR AND REPLACEMENT R
REPAII
=
a
⋛
=
ś
⋛
۲
٥
ź
FOUR
5
O
щ

COMPONENT METHOD CONTRIBUTION	15 204 11.250 1.509 38.789 36.351 21.103 85.738 85.738 85.738 1.500	41.667 9.450 12.240 2.222 15.867 1.126 2.500	13.680 2.14 2.500 2.708 3.421 3.421 1.042 4.286 4.286 4.286 7.786	2,5000 2,5000 2,5000 2,5000
CONTRIBUTION			\$249,160	\$51,340
RECOMMENDED POOLED CONTRIBUTION METHOD	12,010 8,880 1,190 30,630 120 27,910 16,660 67,700 2,760 1,180	32,900 7,460 9,670 1,750 12,530 890 1,970	10,800 170 1,970 2,140 2,700 2,700 31,590 820 3,380 80 1,800	3,950
replacement - dist	212.850 157,500 43,750 543,050 3,000 600,960 612,000 428,690 3,500 1,500	250,000 56,700 73,440 20,000 142,800 32,640 2,500	533,520 3,000 2,500 65,000 65,000 960,000 25,000 60,000 1,500 10,500	5,000
distribution of the on hand \$	000000000	000000	000 0000000	00 0
REPLACEMENT COST	212,850 157,500 43,750 543,050 3,000 600,960 612,000 428,690 3,500 1,500	250,000 56,700 73,440 20,000 142,800 32,640 2,500	533,520 3,000 2,500 65,000 65,000 960,000 25,000 60,000 11,500 11,500	5,000 2,500 2,500 2,500
9	\$2\$\$\$\$\$\$\$\$	ပ လို အဆေ က က က	8 to	00 0
QUANTITY USEFULLIFE (YRS) SIZE UNITS AVERAGE REMAIN	£ £ 8 £ 8 £ 8 £ £ £	7 7 10 30 10 1	8 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
可 UNITS	유 유 구 공 공 구 공 공 A A A A A A A A A A A A A A	UNIT SE EA SE AN	R S S S S S S S S S S S S S S S S S S S	A A A A A
OUAN SIZE	28,380 21,000 7,291 987 1 1,252 408 357,240	5 90 73,440 5 41 408	106,774 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
PROPERTY COMPONENTS	BUILDING EXTERIORS ROOFING FLAT-BUILDING ROOFING FLAT-PARKING GUTTERS & DOWNSPOUTS WINDOWS STORE FRONT STORE FRONT BALCONYPATIO DOORS PAINT BUILDING @ 50% OPENINGS WATERPROOFING ALLOW. BALCONIES & RAILINGS 1,252 WATERPROOFING ALLOW. 1 BALCONIES & RAILINGS 169,040	BUILDING IN EKICK REDECORATIONS CARRETFLOORING INTERIOR PAINTING STAIRWAY PAINTING EXERCISE EQUIPMENT MAIL BOXES OFFICE EQUIP. & FURNISHINGS	GARAGES GARAGE REPAIRS GARAGE REPAIRS GARAGE REPAIRS \$12,940 \$249,150 TOTAL BUILDINGS MECHANICAL EQUIPMENT CHILLERS COOLING TOWER ELEVATORS - TRACTION EMERGENCY GENERATOR AC PACKAGE UNIT W/ AIR HANDLEF WATER REPATENS TRASH COMPACTORS TRASH COMPACTORS	PLUMBING/ELECT. ALLOW. MISC. EQUIPMENT ALLOW. HEATERS, FIRE CONTROLS, VALVES, PUMPS, MOTORS, SECURITY, EXHAUST FANS. ETC. \$51,340 TOTAL MECHANICAL PAVEMENTS & SIDEWALKS PAVEMENT, SIDEWALKS PAVEMENT, SIDEWALKS \$1,970

	4, 813 972 843 107 1,500 2,500		\$403,012 COMPONENT METHOD CONTRIBUTION
\$1,970	8,410	\$7,280	\$318,150
	3,800 770 470 470 510 80 420 1,180 1,180 1,900	200 390 2,760	\$318/150 POOLED CONTRIBUTION METHOD
	19,250 8,750 5,400 9,000 1,500 1,500 1,500 72,000 35,000	7,500 500 3,500	\$5,201,300 replacement - districted
	0000000 00	000	\$0 distribution of the or hand \$
	19,250 8,750 5,400 9,000 1,500 1,500 1,500 72,000 35,000	7.500 500 3.500	\$5,201,300
	ဃၹက <u>လုံးလုံး</u> လူဝဝ ဆွ <u>ာ</u> တ	0 0 0	
	s 0 0 2 2 8 7 7 8 5	30 +	
	SS	A A A A	
	3.500 3.500 900 1 - 1 - 4 - 1 - 4 - 4 - 4 - 4 - 4 - 4 -		
TOTAL PAVEMENTS & SIDEWALKS	RECREATION AREAS SWIMMING POOL WHITE COAT POOL COVER - ADULT POOL COVER - BABY FILTERS/PUMPS WATER HEATERS METAL FENCING DECK & TILE ALLOW. FURNITURE ALLOW. SITE ITEMS POLE LIGHTS SWM PONDS	FENCING MUCCHMISC. REPAIRS ALLOW. MISC. SITE ITEMS ENTRANCE FEATURES, SIGNS, DRAINAGE, FOUNTAIN, MINOR LANDSCAPING, IRRIGATION, RAILINGS, RETAINING WALLS, WALKWAYS, PAVERS, TRASH RECEPTICLES, ETC. \$7,280 TOTAL SITE ITEMS	RESERVES TOTALS

FOUR MIDTOWN MIAMI --- REPAIR AND REPLACEMENT RESERVE CALCULATIONS

\$705,155 \$39,734 20 21

\$1,610,467 (\$13,277 \$54,276 (\$1,67,680 \$36,363 (\$587,894) 14 18 19 19

\$30,463 \$573,365 12

\$15,229 \$812,409 10 11

\$33,207 \$282,743 6 9

\$50,639 \$512,883 \$471,887 \$52,239

\$27,810 \$28,644 2 3

\$27,000

Totals

BONG THE REPORT OF THE PROPERTY OF THE PROPERT	FRIORS T-SULLING T-SURVING	BUILDING INTERIOR REDECOANTONS CAPETIFLOORING INTERIOR SANTING STAIRWAY PAINTING EXERCISE EQUIPMENT MALL ROXES EQUIPMENT OFFICE EQUIP. 8 FURNISHINGS 2	GARAGE REPAIRS GARAGE DOORS GARAGE REPAIRS	MECHANICAL EQUIPMENT COOLING TOWER COOLING TOWER COOLING TOWER ELWAYTORS, TRACTON ELWAYTORS, TRACTON ELWAYTORS, TRACTON WATER HAPPLES RISER FEDULACEMENT SECURITY, EVIALUS SECURITY SECURITY EVIALUS SECURITY SECURITY EVIALUS SECU	PAVEMENT'S & SIDEWALKS PAVEMENT, SIDEWALKS, CURBS	WHITE COAT WHITE COAT POOL COVER. ADULT POOL COVER. ADULT POOL COVER. BABY MATER HEATERS WATER HEATERS GER, \$ THE ALLOW 10 DEX, \$ THE ALLOW 11 OF THE ALLOW 12 OF THE ALLOW 13 OF THE ALLOW 14 OF THE ALLOW 15 OF THE ALLOW 16 OF THE ALLOW 17 OF THE ALLOW 18 OF THE ALLOW 18 OF THE ALLOW 19 OF THE ALLOW 10 OF THE ALLOW 11 OF THE ALLOW 11 OF THE ALLOW 12 OF THE ALLOW 13 OF THE ALLOW 14 OF THE ALLOW 15 OF THE ALLOW 16 OF THE ALLOW 16 OF THE ALLOW 17 OF THE ALLOW 17 OF THE ALLOW 18 OF THE ALLOW 18 OF THE ALLOW 19 OF THE ALLOW 19 OF THE ALLOW 10 OF THE ALLOW 11 OF THE ALLOW 14 OF THE ALLOW 15 OF THE ALLOW 16 OF THE ALLOW 17 OF THE ALLOW 16	STEF TERMS POLE LIGHTS SWAM PONDS FENCING MAILCHMERS ETEMS ALLOW. 3 REMCINGE FEATURES. 3 SIGNS DRAINAGE, FOUNTAIN, MINOR LINGSCHPING, RRIGATION, PALLINGS, RRIANING WALLS, WALKWAYS, PAYERS, TRASH RECEPTICLES, ETC.
4	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 2,500 2,575	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2,500 2,575	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,500 3,605
1	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		0 0 0 75 2,652	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	75 2,652	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 2,732	0 0 0 0 2.732	2	2 2,732	2),035 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,828
FOUR M	482.494 3,939 1,588	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 2,814		2,814	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 888 8 889 9 888
	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	289,819 65,731 85,137 0 0 2,838	0 0 2,898	5,786 5,786 2,688	2,698	0 0 0 0 1,739 1,739	0 0 0 880 4,057
DTOWN MIAMI — REPAIR AND REPLACEMENT	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	, 2985 2, 3885 2, 3885 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3	2,985	2 2 3 3 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	2,985	0 0 0 0 1,797,1	0 0 0 597 4,179
REPAIR AN	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,075	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,075	0 0 0 0 1,845 1,845	0 0 615 4,336
ND REPLAC	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 25,335 180,895 0 3,167	3,167	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,167	24,385 11,024 6,841 0 0 0 1,900	0 0 0 633 4,434
EMENT RE	9 0 0 0 0 0 4,567	0 0 0 0 3,262	3,262	6,524 5,782 5,782	3,262	0 0 0 0 0 7.395,1	0 0 0 552 4,567
RESERVE CALCULATIONS	0 0 0 0 0 576,124 4,704 2,016	3,380 co	3,350	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,360	0 0 0 2,016 0 2,016	0 0 0 672 4,704
LCULATION R	000000000	3,440 00 00 00 00 00 00 00 00 00 00 00 00	3,461	9.6.92 2.92 2.00 2.00 2.00 2.00 3.00 3.00 3.00 3.0	3,461	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 682 4,645
2. 2.	00000000	356,440 B0,841 104,708 0 0 3,564	0 0 3,564	93954 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3.564	0 0 0 0 0 0 0 2,139 2,139	0 0 0 1713 4,990
В	312,577 231,294 0 797,487 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 4,406 3,671	88,112 2,200 2,200 46,993 46,993 3,671	3,671	28,269 0 0 13,217 2,203 0 2,203 2,203	51,399 7,734 5,140
1000 cm	00000000	3,784 000 000 1,784	3,781	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,781	0 0 0 0 2,269 2,269	0 0 756 5,234
10	000000000	3888 888 888	3,695	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3,895	0 0 0 0 2,337 2,337	5,463
26	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 4,012	8,024 1,012	4,012	0 0 0 0 0 2,407	0 0 802 8,546
100 m	000000000	000000000000000000000000000000000000000	0 0 4,132	0 11 0 0 11 0 0 0 0 0 0 0 0 0 0 1322 4	4,132	2,2479	0 0 0 826 5,785
282	5,100 000 000 000 000	0 6 0 0 34,049 243,107 0 0 4,256	0 0 0,256	110,056 110,056 10,056 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	4.256	32,772 14,896 9,193 0 0 0 2,554 2,554	0 0 0 0 851 5,859
*	000000000	438,377 99,424 128,777 0 0 4,384	4.384	00000000000000000000000000000000000000	4,384 4,516.	0 0 0 0 2,630 2,630	0 0 0 0,0 0,0 0,0 0,0 0,0 0,0 0,0 0,0 0
	000000000	2. 000000000000000000000000000000000000	0 0 4,515		4,516	27.73 000 000 000 000 000 000 000 000 000 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0


FOUR MIDTOWN MIAMI -- 20 YEAR CASH FLOW CHART

INFLATION BEGINNING BALANCE PERCENT FUNDED

3 %



3.0%



20	2029	705,155	996,736	1,126,400	\$1,368
6	2028	597,894	541,714	1,273,600	\$1,328 \$111
81	2027	36,363	525,936	1,329,800	\$1,289 \$107
4	2026	1,687,590	510,618	940,200	\$1,252 \$104
16	2025	34,275	495,745	2,017,200	\$1,215 \$101
45	2024	33,277	481,306	1,555,700	\$1,180 \$98
4,	2023	1,610,467	467 287	1,107,700	\$1,145
5	2022	573,355	453,677	2,256,900	\$1,112 \$93
5	2021	30,453	440,463	2,370,600	\$1,080
Ξ.	2020	612,409	427,634	1,960,600	\$1,048 \$87
5	2019	35,229	415,179	2,145,400	\$1,018 \$85
6	2018	282,743	403.086	1,765,500	\$988
æ	2017	33,207	391,346	1,645,200	\$959 \$80
۲	2016	32,239	379,947	1,287,100	\$931
ø	2015	471,987	368,881	939,400	\$904
۷ɔ	2014	512,883	358,137	1,042,500	\$878
4	2013	50,539	347,706	1,197,200	\$852
60	2012	28,544	337,578	000'006	\$827
1/3	2011	27,810	327,746	591,100	\$803
-	2016	27,000	318 200	291,200	\$780
	FISCAL YEAR	ANNUAL EXPENSE	CONTRIBUTION	YEAR END BALANCE	PER YR PER MO (AVG)



