





## **Association Services for CA changed**

XYZ Voltaire St San diego, California 92105 **P**: (654) 987-6549

### PROPOSAL REPORT FOR:

Ocean Beach Residency 234 San Diego City, CA 92115

#### Summary Details For RFP No.183994:

Reference Name: Ocean Beach Residency Phase One

Industry Solicited: Landscape Architect RFP Close Date & Time: 07-29-2012 16:00

Location where work is to be performed: All Lawn and Planting Areas Include private residences/lots,Common areas,Gate/Guard House

Projected Contract Term: Annual

#### **Proposal Overview Details:**

Proposals Submitted: 1 Alt.Proposals Submitted: 0 High Bid: **\$2,300.00** Low Bid: **\$2,300.00** Average Bid: **\$2,300.00** 



#### **RFP TASKS REQUESTED**

## **LINE ITEM #1:** Ocean Beach Residency Phase One.

See attached Aerial View for current configuration (2X Half Courts) - To be replaced with single FULL COURT.

- 1) Remove exisiting hoops and posts. Fill/patch removed posts...
- 2) Install two new gooseneck Basketball hoops at ends of court creating a full court. The Board had previously selected a style hoop from a website model # PR52 at www.basketballhoopsunlimited.com. http://www.basketballhoopsunlimited.com/store/Scripts/prodView.asp?idproduct=77 Additional example photos attached in "Additional Documents". Substitutions must be same style and equal or better quality/materials.
- 3) The current surface appears to be in fairly good condition, I believe it is asphalt with a green painted surface but I did observe two large cracks. These should be filled/sealed for safety and appearance.
- 4) Remove existing painted keys (remove/coat over for smooth surface, best recommendation(s) for economy & durability of new coating/paint) and repaint keys for full court.

#### **Attachment for Line Item 1:None**

**VENDOR 1:** 

**LINE ITEM PRICE: \$ 1,000.00** 

#### LINE ITEM #2: Secon.

See attached Aerial View for current configuration (2X Half Courts) - To be replaced with single FULL COURT.

- 1) Remove exisiting hoops and posts. Fill/patch removed posts...
- 2) Install two new gooseneck Basketball hoops at ends of court creating a full court. The Board had previously selected a style hoop from a website model # PR52 at www.basketballhoopsunlimited.com. http://www.basketballhoopsunlimited.com/store/Scripts/prodView.asp?idproduct=77 Additional example photos attached in "Additional Documents". Substitutions must be same style and equal or better quality/materials.
- 3) The current surface appears to be in fairly good condition, I believe it is asphalt with a green painted surface but I did observe two large cracks. These should be filled/sealed for safety and appearance.
- 4) Remove existing painted keys (remove/coat over for smooth surface, best recommendation(s) for economy & durability of new coating/paint) and repaint keys for full court.

#### **Attachment for Line Item 2:None**

**VENDOR 1:** 

LINE ITEM PRICE: \$ 100.00

# All other items, charges & fees not itemized above

**VENDOR 1:** 

\$ 1,000.00

### **SPECIAL REQUIREMENTS -- Vendors meet the following requirements:**

# VENDOR 1:

### **GENERAL NOTES:**

NONE

**GENERAL EXCEPTION(S):** 

None

### Licensed

Professional

# VENDOR 1:

Professional License: OLN\_Allied\_Local\_Business\_Tax\_Receipt.jpg,Barbie\_Doll.jpg

General Liability Insurance: capture4.PNG

Workers Comp Insurance:

W-9: Scan2.jpg

WARRANTY-INFO: Barbie\_Doll.jpg

Warranty: test