

# MAACO UNION - M2409

RO Number: 22182

|              |                       |             |                          |                 |               |
|--------------|-----------------------|-------------|--------------------------|-----------------|---------------|
| Owner:       | <b>EDSON, TERRY</b>   | Year:       | <b>2020</b>              | Exterior Color: | <b>SILVER</b> |
| Vehicle In:  | <b>1/19/2026</b>      | Make:       | <b>LINC</b>              | Paint Code:     |               |
| Vehicle Out: |                       | Model:      | <b>MKZ Reserve AWD</b>   | License:        |               |
| Estimator:   | <b>Taimur R.</b>      | Body Style: | <b>4D SED</b>            | Mileage In:     | <b>38055</b>  |
| Insurance:   | <b>SILVERROCK INC</b> | VIN:        | <b>3LN6L5F90LR612560</b> | Job Number:     |               |

## Work Order - Maaco Bodyman

| Line                | Inc | Operation        | Qty | Part Number    | Description                      | Labor Type | Part Type | Assigned Hours | Tech Initials |
|---------------------|-----|------------------|-----|----------------|----------------------------------|------------|-----------|----------------|---------------|
| 2                   |     |                  |     |                | PILLARS, ROCKER & FLOOR          |            |           |                |               |
| 3                   |     | Repair           | 0   | DP5Z54211A11A  | LT Aperture panel                | Body       |           | 8.0            |               |
| 5                   |     |                  |     |                | FRONT DOOR                       |            |           |                |               |
| 6                   |     | Repair           | 0   | DP5Z5420125A   | LT Door shell                    | Body       |           | 5.5            |               |
| 8                   |     | Remove / Install | 0   | DP5Z5421453A   | LT Belt molding                  | Body       |           | 0.3            |               |
| 9                   |     | Remove / Replace | 1   | EP5Z14A626BA   | LT Applique                      | Body       | OEM       | 0.4            |               |
| 10                  |     | Remove / Replace | 1   | GP5Z5420531A   | LT Door w'strip                  | Body       | OEM       | 0.7            |               |
| 11                  |     | Remove / Replace | 1   | HP5Z5421597A   | LT Run channel                   | Body       | OEM       | 0.4            |               |
| 12                  |     | Remove / Install | 0   | DP5Z5421411B   | LT Door glass LINCOLN            | Body       |           | 0.6            |               |
| 13                  |     | Remove / Install | 0   | HP5Z17683AB    | LT R&I mirror                    | Body       |           | 0.3            |               |
| 14                  |     | Remove / Install | 0   | HP5Z5423943AB  | LT R&I trim panel                | Body       |           | 0.6            |               |
| 15                  |     | Remove / Install | 0   | DP5Z5421452A   | RT Belt molding                  | Body       |           | 0.3            |               |
| 16                  |     | Remove / Install | 0   | DP5Z5420878A   | RT Side molding                  | Body       |           | 0.3            |               |
| 17                  |     |                  |     |                | REAR DOOR                        |            |           |                |               |
| 18                  |     | Remove / Replace | 1   | DP5Z54255A35AB | LT Applique front                | Body       | OEM       | 0.2            |               |
| 19                  |     | Remove / Install | 0   | DP5Z5425861A   | LT Belt molding                  | Body       |           | 0.3            |               |
| 20                  |     | Remove / Replace | 1   | HP5Z5425767A   | LT Run channel                   | Body       | OEM       | 0.3            |               |
| 21                  |     | Remove / Install | 0   | DP5Z5425713A   | LT Door glass LINCOLN green tint | Body       |           | 0.5            |               |
| 22                  |     | Remove / Install | 0   | HP5Z5427407AB  | LT R&I trim panel                | Body       |           | 0.6            |               |
| 23                  |     | Remove / Install | 0   | EP5Z5424631A   | LT R&I door assy                 | Body       |           | 1.1            |               |
| 24                  |     | Remove / Install | 0   | DP5Z5425860A   | RT Belt molding                  | Body       |           | 0.3            |               |
| 25                  |     | Repair           | 0   | EP5Z5424630A   | RT Door shell                    | Body       |           | 3.0            |               |
| <b>Subtotals:</b>   |     |                  |     |                |                                  | Body       |           | 23.7           |               |
| <b>Grand Total:</b> |     |                  |     |                |                                  |            |           | <b>23.7</b>    |               |