

Customer: RYAN KIM & SONG YUN
Property: 1048 UNDERHILL DR

PLACENTIA, CA 92870

Home: 1048 UNDERHILL DR

PLACENTIA, CA 92870

Claim Rep.: Justin Kirisits

Company: TRAVELERS COMMERCIAL INSURANCE COMPANY

Business: PO Box 650293 Business: (877) 872-8228

Dallas, TX 75265-0293

Claim Number: H9Z8199001H Policy Number: 0CBQ74604274417633 1 Type of Loss: WATER DAMAGE - NON-

WEATHER RELATED

Date of Loss: 12/29/2020 12:00 AM Date Completed: Price List: CAOG8X\_JAN21

Coverage	Deductible	Policy Limit
Dwelling	\$2,500.00	\$579,000.00
Other Structures	\$0.00	\$57,900.00
Contents	\$0.00	\$405,300.00

#### Dear RYAN KIM & SONG YUN:

We have prepared this estimate regarding your loss or damage. A letter that explains your coverage and benefits is being sent to you separately. Because the information in an estimate serves as the basis for a determination of your benefits, you (and if applicable, your contractor) should review this estimate carefully. Let us know immediately (and prior to beginning any work) if you have any questions regarding the estimate.

Under most insurance policies, claim settlement begins with an initial payment for the actual cash value of the covered loss or damage. To determine actual cash value, we estimate the item's replacement cost, and then, if appropriate, take a deduction for depreciation. Depreciation represents a loss in value that occurs over time. In determining the amount to deduct for depreciation, if any, to apply to an item, we consider not just the age of the item immediately prior to the loss or damage but also its condition at that time. For each line item included in this estimate, the estimate shows not only the estimated replacement cost value, but also the amount of depreciation (if any) applied to the item, the item age and item condition upon which the depreciation (if any) was based and the item's actual cash value.

Thank you for allowing us to be of service, and thank you for choosing TRAVELERS COMMERCIAL INSURANCE COMPANY for your insurance needs. If you have any questions regarding this estimate or any aspect of your claim, please contact Justin Kirisits at (877) 872-8228.

You can check the status of your claim, view your policy and much more at www.mytravelers.com.

Answers to commonly asked questions can be found at https://www.travelers.com/claims/manage-claim/property-claim-process

You can also upload documents directly to your claim at www.travelers.com/claimuploadcenter.

For more information about how the claim process works and where to find services to help you recover, visit travelers.com/claim.



#### Guide to Understanding Your Property Estimate

#### Common Units of Measure

EA - Each CY - Cubic Yard LF - Linear Foot SO - Square HR - Hour

#### SF - Square Foot DA – Day SY - Square Yard CF - Cubic Foot RM - Room

#### Your Estimate Cover Sheet .....

The cover sheet of your estimate includes important information such as:

- (A) Your Travelers claim professional's contact information
- (B) Your claim number
- (C) The types of coverage under your policy, including the applicable deductibles and policy limits.
- (D) Your estimate may include policy sublimits for specific items, such as money. Each sublimit has a unique ID tag. That ID tag will appear next to any line item subject to the sublimit.

# YOUR ESTIMATE COVER SHEET

#### Your Estimate Detail .....

This is where the details about your lost or damaged property can be found.


- (E) Description Details describing the activity or items being estimated.
- (F) Quantity The number of units (for example, square feet) for an item.
- (G) Unit The cost of a single unit.
- (H) Replacement Cost Value (RCV) The estimated cost of repairing a damaged item or replacing an item with a similar one. RCV is calculated by multiplying Quantity x Unit Cost.
- (I) Age The age of the item.
- (J) Life The item's expected life assuming normal wear and tear and proper maintenance.
- (K) Condition The item's condition relative to the expected condition of an item of that age. (New, Above Average, Average, Below Average, Replaced)
- (L) Depreciation % The percentage of the loss of value that has occurred over time based on factors such as age, life expectancy, condition, and obsolescence.
- (M) Depreciation Loss of value that has occurred over time based on factors such as age, life expectancy, condition, and obsolescence. If depreciation is recoverable, the amount is shown in ( ). If depreciation is not recoverable, the amount is shown in <>.
- (N) Actual Cash Value (ACV) The estimated value of the item or damage at the time of the loss. Generally, ACV is calculated as Replacement Cost Value (RCV) minus Depreciation.
- (O) Labor Minimums The cost of labor associated with drive time, setup time and applicable administrative tasks required to perform a minor repair.

# YOUR ESTIMATE DETAI 378.87

#### 

For each type of coverage involved in your estimate there is a summary section that shows the total estimated costs (RCV and ACV) and net claim amount for the coverage type. The example to the right depicts a Dwelling coverage summary.

- (P) Line Item Total The sum of all the line items for that particular coverage.
- (Q) Total Replacement Cost Value The total RCV of all items for that coverage.
- (R) Total Actual Cash Value The total ACV of all items for that coverage.
- (S) Deductible The amount of the loss paid by you. A deductible is generally a specified dollar amount or a percentage of your policy limit.
- (T) Net Claim The amount payable to you after depreciation and deductible have been applied. This amount can never be greater than your coverage limit.
- (U) Total Recoverable Depreciation The total amount of depreciation you can potentially recover.



We encourage you to contact us if you have additional questions regarding your claim or anything in this guide.

For information about how the claim process works and where to find services to help you recover, visit travelers.com/claim.



#### travelers.com

The Travelers Indemnity Company and its property casualty affiliates. One Tower Square, Hartford, CT 06183

This material is for informational purposes only. All statements herein are subject to the provisions, exclusions and conditions of the applicable policy. For an actual description of all coverages, terms and conditions, refer to the insurance policy. Coverages are subject to individual insureds meeting our underwriting qualifications and to state availability



#### RYAN\_KIM\_\_\_\_1

#### Main Level

Richer (A2)
| Kitcher (A3) | Bedrom clo

Living Room

405.59 SF Ceiling

Height: 8'

780.67 SF Walls 1186.26 SF Walls & Ceiling 44.44 SY Flooring

399.95 SF Floor

105.58 LF Ceil. Perimeter

96.58 LF Floor Perimeter

 Door
 2' 3" X 6' 8"

 Door
 2' 6" X 6' 8"

 Missing Wall - Goes to Floor
 3' X 8'

 Door
 2' 4" X 6' 8"

 Missing Wall
 10' 5" X 8'

 Door
 6' X 6' 8"

Opens into Exterior
Opens into BEDROOM
Opens into ENTRY\_FOYER
Opens into HALL\_CLOSET
Opens into KITCHEN


**Opens into Exterior** 

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
1. R&R Engineered woo	od flooring								
306.56 SF	11.63	148.60	742.78	4,456.67	0/50 yrs	Avg.	0%	(0.00)	4,456.67
2. Add for glued down a	pplication ove	r concrete sub	strate						
306.56 SF	2.60	23.34	164.08	984.48	0/150 yrs	Avg.	0%	(0.00)	984.48
3. Baseboard - Detach &	z reset								
65.75 LF	2.97	0.12	39.08	234.48	0/NA	Avg.	0%	(0.00)	234.48
4. Paint baseboard - two	coats								
65.75 LF	1.50	0.75	19.88	119.26	3/15 yrs	Avg.	20%	(1.71)	117.55
5. Engineered wood floo	oring								
93.39 SF	9.27	45.27	182.20	1,093.20	0/50 yrs	Avg.	0%	(0.00)	1,093.20
6. Add for glued down a	pplication ove	r concrete sub	strate						
93.39 SF	1.09	7.11	21.78	130.69	0/150 yrs	Avg.	0%	(0.00)	130.69
7. 1/2" - drywall per LF	- up to 2' tall								
25.83 LF	11.82	2.53	61.56	369.40	0/150 yrs	Avg.	0%	(0.00)	369.40
8. Texture drywall - ligh	t hand texture								
51.66 SF	0.79	0.27	8.22	49.30	0/150 yrs	Avg.	0%	(0.00)	49.30
9. Seal the surface area	w/PVA primer	- one coat							
51.66 SF	0.61	0.27	6.36	38.14	0/15 yrs	Avg.	0%	(0.00)	38.14
10. Paint Walls - two co	ats								
696.00 SF	1.00	14.01	142.00	852.01	3/15 yrs	Avg.	20%	(32.02)	819.99
11. Mask and prep for p	aint - tape only	(per LF)							
105.58 LF	0.63	0.37	13.38	80.27	0/15 yrs	Avg.	0%	(0.00)	80.27
12. Baseboard - 3 1/4"									
25.83 LF	3.31	2.71	17.64	105.85	0/150 yrs	Avg.	0%	(0.00)	105.85
13. Seal & paint basebox	ard - three coat	S							
25.83 LF	2.25	0.36	11.70	70.18	3/15 yrs	Avg.	20%	(0.83)	69.35
WATER MITIGATION									



#### **CONTINUED - Living Room**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
14. Tear out non-salv so	lid/eng. wood f	flr & bag for	disposal						
93.39 SF	3.73	0.65	0.00	348.99	NA	NA	NA	(0.00)	348.99
15. Air mover (per 24 ho	our period) - No	o monitoring							
18.00 EA	27.27	0.00	0.00	490.86	0/NA	Avg.	0%	(0.00)	490.86
16. Apply anti-microbia	l agent to the si	urface area							
145.05 SF	0.27	0.38	0.00	39.54	0/NA	Avg.	0%	(0.00)	39.54
17. Tear out baseboard									
25.83 LF	0.52	0.00	0.00	13.43	NA	NA	NA	(0.00)	13.43
18. Tear out wet drywal	l, cleanup, bag,	per LF - up	to 2' tall						
25.83 LF	3.70	0.77	0.00	96.34	NA	NA	NA	(0.00)	96.34
19. Add for tear out wd	flr glued down	over concret	e substrate						
93.39 SF	1.86	0.00	0.00	173.71	NA	NA	NA	(0.00)	173.71
20. Dehumidifier (per 24	4 hour period) -	- XLarge - N	o monitoring						
3.00 EA	102.50	0.00	0.00	307.50	0/NA	Avg.	0%	(0.00)	307.50
Totals: Living Room		247.51	1,430.66	10,054.30				34.56	10,019.74



Pantry Height: 8'

140.00 SF Walls159.00 SF Walls & Ceiling2.11 SY Flooring17.50 LF Ceil. Perimeter

19.00 SF Ceiling19.00 SF Floor17.50 LF Floor Perimeter


Door 2' 10" X 6' 8" Opens into KITCHEN

	QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWEL	LING									
21. En	gineered wood floo	oring								
	19.00 SF	9.27	9.21	37.06	222.40	0/50 yrs	Avg.	0%	(0.00)	222.40
22. Ad	d for glued down a	pplication over	concrete sub	ostrate						
	19.00 SF	1.09	1.45	4.44	26.60	0/150 yrs	Avg.	0%	(0.00)	26.60
23. 1/2	" - drywall per LF	- up to 2' tall								
	17.50 LF	11.82	1.72	41.72	250.29	0/150 yrs	Avg.	0%	(0.00)	250.29
24. Te	xture drywall - ligh	t hand texture								
	35.00 SF	0.79	0.18	5.58	33.41	0/150 yrs	Avg.	0%	(0.00)	33.41
25. Sea	al the surface area v	w/PVA primer	one coat							
	35.00 SF	0.61	0.18	4.32	25.85	0/15 yrs	Avg.	0%	(0.00)	25.85



#### **CONTINUED - Pantry**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
26. Paint the walls - two	coats								
140.00 SF	1.00	2.82	28.56	171.38	3/15 yrs	Avg.	20%	(6.44)	164.94
27. Mask and prep for pa	aint - tape only	(per LF)							
17.50 LF	0.63	0.06	2.22	13.31	0/15 yrs	Avg.	0%	(0.00)	13.31
28. Baseboard - 3 1/4"									
17.50 LF	3.31	1.84	11.94	71.71	0/150 yrs	Avg.	0%	(0.00)	71.71
29. Seal & paint baseboa	ard - three coats	S							
17.50 LF	2.25	0.25	7.94	47.57	3/15 yrs	Avg.	20%	(0.56)	47.01
30. Interior door - Reset	- slab only								
1.00 EA	14.22	0.00	2.84	17.06	0/NA	Avg.	0%	(0.00)	17.06
31. Paint door slab only	- 2 coats (per s	ide)							
2.00 EA	38.61	1.31	15.70	94.23	3/15 yrs	Avg.	20%	(3.00)	91.23
WATER MITIGATION									
32. Tear out non-salv so	lid/eng. wood f	lr & bag for c	lisposal						
19.00 SF	3.73	0.13	0.00	71.00	NA	NA	NA	(0.00)	71.00
33. Air mover (per 24 ho	our period) - No	o monitoring							
3.00 EA	27.27	0.00	0.00	81.81	0/NA	Avg.	0%	(0.00)	81.81
34. Apply anti-microbia	l agent to more	than the floor	r						
54.00 SF	0.27	0.14	0.00	14.72	0/NA	Avg.	0%	(0.00)	14.72
35. Tear out baseboard									
17.50 LF	0.52	0.00	0.00	9.10	NA	NA	NA	(0.00)	9.10
36. Tear out wet drywall	l, cleanup, bag,	per LF - up to	o 2' tall						
17.50 LF	3.70	0.52	0.00	65.27	NA	NA	NA	(0.00)	65.27
37. Add for tear out wd	flr glued down	over concrete	substrate						
19.00 SF	1.86	0.00	0.00	35.34	NA	NA	NA	(0.00)	35.34
38. Interior door slab on	ly - Detach								
1.00 EA	6.63	0.00	0.00	6.63	0/NA	Avg.	0%	(0.00)	6.63
Totals: Pantry		19.81	162.32	1,257.68				10.00	1,247.68



**Hall Closet** 

Height: 8'

160.00 SF Walls177.03 SF Walls & Ceiling1.89 SY Flooring20.00 LF Ceil. Perimeter

17.03 SF Ceiling17.03 SF Floor20.00 LF Floor Perimeter

Door 2' 4" X 6' 8" Opens into LIVING\_ROOM



QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
39. Engineered wood flo	oring								
17.03 SF	9.27	8.26	33.24	199.37	0/50 yrs	Avg.	0%	(0.00)	199.37
40. Add for glued down a	application ove	er concrete su	ostrate		•			, ,	
17.03 SF	1.09	1.30	3.98	23.84	0/150 yrs	Avg.	0%	(0.00)	23.84
41. 1/2" - drywall per LF	- up to 2' tall								
20.00 LF	11.82	1.96	47.68	286.04	0/150 yrs	Avg.	0%	(0.00)	286.04
42. Texture drywall - ligh	ht hand texture								
40.00 SF	0.79	0.21	6.36	38.17	0/150 yrs	Avg.	0%	(0.00)	38.17
43. Seal the surface area	w/PVA primer	- one coat							
40.00 SF	0.61	0.21	4.92	29.53	0/15 yrs	Avg.	0%	(0.00)	29.53
44. Paint the walls - two	coats								
160.00 SF	1.00	3.22	32.64	195.86	3/15 yrs	Avg.	20%	(7.36)	188.50
45. Mask and prep for pa	int - tape only	(per LF)							
20.00 LF	0.63	0.07	2.54	15.21	0/15 yrs	Avg.	0%	(0.00)	15.21
46. Baseboard - 3 1/4"									
20.00 LF	3.31	2.10	13.66	81.96	0/150 yrs	Avg.	0%	(0.00)	81.96
47. Seal & paint baseboa	rd - three coats	S							
20.00 LF	2.25	0.28	9.06	54.34	3/15 yrs	Avg.	20%	(0.64)	53.70
48. Interior door - Detach	n & reset - slab	•							
1.00 EA	23.66	0.00	4.74	28.40	0/NA	Avg.	0%	(0.00)	28.40
49. Paint door slab only -	•	•							
2.00 EA	38.61	1.31	15.70	94.23	3/15 yrs	Avg.	20%	(3.00)	91.23
WATER MITIGATION									
50. Tear out non-salv sol	id/eng. wood f	lr & bag for d	isposal						
17.03 SF	3.73	0.12	0.00	63.64	NA	NA	NA	(0.00)	63.64
51. Air mover (per 24 ho	ur period) - No	monitoring							
6.00 EA	27.27	0.00	0.00	163.62	0/NA	Avg.	0%	(0.00)	163.62
52. Apply anti-microbial	agent to more	than the floor	•						
57.03 SF	0.27	0.15	0.00	15.55	0/NA	Avg.	0%	(0.00)	15.55
53. Tear out baseboard									
20.00 LF	0.52	0.00	0.00	10.40	NA	NA	NA	(0.00)	10.40
54. Tear out wet drywall,	, cleanup, bag,	per LF - up to	2' tall						
$20.00\mathrm{LF}$	3.70	0.60	0.00	74.60	NA	NA	NA	(0.00)	74.60
55. Add for tear out wd f	Ir glued down	over concrete	substrate						
17.03 SF	1.86	0.00	0.00	31.68	NA	NA	NA	(0.00)	31.68
Totals: Hall Closet		19.79	174.52	1,406.44				11.00	1,395.44





Bedroom Height: 8'

336.53 SF Walls468.77 SF Walls & Ceiling14.69 SY Flooring46.09 LF Ceil. Perimeter

132.24 SF Ceiling 132.24 SF Floor 41.26 LF Floor Perimeter


Door 2' 6" X 6' 8" Door 4' 10" X 6' 8" Opens into LIVING\_ROOM
Opens into BEDROOM\_CLOS

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
56. R&R Engineered wo	ood flooring								
66.12 SF	11.63	32.05	160.20	961.22	0/50 yrs	Avg.	0%	(0.00)	961.22
57. Add for glued down	application over	er concrete su	bstrate						
66.12 SF	2.60	5.03	35.38	212.32	0/150 yrs	Avg.	0%	(0.00)	212.32
58. Baseboard - Detach	& reset								
31.26 LF	2.97	0.06	18.58	111.48	0/NA	Avg.	0%	(0.00)	111.48
59. Paint baseboard - two	o coats								
31.26 LF	1.50	0.36	9.46	56.71	3/15 yrs	Avg.	20%	(0.81)	55.90
60. Engineered wood flo	ooring								
66.12 SF	9.27	32.05	129.00	773.98	0/50 yrs	Avg.	0%	(0.00)	773.98
61. Add for glued down	application over	er concrete su	ıbstrate						
66.12 SF	1.09	5.03	15.42	92.52	0/150 yrs	Avg.	0%	(0.00)	92.52
62. 1/2" - drywall per LH	F - up to 2' tall								
10.00 LF	11.82	0.98	23.84	143.02	0/150 yrs	Avg.	0%	(0.00)	143.02
63. Texture drywall - lig	tht hand texture								
20.00 SF	0.79	0.11	3.18	19.09	0/150 yrs	Avg.	0%	(0.00)	19.09
64. Seal the surface area	w/PVA prime								
20.00 SF	0.61	0.11	2.46	14.77	0/15 yrs	Avg.	0%	(0.00)	14.77
65. Paint the walls - two	coats								
336.53 SF	1.00	6.77	68.66	411.96	3/15 yrs	Avg.	20%	(15.48)	396.48
66. Mask and prep for pa	aint - tape only	(per LF)							
46.09 LF	0.63	0.16	5.84	35.04	0/15 yrs	Avg.	0%	(0.00)	35.04
67. Baseboard - 3 1/4"									
10.00 LF	3.31	1.05	6.84	40.99	0/150 yrs	Avg.	0%	(0.00)	40.99
68. Seal & paint baseboa	ard - three coat	S							
10.00 LF	2.25	0.14	4.52	27.16	3/15 yrs	Avg.	20%	(0.32)	26.84
69. Interior door - Detac									
3.00 EA	23.66	0.00	14.20	85.18	0/NA	Avg.	0%	(0.00)	85.18
70. Paint door slab only	-								
6.00 EA	38.61	3.94	47.12	282.72	3/15 yrs	Avg.	20%	(9.00)	273.72
WATER MITIGATION									
71. Tear out non-salv so	lid/eng. wood f	flr & bag for o	disposal						
66.12 SF	3.73	0.46	0.00	247.09	NA	NA	NA	(0.00)	247.09
72. Air mover (per 24 ho	our period) - No	o monitoring							
6.00 EA	27.27	0.00	0.00	163.62	0/NA	Avg.	0%	(0.00)	163.62
							1/	20/2021	Page: 7



#### **CONTINUED - Bedroom**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
73. Apply anti-microbia	l agent to part o	of the floor							
86.12 SF	0.27	0.23	0.00	23.48	0/NA	Avg.	0%	(0.00)	23.48
74. Tear out baseboard									
10.00 LF	0.52	0.00	0.00	5.20	NA	NA	NA	(0.00)	5.20
75. Tear out wet drywal	l, cleanup, bag,	per LF - up to	o 2' tall						
10.00 LF	3.70	0.30	0.00	37.30	NA	NA	NA	(0.00)	37.30
76. Add for tear out wd	flr glued down	over concrete	substrate						
66.12 SF	1.86	0.00	0.00	122.98	NA	NA	NA	(0.00)	122.98
77. Dehumidifier (per 24	4 hour period) -	No monitori	ng						
3.00 EA	62.01	0.00	0.00	186.03	0/NA	Avg.	0%	(0.00)	186.03
Totals: Bedroom		88.83	544.70	4.053.86				25.61	4.028.25



Kitchen Height: 8'

352.22 SF Walls 539.61 SF Walls & Ceiling

20.82 SY Flooring

46.25 LF Ceil. Perimeter

187.39 SF Ceiling

187.39 SF Floor

43.58 LF Floor Perimeter

**Missing Wall - Goes to Floor** 

Door Missing Wall 2' 8" X 6' 8" 2' 10" X 6' 8"

10' 5" X 8'

Opens into DINING\_ROOM Opens into PANTRY Opens into LIVING\_ROOM

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
78. Engineered wood flo	ooring								
62.50 SF	9.27	30.30	121.94	731.62	0/50 yrs	Avg.	0%	(0.00)	731.62
79. R&R Engineered wo	ood flooring								
124.89 SF	11.63	60.54	302.58	1,815.59	0/50 yrs	Avg.	0%	(0.00)	1,815.59
80. Add for glued down	application over	er concrete su	bstrate						
124.89 SF	2.60	9.51	66.84	401.06	0/150 yrs	Avg.	0%	(0.00)	401.06
81. Add for glued down	application over	er concrete su	bstrate						
62.50 SF	1.09	4.76	14.58	87.47	0/150 yrs	Avg.	0%	(0.00)	87.47
82. 1/2" - drywall per LF	F - up to 2' tall								
6.83 LF	11.82	0.67	16.28	97.68	0/150 yrs	Avg.	0%	(0.00)	97.68
83. Texture drywall - lig	ht hand texture								
13.66 SF	0.79	0.07	2.18	13.04	0/150 yrs	Avg.	0%	(0.00)	13.04
							1/2	20/2021	Page: 8



#### **CONTINUED - Kitchen**


	QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
84.	Seal the surface area	w/PVA primer	- one coat							
	13.66 SF	0.61	0.07	1.68	10.08	0/15 yrs	Avg.	0%	(0.00)	10.08
85.	Paint the surface area	a - two coats				•				
	131.13 SF	1.00	2.64	26.74	160.51	3/15 yrs	Avg.	20%	(6.03)	154.48
86.	Mask and prep for pa	aint - tape only	(per LF)							
	46.25 LF	0.63	0.16	5.86	35.16	0/15 yrs	Avg.	0%	(0.00)	35.16
87.	Baseboard - 3 1/4"									
	5.00 LF	3.31	0.53	3.42	20.50	0/150 yrs	Avg.	0%	(0.00)	20.50
88.	Seal & paint baseboa	ard - three coats								
	5.00 LF	2.25	0.07	2.28	13.60	3/15 yrs	Avg.	20%	(0.16)	13.44
89.	Refrigerator - Remov	ve & reset								
	1.00 EA	43.86	0.00	8.78	52.64	0/NA	Avg.	0%	(0.00)	52.64
90.	Dishwasher - Reset									
	1.00 EA	95.95	0.00	19.20	115.15	0/NA	Avg.	0%	(0.00)	115.15
91.	Install Built-in doub	le oven reset								
	1.00 EA	154.09	0.00	30.82	184.91	0/15 yrs	Avg.	0%	(0.00)	184.91
92.	Cabinetry - full heigh	ht unit - Reset								
	2.50 LF	43.43	0.00	21.72	130.30	0/NA	Avg.	0%	(0.00)	130.30
93.	Cabinetry - lower (ba	ase) units - Res	et							
	12.75 LF	43.59	0.00	111.16	666.93	0/NA	Avg.	0%	(0.00)	666.93
94.	Sink - undermount -	Reset								
	2.00 EA	122.54	0.23	49.06	294.37	0/NA	Avg.	0%	(0.00)	294.37
;	Sink in island and low	ver cabinet								
95.	Electrician - per hou	r								
	2.00 HR	100.28	0.00	40.12	240.68	0/NA	Avg.	0%	(0.00)	240.68
]	Labor to reset electric	al on island								
96.	Install Sink faucet - I	Kitchen reset								
	2.00 EA	64.00	0.00	25.60	153.60	0/15 yrs	Avg.	0%	(0.00)	153.60
97.	Countertop - solid su	ırface/granite - 1	Reset							
	32.38 SF	15.55	0.00	100.70	604.21	0/NA	Avg.	0%	(0.00)	604.21
98.	Countertop - Granite	or Marble - bu	ff & polish							
	55.38 SF	14.19	2.23	157.60	945.67	0/NA	Avg.	0%	(0.00)	945.67
99.	Countertop - solid su	ırface/granite -	Detach & reso	et						
	23.00 SF	36.18	0.00	166.42	998.56	0/NA	Avg.	0%	(0.00)	998.56
100	. Cabinetry - lower (	base) units - De	tach & reset							
	9.50 LF	72.72	0.00	138.16	829.00	0/NA	Avg.	0%	(0.00)	829.00
101	. Detach & Reset Co	oktop - gas					-			
	1.00 EA	145.53	0.00	29.10	174.63	0/15 yrs	Avg.	0%	(0.00)	174.63
WA	TER MITIGATION					•	-		•	
	. Tear out non-salv s	olid/eng_wood	flr & bag for	disposal						
102	62.50 SF	3.73	0.44	0.00	233.57	NA	NA	NA	(0.00)	233.57
	02.30 51	5.15	0.44	0.00	233.31	IVA	INA	11/1	(0.00)	433.31



#### **CONTINUED - Kitchen**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
103. Air mover (per 24 h	hour period) - N	lo monitorin	g						
12.00 EA	27.27	0.00	0.00	327.24	0/NA	Avg.	0%	(0.00)	327.24
104. Apply anti-microbi	al agent to the	surface area				_			
76.16 SF	0.27	0.20	0.00	20.76	0/NA	Avg.	0%	(0.00)	20.76
105. Tear out baseboard									
5.00 LF	0.52	0.00	0.00	2.60	NA	NA	NA	(0.00)	2.60
106. Tear out wet drywa	ıll, cleanup, bag	g, per LF - up	to 2' tall						
6.83 LF	3.70	0.20	0.00	25.47	NA	NA	NA	(0.00)	25.47
107. Add for tear out wo	l flr glued dowr	over concre	ete substrate						
62.50 SF	1.86	0.00	0.00	116.25	NA	NA	NA	(0.00)	116.25
108. Dishwasher - Detac	ch								
1.00 EA	57.23	0.00	0.00	57.23	0/NA	Avg.	0%	(0.00)	57.23
109. Remove Built-in do	ouble oven deta	ch							
1.00 EA	33.83	0.00	0.00	33.83	NA	NA	NA	(0.00)	33.83
110. Cabinet - full heigh	t unit - Detach								
1.00 LF	20.25	0.00	0.00	20.25	0/NA	Avg.	0%	(0.00)	20.25
111. Cabinet - lower (ba	se) unit - Detac	eh .							
12.75 LF	20.32	0.00	0.00	259.08	0/NA	Avg.	0%	(0.00)	259.08
112. Sink - undermount	- Detach								
2.00 EA	50.12	0.00	0.00	100.24	0/NA	Avg.	0%	(0.00)	100.24
Sink in island and lov	ver cabinet								
113. Remove Sink fauce	et - Kitchen deta	ach							
2.00 EA	23.27	0.00	0.00	46.54	NA	NA	NA	(0.00)	46.54
114. Countertop - solid s	surface/granite	- Detach							
32.38 SF	8.76	0.00	0.00	283.65	0/NA	Avg.	0%	(0.00)	283.65
115. Water Extraction &	Remediation 7	Γechnician -	per hour						
1.00 HR	62.02	0.00	0.00	62.02	0/NA	Avg.	0%	(0.00)	62.02
Labor to detach electr	rical on island								
Totals: Kitchen		112.62	1,462.82	10,365.69				6.19	10,359.50





**Dining Room** 

Height: 8'

306.22 SF Walls
138.42 SF Ceiling
444.64 SF Walls & Ceiling
15.38 SY Flooring
36.50 LF Floor Perimeter

47.17 LF Ceil. Perimeter


8' X 6' 8"

Missing Wall - Goes to Floor

Missing Wall - Goes to Floor 2' 8" X 6' 8"

Opens into ENTRY\_FOYER
Opens into KITCHEN

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
116. R&R Engineered w	ood flooring								
138.42 SF	11.63	67.10	335.40	2,012.32	0/50 yrs	Avg.	0%	(0.00)	2,012.32
117. Add for glued down	n application o	ver concrete s	ubstrate						
138.42 SF	2.60	10.54	74.08	444.51	0/150 yrs	Avg.	0%	(0.00)	444.51
118. Baseboard - Detach	a & reset								
36.50 LF	2.97	0.06	21.70	130.17	0/NA	Avg.	0%	(0.00)	130.17
119. Paint baseboard - tv	wo coats								
36.50 LF	1.50	0.42	11.04	66.21	3/15 yrs	Avg.	20%	(0.95)	65.26
Totals: Dining Room		78.12	442.22	2,653.21				0.95	2,652.26



Entry/Foyer

Height: 20'

 1455.23 SF Walls
 317.97 SF Ceiling

 1773.21 SF Walls & Ceiling
 301.78 SF Floor

33.53 SY Flooring76.63 LF Ceil. Perimeter

65.63 LF Floor Perimeter

Missing Wall - Goes to Floor Missing Wall - Goes to Floor Door

3' X 8' 2' 6" X 6' 8"

8' X 6' 8"


Opens into DINING\_ROOM
Opens into LIVING\_ROOM
Opens into Exterior

,387.19
969.12
234.03



#### **CONTINUED - Entry/Foyer**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
123. Paint baseboard - tv	vo coats								
65.63 LF	1.50	0.75	19.86	119.06	3/15 yrs	Avg.	20%	(1.71)	117.35
124. Paint the walls - tw	o coats								
1455.23 SF	1.00	29.29	296.90	1,781.42	3/15 yrs	Avg.	20%	(66.94)	1,714.48
125. Mask and prep for J	paint - tape onl	y (per LF)							
76.63 LF	0.63	0.27	9.72	58.27	0/15 yrs	Avg.	0%	(0.00)	58.27
126. Additional cost for	high wall or ce	eiling - 11' to	14'						
196.88 SF	0.06	0.00	2.36	14.17	3/15 yrs	Avg.	20%	(0.00)	14.17
127. Additional cost for	high wall or ce	eiling - Over	14'						
393.77 SF	0.10	0.00	7.88	47.26	0/15 yrs	Avg.	0%	(0.00)	47.26
Totals: Entry/Foyer		199.68	1,268.44	7,610.52				68.65	7,541.87



#### **Bedroom closet**

Height: 8'

106.57 SF Walls123.12 SF Walls & Ceiling

16.55 SF Floor


1.84 SY Flooring17.35 LF Ceil. Perimeter

12.52 LF Floor Perimeter

Door 4' 10" X 6' 8" Opens into BEDROOM

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
128. R&R Engineered w	vood flooring								
16.55 SF	11.63	8.02	40.10	240.60	0/50 yrs	Avg.	0%	(0.00)	240.60
129. Add for glued dow	n application ov	er concrete su	ıbstrate						
16.55 SF	2.60	1.26	8.86	53.15	0/150 yrs	Avg.	0%	(0.00)	53.15
130. Baseboard - Detach	h & reset								
12.52 LF	2.97	0.02	7.44	44.64	0/NA	Avg.	0%	(0.00)	44.64
131. Paint baseboard - tv	wo coats								
12.52 LF	1.50	0.14	3.78	22.70	3/15 yrs	Avg.	20%	(0.33)	22.37
132. Bypass (sliding) do	oor set - slabs or	ıly - Detach &	reset						
1.00 EA	33.40	0.00	6.68	40.08	0/NA	Avg.	0%	(0.00)	40.08
133. Paint bypass door s	set - slab only - 2	2 coats (per si	de)						
2.00 EA	49.32	2.56	20.24	121.44	3/15 yrs	Avg.	20%	(5.85)	115.59
Totals: Bedroom closes	t	12.00	87.10	522.61				6.18	516.43





Upstairs Height: 8'

496.00 SF Walls691.67 SF Walls & Ceiling21.74 SY Flooring62.00 LF Ceil. Perimeter

195.67 SF Ceiling195.67 SF Floor62.00 LF Floor Perimeter

Missing Wall			6' X 8'		•	Opens into	Exterior		
QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING									
134. Paint the walls - tw	o coats								
496.00 SF	1.00	9.98	101.20	607.18	3/15 yrs	Avg.	20%	(22.82)	584.36
135. Mask and prep for	paint - tape onl	y (per LF)							
62.00 LF	0.63	0.22	7.86	47.14	0/15 yrs	Avg.	0%	(0.00)	47.14
136. Content Manipulat	ion charge - per	r hour							
1.00 HR	44.44	0.00	8.88	53.32	0/NA	Avg.	0%	(0.00)	53.32
Totals: Upstairs		10.20	117.94	707.64				22.82	684.82

#### **Contents**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
CONTENTS									
137. Job-site cargo/stora	nge container - 2	20' long - per r	nonth						
1.00 MO	87.83	7.69	0.00	95.52	0/NA	Avg.	0%	(0.00)	95.52
138. Job-site cargo conta	ainer - pick up/	del. (each way	) 16'-40'						
2.00 EA	99.40	17.40	0.00	216.20	0/NA	Avg.	0%	(0.00)	216.20
139. Content Manipulati	ion charge - per	r hour							
64.00 HR	44.44	0.00	0.00	2,844.16	0/NA	Avg.	0%	(0.00)	2,844.16
140. Evaluate pack & in	ventory misc it	ems - per Med	box						
15.00 EA	13.80	4.42	0.00	211.42	0/NA	Avg.	0%	(0.00)	211.42
Totals: Contents		29.51	0.00	3,367.30				0.00	3,367.30

#### **General Items**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
DWELLING 141. Per American Leak	z Dataction								
1.00 EA	275.00	0.00	0.00	275.00	0/NA	Avg.	0%	(0.00)	275.00
							1/2	20/2021	Page: 13



#### **CONTINUED - General Items**

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
142. Per Sung Shin Plui	mbing to access	s leak							
1.00 EA	500.00	0.00	0.00	500.00	0/NA	Avg.	0%	(0.00)	500.00
144. Tandem axle dump	trailer - per lo	ad - includin	g dump fees						
1.00 EA	213.86	0.00	42.78	256.64	NA	NA	NA	(0.00)	256.64
WATER MITIGATION									
143. Tandem axle dump	trailer - per lo	ad - includin	g dump fees						
1.00 EA	213.86	0.00	0.00	213.86	NA	NA	NA	(0.00)	213.86
Totals: General Items		0.00	42.78	1,245.50				0.00	1,245.50
Total: Main Level		818.07	5,733.50	43,244.75				185.96	43,058.79
Line Item Totals: RYA	AN_KIM	818.07	5,733.50	43,244.75				185.96	43,058.79

<sup>[%] -</sup> Indicates that depreciate by percent was used for this item

#### **Grand Total Areas:**

1,408.02	SF Walls SF Floor SF Long Wall	156.45	SF Ceiling SY Flooring SF Short Wall	395.57	SF Walls and Ceiling LF Floor Perimeter LF Ceil. Perimeter
,	Floor Area Exterior Wall Area	,	Total Area Exterior Perimeter of Walls	4,133.45	Interior Wall Area
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length

<sup>[</sup>M] - Indicates that the depreciation percentage was limited by the maximum allowable depreciation for this item



Coverage	Item Total	%	<b>ACV Total</b>	%
Dwelling	35,175.43	81.34%	34,989.47	81.26%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	3,367.30	7.79%	3,367.30	7.82%
Water Mitigation	4,702.02	10.87%	4,702.02	10.92%
Total	43,244.75	100.00%	43,058.79	100.00%



# Summary for Dwelling

#### **Summary for All Items**

Line Item Total	28,658.66
Material Sales Tax	783.27
Overhead	2,866.75
Profit	2,866.75
Replacement Cost Value	\$35,175.43
Less Depreciation	(185.96)
Actual Cash Value	\$34,989.47
Less Deductible	(2,500.00)
Net Claim	\$32,489.47
Total Depreciation	185.96
Total Recoverable Depreciation	185.96
Net Claim if Depreciation is Recovered	\$32,675.43



# **Summary for Contents**

#### **Summary for All Items**

Line Item Total	3,337.79
Material Sales Tax	4.42
Storage Rental Tax	25.09
Overhead	0.00
Profit	0.00
Replacement Cost Value	\$3,367.30
Actual Cash Value	\$3,367.30
Net Claim	\$3,367.30

Justin Kirisits



# **Summary for** Water Mitigation

#### **Summary for All Items**


Line Item Total	4,696.73
Material Sales Tax	5.29
Overhead	0.00
Profit	0.00
Replacement Cost Value	\$4,702.02
Actual Cash Value	\$4,702.02
Net Claim	\$4,702.02

Justin Kirisits



#### Recap of Taxes, Overhead and Profit

	Overhead (10%)	<b>Profit</b> (10%)	Material Sales Tax (8.75%)	Storage Rental Tax (8.75%)
Line Items	2,866.75	2,866.75	792.98	25.09
Total	2,866.75	2,866.75	792.98	25.09





Main Level