
로봇팔조립매뉴얼

로봇공학입문설계

부품 리스트

부품명		수량
육각렌치	M3x15	3
육각렌치	M6x20	1
베어링	606	1
볼	-	-
와셔	M6	1
육각렌치	M3x25	2
너트	M3	2
무두나사	M4x32	1
육각렌치	M4x55	1
둥근육각	M4x22	5
둥근육각	M4x30	1
둥근육각	M4x40	1
나일론 너트	M4	8
플라스틱 와셔	M4x10	10



1.






















<측면>

4.





