


Check Buttons (200 ms)



Read Temperature (500 ms)



Update Status (1000 ms) If temperature > setPoint LED On Print Data If temperature < setPoint LED Off