



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/01/2026

Shift: C

Incharge(s): Nagendra Midde

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------------|---|------------|----------------------|----------------------|---------|
| 1 | OHP | WBR ON CO 26 | SLEW DRIVE TRIPPED | RESET | 23:55:00 | 00:05:00 | |
| 2 | OHP | CO 26 | OLR ACTED | RESET | 00:00:00 02:10:00 | 00:10:00 02:20:00 | |
| 3 | OHP | CO 29 | OLR ACTED | RESET | 00:00:00 | 00:10:00 | |
| 4 | OHP | BRC ON CO 33M B/C | OLR ACTED DUE TO JAMMING | RESET | 01:00:00 | 01:15:00 | |
| 5 | OHP | CO 113 | OLR ACTED | RESET | 04:50:00 | 05:00:00 | |
| 6 | OHP | TBS ON CO 20 LT | DRIVE TRIPPED | RESET | 03:50:00 | 04:05:00 | |
| 7 | OHP | WBR ON CO 6A B/W | HYDRAULIC PUMP CONTROL MCB IS IN OFF CONDITION | MADE IT ON | 02:40:00 | 02:50:00 | |
| 8 | CHP | CC 32 | OLR ACTED | RESET | 23:25:00 | 23:30:00 | |
| 9 | CHP | CC 51 | FEEDING CONV OLR ACTED | RESET | 23:10:00 | 05:30:00 | 7 TIMES |
| 10 | CHP | CC 14 | CONTROL MCB TRIPPING DUE TO EARTH FAULT IN C/S MODULE | REPLACED | 22:30:00 | 22:50:00 | |