



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/12/2025

Shift: B

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|------------------------------|---|----------|----------|---------|
| 1 | OHP | VS-1A | Reported tripped | OLR acted.Reset done | 20:30:00 | 20:35:00 | |
| 2 | OHP | BRC on CO-8A | Reported CT not taking place | Fuse burnt.Limit cable checked and insulated properly at a joint and tested okay | 17:50:00 | 18:30:00 | |
| 3 | OHP | BRC on CO-8A | Reported Ct not taking place | Checked and found JB-1 TO JB-2 core problem.cores changed and tested okay | 18:55:00 | 19:45:00 | |
| 4 | CHP | CC-51 | MPD tripped | Feeding conveyor stopped.Reset done(8 times) | 15:10:00 | 20:30:00 | |
| 5 | CHP | CC-51 | Reported tripped | OLR acted.Reset done | 20:10:00 | 20:15:00 | |
| 6 | CHP | CC-37 SCR-7 | Reported no power | Checked and found HT fuse burnt at I/O panel.Cable meggered and found okay.Fuse replaced and charged and operations tested okay | 17:00:00 | 18:05:00 | |
| 7 | WT | OT-1 | Reported tripped | D1 tripped.Reset done | 16:20:00 | 16:30:00 | |
| 8 | IOSA | BRC | Reported CT not taking place | Drive tripped(over current fault) due to overload.Reset done | 19:10:00 | 19:20:00 | |