



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/12/2025

Shift: B

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|---|--|----------------------|----------------------|-------------------|
| 1 | OHP | CO-29 | Reported tripped | OLR acted.Reset done(2 times) | 16:05:00 19:50:00 | 16:10:00 19:55:00 | |
| 2 | OHP | VF-23 | M-1 acted | Reset done | 14:50:00 | 15:00:00 | |
| 3 | OHP | BRC on CO-32 | Lt not taking place | Drive-2 tripped.Reset done | 15:50:00 | 16:00:00 | |
| 4 | OHP | VF-23 | M1 tripped | R-ph cut in motor TB.connected properly and tested okay | 16:00:00 | 16:30:00 | |
| 5 | OHP | CR-1 | Reported showing running but physically motor not running | Voltage controller changed and connections checked and tested okay | 14:00:00 | 19:00:00 | |
| 6 | CHP | Cc-117 | Reported tripped | OLR acted.Reset done | 15:10:00 | 15:20:00 | |
| 7 | CHP | CC-131 | Reported tripped | OLR acted.Reset done | 21:40:00 | 21:45:00 | |
| 8 | WT | OT-1 | Reported tripped | D-1 tripped on PGEF-1 fault.Reset done | 20:15:00 | 20:20:00 | |
| 9 | IOSA | OC-7B | Reported not healthy | Checked and found MPD failure.contact removed and tested okay | 20:00:00 | 21:30:00 | MPD to be changed |
| 10 | IOSA | BRC | CT Emergency limit acted | Normal limit handle adjustment done and tested okay | 21:00:00 | 21:30:00 | |