

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 13/06/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-------------------|--|---|----------|----------|-----------------------------------|
| 1 | OHP | co 76R | OLR ACTED | RESET | 14:30:00 | 14:40:00 | |
| 2 | OHP | CO 11(C) DRIVE | OLR ACTED | RESET | 14:40:00 | 14:50:00 | |
| 3 | OHP | CO76R | ZS PROBE DAMAGED | ZS BYPASSED | 15:00:00 | 15:20:00 | |
| 4 | OHP | WOBR ON CO 26 | LT NOT TAKING PLACE O/T ACTED | RELEASED AND PCRD CABLE PROPER WINDING WAS DONE | 16:30:00 | 17:00:00 | |
| 5 | OHP | WOBR ON CO 26 | SLEW NOT TAKING PLACE DRIVE TRIP | RESET | 17:30:00 | 17:40:00 | |
| 6 | OHP | WOBR ON CO 25 | SLEW NOT MOVING M1 OLR ACTED | RESET | 17:45:00 | 18:00:00 | |
| 7 | OHP | CO76R | ZS PROBE CHANGED | KEPT IN CIRCUIT | 20:00:00 | 20:30:00 | |
| 8 | OHP | WOBR ON CO26 | PCRD O/T ACTED 3LAYERS CABLE ON THE GROUND | O/T RELEASED AND CABLE LAYING WAS DONE | 21:25:00 | 22:00:00 | PCRD CIRCUIT TO BE CHKED |
| 9 | CHP | CC 17 | ZS CAGE BOLTS AMD PROBE LOOSE | ZS CAGE BOLTS TIGHT AND PROBE FIXING PROPERLY THAN OK | 14:10:00 | 14:20:00 | |
| 10 | CHP | CC32 SCR 5 | LT NOT TAKI8NG PLACE M4 TRIP FREQUENTLY | M4 OUT GOING CABLE REMOVED AT MPCB THAN OK | 15:00:00 | 15:30:00 | |
| 11 | CHP | sc7 cc 39 | slew not working,oil level low,hose pipe damaged | mechanical problem | 20:30:00 | 20:40:00 | |
| 12 | CHP | CC 105 SCR 10 | LUFFING NOT WORKING | OUT PUT RELAYS TIGHT IT THAN OK | 16:00:00 | 16:30:00 | |



RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 13/06/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-------------------|--|--|----------|----------|------------------------|
| 13 | CHP | scr 9 cc 104 | signal missing, modem not pinging, | bypass in cm 18 i/o rack yard interlock zss cage | 21:00:00 | 21:20:00 | |
| 14 | CHP | CC 125 | OLR ACTED | RESET | 17:05:00 | 17:10:00 | DUE TO OVER LOAD |
| 15 | CHP | CC 32 SCr5 | LT problem mpcb 4 trip, wheel stuck mech problem | m4 removed | 15:00:00 | 15:30:00 | |
| 16 | CHP | CC 34 scr2 | pcrd chain damaged | ,loop provided drum arrested | 20:30:00 | 20:45:00 | informed operation |
| 17 | CHP | CC 33 scr 4 | pcrd problem,cable zigzag | cble unwinding and winding done | 16:10:00 | 16:30:00 | |
| 18 | CHP | CC 125 | olr acted | reset it done | 20:25:00 | 20:35:00 | |
| 19 | CHP | CC 39 SCR 7 | PCRD MAIN CONTACTOR NO PICK UP CONTROL PROBLEM | OLR TO TB 1 HIGH GIVEN THAN OK | 20:00:00 | 20:30:00 | |
| 20 | IOSA | TBS ON OC 13 A | LT END LIMIT ACTED DUE TO GRASS | LIMIT RELEASED | 15:45:00 | 16:00:00 | |