



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/11/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--------------------------------|--------------------|----------|----------|---------|
| 1 | OHP | RSCO6A | olr acted | reset | 16:20:00 | 16:30:00 | |
| 2 | OHP | VF 1A | olr acted | reset | 20:55:00 | 21:05:00 | |
| 3 | OHP | co 26 | OLr acted | reset | 15:45:00 | 15:55:00 | |
| 4 | OHP | WOBR on co 26 | slew not working,drive tripped | reset | 14:45:00 | 15:00:00 | |
| 5 | OHP | WOBR on CO 26 | LT not working,OT acted | ot released | 17:20:00 | 17:35:00 | |
| 6 | OHP | BRC on CO 34 | emergency PB acted | released | 18:00:00 | 18:20:00 | |
| 7 | OHP | TBS on CO 21 | LT not working,drive tripped | reset | 22:00:00 | 22:10:00 | |
| 8 | CHP | CC 113 A | motor tripped | reset | 15:40:00 | 15:45:00 | |
| 9 | CHP | CC 54 | OLr acted | reset | 15:44:00 | 17:00:00 | 3 times |
| 10 | CHP | CC 51 | MPD tripped 8 times | reset | 18:00:00 | 21:30:00 | |
| 11 | CHP | CC 34 scr1 | LT not working ,ol acted | reset | 16:00:00 | 16:15:00 | |
| 12 | CHP | CC 38 SCR 6 | slew not working,jamming | informed operation | 16:10:00 | 16:20:00 | |
| 13 | CHP | CC 49 | ZSS acted sensor probe problem | probe replaced | 16:10:00 | 16:30:00 | |
| 14 | CHP | CC 39 SCR 2 | slew not working,overload | reset | 17:10:00 | 17:20:00 | |
| 15 | CHP | CC 31 | motor trips due to ol | reset | 21:40:00 | 21:50:00 | |



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/11/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------|--|---------------------------------|----------|----------|---------|
| 16 | CHP | CC 201 | olr acted | reset | 19:30:00 | 19:40:00 | |
| 17 | WT | OT 3 | brake problem,timer,ER contactor stucked | ER contactor and timer replaced | 15:00:00 | 16:00:00 | |
| 18 | WT | CT 1 | inhaul mpccb trips | made it on | 21:30:00 | 21:40:00 | |
| 19 | WT | OP9 | no rev movement,d4 trips in ol | reset | 16:00:00 | 16:10:00 | |