



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/12/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|-------------------------------------|----------------------|----------------------|------------------|
| 1 | OHP | CO-29 | OLR ACTED | RESET DONE | 10:40:00 | 10:45:00 | |
| 2 | OHP | CO-26 | OLR ACTED | RESET DONE | 10:10:00 | 10:20:00 | |
| 3 | OHP | CO-9A | REPORTED STOPPING ON ZSS FOUND ZSS PROBE DAMAGED | PROBE REPLACED WITH NEW ONE THAN OK | 10:50:00 | 11:15:00 | |
| 4 | OHP | BRC ON CO-32 | REPORTED B/W-1 NOT RUNNING FOUND GUIDE ROLLER PROBLEM | INFORMED TO OPERATION | 07:05:00 | 07:20:00 | |
| 5 | OHP | BRC ON CO-28 | REPORTED ALL DRIVES ARE NOT RUNNING FOUND E/STOP ACTED | RELEASED | 07:30:00 | 07:45:00 | |
| 6 | OHP | WOBR ON CO-25 | REPORTED B/W NOT RUNNING FOUND POWER MCCB TRIPPED | B/W MOTOR BURNT | 11:30:00 | 12:00:00 | G SHIFT ATTENDED |
| 7 | CHP | CC-117 | OLR ACTED (2TIMES) | RESET DONE | 06:05:00 10:15:00 | 06:15:00 10:25:00 | |
| 8 | CHP | CC-51 | MPD ACTED FEEDING CONVEYOR (6TIMES) | RESET DONE | 08:00:00 | 11:15:00 | |
| 9 | CHP | CC-52 | MPD TRIPPED (FEEDING CONVEYOR) | RESET DONE | 12:50:00 | 12:55:00 | |
| 10 | CHP | CC-54 | OLR ACTED | RESET DONE | 08:40:00 | 08:45:00 | |
| 11 | CHP | CC-39 SCR-6 | REPORTED LT NOT WORKING FOUND DRIVE TRIP FAULT CODE OF-7404 | RESET DONE | 07:00:00 | 07:10:00 | |
| 12 | CHP | CC-39 SCR-6 | LT DRIVE TRIP FAULT CODE OF-30002 | RESET DONE | 07:50:00 | 08:00:00 | |
| 13 | CHP | CC-32 SCR-5 | B/C NOT RUNNING BELT SLIPPING | INFORMED TO MECHANICAL | 07:45:00 | 07:55:00 | |



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/12/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|---|-------------------------------|----------|----------|---------|
| 14 | CHP | CC-32 SCR-5 | B/C TRIPPED ON OLR | RESET DONE | 08:40:00 | 08:50:00 | |
| 15 | CHP | CC-33 SCR-3 | B/W NOT RUNNING | FAULT RESET DONE THAN OK | 09:00:00 | 09:10:00 | |
| 16 | CHP | CC-40 SCR-2 | SLEW NOT WORKING FOUND DRIVE TRIP AND 30 DEGREE LIMIT ACTED | RELEASED AND DRIVE RESET DONE | 11:25:00 | 11:40:00 | |
| 17 | WT | OT-4 | DRIVE -2 TRIP PGF-4 FAULT | RESET DONE | 13:55:00 | 14:00:00 | |