

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL GENERAL SHIFT REPORT

Date: 19/05/2025 Area: IOSA

Equipment	Job
TBS	FAULTY PULL CHORD REMOVED FROM RIGHT BOOM CONVEYOR AND REPLACED WITH RECTIFIED PULLCHORD.
OC-18A	ZONE-3 PULLCHORDS and BELTSWAY SWITCHS FEEDBACK CHECKED AND COVERED WITH SHEETS.
OC-6A	LIGHTING DEFECTS RECTIFIED
OC-4A	FIELD DEVICES FEEDBACK AND INTERLOCK CHECKING DONE.