

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 26/04/2025

Shift: B

Incharge(s): G Eswara Rao

SI No	Area	Equipment	Problem	Action	From	То	Remarks
1	OHP	co 6a	tripped on material over feeding	reset done after 15 min.	18:30:00	18:45:00	
2	OHP	co 34	tripped on olr	reset done	18:00:00	18:10:00	
3	OHP	tbs on co 7a	bc signal is not getting to ocr/cs acted due to input supply wire got open at module.	cs bypassed at module	21:11:00	21:30:00	
4	OHP	co 35	tripped on olr 2times	reset done	16:05:00 17:10:00	16:15:00 17:20:00	
5	OHP	brc on co 31	It not taking place/selector in local mode	kept in remote	20:10:00	20:25:00	
6	CHP	CC 51	OLR ACTED	RESET	19:25:00 21:10:00	19:30:00 21:15:00	
7	CHP	SCR5 ON CC 32 LT	DRIVE TRIPPED	RESET	18:20:00	18:30:00	
8	CHP	SCR 5 ON CC 32 B/C	OLR ACTED	RESET	18:10:00	18:20:00	
9	CHP	SCR 4 ON CC 33 LT	M3, M9 TRIPPED DUE TO TRACK JAMMING	RESET INFORMED OPRN TO CLEAN	18:35:00	18:45:00	
10	CHP	R1 ON CC 111	ANTENNA NOT RECIEVING SIGNAL IF MACHINE IS IN EXTREME TAIL END	FORWARD DONE THEN OK	19:40:00	20:00:00	
11	CHP	SCR 7 ON CC 39 LT	PCRD O/T ACTED	RESET	19:40:00	19:55:00	