



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/12/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|-----------------------------------------------------------------|--------------------------------|----------------------------------|----------------------------------|-------------------------|
| 1 | OHP | BRC ON CO-30 | REPORTED B/W-1 NOT RUNNING FOUND CONTROL MCB TRIPPED | MADE ON THAN OK | 07:00:00 | 07:15:00 | |
| 2 | OHP | CO-85 | TRIPPED ON OLR (3TIMES) | RESET DONE | 09:00:00 13:40:00 13:50:00 | 09:15:00 13:45:00 14:00:00 | DUE TO MATERIAL JAMMING |
| 3 | OHP | CO-25 | TRIPPED ON OLR | RESET DONE | 10:00:00 | 10:15:00 | |
| 4 | OHP | TBS ON CO-7A | REPORTED LT NOT TAKING PLACE FOUND SELECTOR SWITCH OFF POSITION | SELECTOR KEPT REMOTE THAN OK | 10:00:00 | 10:15:00 | |
| 5 | CHP | CC-52 | FEEDING CONVEYOR MPD ACTED | RESET DONE | 08:15:00 | 08:20:00 | |
| 6 | CHP | CC-54 | OLR ACTED | RESET DONE | 12:35:00 | 12:40:00 | |
| 7 | CHP | CC-51 | MPD TRIP FEEDING CONVEYOR (3TIMES) | RESET DONE | 08:05:00 08:15:00 12:35:00 | 08:10:00 08:20:00 12:40:00 | |
| 8 | CHP | CC-31 SCR-4 | LUFF DOWN LIMIT ACTED | BYPASSED OPERATION REQUIREMENT | 07:00:00 | 07:05:00 | |
| 9 | CHP | CC-33 | OLR ACTED | RESET DONE | 09:00:00 | 09:10:00 | |
| 10 | CHP | CC-32 R-1 | LUFF NOT WORKING FOUND MPCB TRIP | MADE ON THAN OK | 10:05:00 | 10:15:00 | |
| 11 | CHP | CC-33 SCR-5 | LT NOT TAKING PLACE DRIVE TRIP (F7900) (2TIMES) | RESET DONE | 10:05:00 12:10:00 | 10:15:00 12:15:00 | |
| 12 | CHP | CC-125 | OLR ACTED(2TIMES) | RESET DONE | 10:10:00 12:05:00 | 10:15:00 12:10:00 | |