

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 01/07/2025

Shift: C

Incharge(s): Lal Singh

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-----------------|--|---|--|--|------------------|
| 1 | OHP | CO-26 | TRIPPED ON OLR | RESET DONE | 03:45:00 | 03:50:00 | |
| 2 | OHP | CO-20 TBS | LT NOT WORKING BECAUSE OF PCRD OVER TENSION | RELEASED | 03:50:00 | 04:00:00 | |
| 3 | CHP | CC-51 | TRIPPED ON OLR | RESET DONE | 01:40:00 | 01:45:00 | |
| 4 | CHP | CC-36 S-1 | SIGNAL MISSING | PLC AND MODEM POWER RECYCLE | 00:30:00 | 00:50:00 | |
| 5 | CHP | CC-40 SCR-6 | SLEW NOT WORKING | PUMP STOPPING IN BETWEEN AIR BLAST COOLER MPCB AUX CONTACT MISSING bypassed | 01:00:00 | 01:50:00 | TO BE CHANGED |
| 6 | CHP | CC-33 | TRIPPED ON OLR | RESET DONE | 02:35:00 03:00:00 03:30:00 05:00:00 | 02:45:00 03:15:00 03:45:00 05:15:00 | |
| 7 | CHP | CC-32 SCR -5 | YARD LATE STOPPING AFTER BC STOP AS PER OPERATION | INTERLOCK CHECKED FOUND OK | 03:30:00 | 03:45:00 | |
| 8 | CHP | CC-54 | TRIPPED ON OLR | RESET DONE | 04:30:00 05:10:00 | 04:35:00 05:15:00 | |