

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 14/10/2025

Shift: B

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-----------------|---|--|----------|----------|----------------------------|
| 1 | OHP | BRC ON CO-32 | REPORTED CT NOT TAKING PLACE CHECKED AND FOUND CT POWER OFF CONDITION | CT POWER MADE ON THAN OK | 19:00:00 | 19:15:00 | |
| 2 | CHP | CC-32 R-1 | YARD TO BC ZSS INTERLOCK PROB PROBLEM | PROB CHANGED | 15:40:00 | 16:20:00 | |
| 3 | CHP | CC-37 SCR-7 | PCRD OLR ONE PHASE BURNT | OLR CHANGED AND TESTED | 19:05:00 | 19:45:00 | |
| 4 | CHP | CC-51 | MPD TRIPPED 4 TIMES | RESET DONE | 19:00:00 | 20:35:00 | |
| 5 | CHP | cc-33 SCR-5 | LT NOT WORKING PCRD OT AND CABLE ZIG ZAG | RELESED AND CABLE WINDING DONE WITH MECH | 14:40:00 | 15:00:00 | |
| 6 | WT | OP-4 | NOT MOVE CHECKED AND FOUND DRIVE -3 OLR ACTED | RESET DONE | 16:00:00 | 16:30:00 | PUSHER COUPLING TIME |
| 7 | WT | CO-3 | STOPPING ON ZSS FOUND ZSS PROBE LOOSE | ZSS PROBE FIXED PROPERLY THAN OK | 18:00:00 | 18:15:00 | |
| 8 | WT | OT-1 | TRIPPED ON PGF -1 FAULT | RESET DONE | 21:00:00 | 21:10:00 | |
| 9 | IOSA | BRC | HYDRAULIC PUMP MCCB TRIPPED | RESET DONE AND TESTED | 16:20:00 | 16:40:00 | |