



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/12/2025

Shift: B

Incharge(s): Amit Roy

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|-----------------------------|--|----------|----------|----------|
| 1 | OHP | CO-16 | Reported ZSS acting | Checked and found wire came out of tb in MCC panel.Connected and tested okay | 16:30:00 | 17:30:00 | |
| 2 | OHP | BRC on CO-31 | B/C not running | Stop PB contact not making at operator cabin.Made free and tested okay | 17:10:00 | 17:20:00 | |
| 3 | OHP | TBS on CO-7A | LT winding not taking place | Tension released and winding done and tested okay | 19:30:00 | 20:20:00 | NO delay |
| 4 | CHP | CC-51 | Reported tripped | MPD tripped.Feeding conveyor stopped(7 times).Reset done | 16:30:00 | 21:20:00 | |
| 5 | CHP | CC 131 | Reported tripped | OLR acted.Reset done(2 times) | 19:20:00 | 21:27:00 | |
| 6 | WT | OT-4 | Reported tripped | Drive-2 tripped on PGF-4 fault.Reset done | 15:20:00 | 15:25:00 | |
| 7 | WT | OT-3 | Reported tripped | Drive-2 tripped on encoder fault.Control MCB found in off condition in brake panel.Made on | 16:40:00 | 16:45:00 | |