



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/01/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	WT	Air compressor	Reported not working	I/C 125A(2 nos.) fuses blown. Replaced and tested okay	14:00:00	14:30:00	
2	WT	CO-3(C/D)	Reported reverse movement not taking place	Checked and found internal loop missing. Loop provided from RL-5 to RI-9 and tested okay	21:30:00	22:20:00	
3	IOSA	TBS	LT not taking place	M-4 gearbox problem. Motor disconnected and tested okay	14:00:00	17:30:00	