

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 26/08/2025

Shift: B

Incharge(s): Lal Singh

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|----------------------|----------------------------|---|----------|----------|------------------------|
| 1 | OHP | CO-34 | TRIPPED ON OLR | RESET DONE | 19:10:00 | 19:15:00 | |
| 2 | OHP | CO-32 BRC | CT NOT WORKING LIMIT STUCK | MADE FREE GREASING DONE | 19:15:00 | 19:40:00 | |
| 3 | OHP | CO-29 | TRIPPED ON OLR | RESET DONE | 20:20:00 | 20:30:00 | |
| 4 | CHP | CC-40 SCR-3 | LT NOT WORKING | DUE TO TRACK JAMMING INFORMED OPERATION | 15:00:00 | 15:10:00 | |
| 5 | CHP | CC-112 SCR-8 | BC NOT STARTING | DISCHARGE CHUT SENSOR ACTED DUE TO JAMMING INFORMED OPERATION | 15:20:00 | 15:30:00 | |
| 6 | CHP | CC-105 SCR-10 | LT NOT WORKING M2 TRIPPING | MOTOR DISCONNECTEDTESTED | 15:40:00 | 15:55:00 | |
| 7 | CHP | CC-39 SCR-7 | LT NOT WORKING | DRIVE TRIPPED ON OL RESET DONE | 17:50:00 | 18:00:00 | |
| 8 | CHP | CC-105 SCR-10 | BC NOT RUNNING | MPD TRIPP RESET DONE | 18:30:00 | 18:40:00 | |
| 9 | CHP | CC-28 TT | CHUT SENSOR ACTED | PROB AND MODULE CLEANING DONE THEN RESET | 17:00:00 | 17:20:00 | |
| 10 | CHP | CC-17, CC-19 | BRS KEPT IN CKT | DONE | 18:00:00 | 18:10:00 | |
| 11 | CHP | CC-53 TT POSITION | CABLE AND SENSOR PROBLEM | BYPASSED IN IO RACK | 18:00:00 | 18:20:00 | |
| 12 | WT | op-10 | MOTORS TRIPPING | CHECKING GOING ON | 21:45:00 | 22:00:00 | INFORMED TO C SHIFT |