

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 20/05/2025 Incharge(s): V Balaji Naik,G Eswara Rao Shift: A

SI No	Area	Equipment	Problem	Action	From	То	Remarks
1	OHP	brc on co 28	LT not taking place/stop pb operated at panel	pb released.	12:20:00	12:35:00	
2	OHP	tbs on co 22	It not taking place/pcrd cable tension acted	cable tension released then ok	12:10:00	12:25:00	
3	OHP	brc on co 32	bc not running/olr acted	reset done	09:45:00	09:55:00	
4	OHP	TIS ON CO 29	zss bypass request from ope.	zss bypassed at module and feed back bypassed at i/o rack	12:50:00	13:00:00	
5	OHP	tbs on co 20	right luffing not taking place/drive tripped	reset done	09:15:00	09:30:00	
6	OHP	co 5	pc acted/	pc bypassed for operation request	13:10:00	13:20:00	
7	CHP	cc24	olr acted	reset done	08:00:00	08:05:00	
3	CHP	cc 23	c/ s acted due rain	reset done	07:10:00	07:20:00	
9	CHP	cc 39 scr 7	slew not working/spider out alarm acted	reset done	08:00:00	08:10:00	
10	CHP	cc 111	brs not getting reset	probe cleaning done then reset	07:25:00	07:35:00	
11	CHP	cc 41	brs not getting reset	probe cleaning done then reset	07:45:00	08:00:00	
12	CHP	scr 8 on cc112	td elect. healthy red	glass fuse blown/fuse replaced.	06:50:00	07:00:00	xa05 -2
13	CHP	scr 8on cc 112	bc not running/c/s acted due to rain	reset done	08:30:00	08:40:00	
14	CHP	scr 8 on cc112	bw not running/oil level low	inform to ope. and mech	12:25:00	13:00:00	
15	CHP	cc 36	bc not working/bss acted	bss released	13:40:00	13:55:00	
16	CHP	cc 54	tripped on olr /due to jamming	reset done	07:30:00	13:00:00	
17	CHP	cc 131	olr acted due to jamming	reset done	09:05:00	13:30:00	Pag



RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 20/05/2025

Shift: A

Incharge(s): V Balaji Naik,G Eswara Rao

SI No	Area	Equipment	Problem	Action	From	То	Remarks
18	CHP	SCR7 on Cc39	Slew not working found left limit switch acted	Limit released limit side jamming is cleared by operation	12:00:00	12:00:00	4.05 pm to 4.30pm
19	WT	oc 1a,of1a2a	reported red	plc power recycled @lc 9	12:00:00	12:05:00	
20	IOSA	tbs on 13a	communication problem	control wire loose at SMPS /tightend then ok	06:00:00	07:20:00	
21	IOSA	tbs on co 13a	cjd not getting reset	probe cleaning done then reset	06:00:00	06:15:00	